VEHICLE DESCRIPTION - VW Touran Highline 1.5 TSI







First registration date 9/2023	**VIN:** WVGZZZ1T2RW005359
Colour: Black Metalic Normal gloss	**Mileage (km):** 42.668
Gear: Automatic (7 Gears)	**Fuel type:** Gasoline
Body type: MPV	**Number of doors:** 5
Drive type: FWD	**Model year:** 2015
Engine power: 110 kW	**Number of seats:** 7
Engine size (cc) 1498	**Interior:**

VEHICLE DETAILS

Number of keys: 2	**Number of license plates:** 2	**Registration certificate:** Part 1 & 2 present	**Service documentation:** No
Inspection date: 23-10-2026	**Last service (year/month):**	**Mileage (km) at last service:**	

SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition: Yes	**Legal tire tread (minimum 1.6 mm):** Yes

WHEELS


TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Alloy rim	16''	5 mm
Fitted	Summer tires		Rear Right	Alloy rim	16''	5 mm
Fitted	Summer tires		Rear Left	Alloy rim	16''	5 mm
Fitted	Summer tires		Front Right	Alloy rim	16''	5 mm

Legal tire tread (minimum 1.6 mm):
Yes

ACCESSORIES

ergoActive seats in front with 14-way adjustment and massage feature, Easy Open & Close package without SAFELOCK, Adaptive Cruise Control ACC stop & go up to 210 km/h and Automatic Emergency Braking Front Assist, Heated windshield, 2 single seats in 3rd row of seats retractable into cargo area, Lane keeping system Lane Assist, Radio "Ready 2 Discover" incl. "Streaming & Internet", Winter package, Denmark: Comfort package II forces TL: PF1/2-P14-PM5 CL: PF1/2-P14- PM5-PB4 HL: P14-PM5-PB4-2H5-7X2, VE: Special goodwill 2023 II, Preparation for We Connect and We Connect Plus or VW Connect and VW Connect Plus, No special edition, Standard wheel bolts, Vehicle class differentiation -5T0-, Rear exhaust tailpipe (standard), Emission standard EU6 AP, Without trailer hitch, Driver and front passenger airbag with front passenger airbag deactivation- including knee airbag on driver side, Activated carbon canister (Evaporative Emission Control System (EVAP)), Overhead storage compartments, Diversity antenna for FM reception, Ext. mirrors- power-folding- auto-dimm. on driver side- surround lighting and front pass. ext. mirror lowering funct., Aspherical exterior mirror on driver side, Right exterior mirror- convex, Without alternative drive system, Front-wheel drive, Without "Multimedia" in vehicle, Sports equipment, Autonomous Emergency Braking Front Assist (for Adaptive Cruise Control ACC up to 210 km/h), Disc brakes in rear, Battery 380 A (59 Ah) EFB+, Disc brakes in front, Body-colored exterior mirror housings and door handles, Standard battery/alternator capacity, Part set without country-specific prescriptive standard, Tool kit, Electronic Stability Control w/ driver steering recommendation- ABS- ASR- EDL- EDTC and trailer stabilization, Manual in Danish, Operating voltage 12 V, Automatically-heated washer nozzles in front, Without Adaptive Chassis Control, Chrome elements on power mirror switch- rotary light/power window switch- front vents and interior door handles, Without C-rails, Operating permit- alteration, Silver-anodized roof rails, Standard roof, Rear shock absorption- basic version 1, Shock absorption in front, Without UN-ECE cybersecurity & software update, Without ECO function, Dual-clutch transmission DSG DQ200, Electronic immobilizer, Decorative inserts "Piano Black" for dashboard and front door trim panels, Without protective film for scuff plate, Without identification lights, Park Distance Control - warning signals for obstacles in the front and rear, Proactive passenger protection system in combination with Front Assist and Side Assist, 2 USB-C ports in the front- charging capacity up to 45 W, Without fire extinguisher, Pedestrian and cyclist monitoring as well as re-active hood, Standard pedal cluster, Aut. headlight control with separate daytime running light- entry lighting and manual exit lighting, Allergen filter, Electromechanical parking brake with Auto Hold function, No special purpose vehicle- standard equipment, Alternator 140 A, Weight range 5 installation control only- no requirement forecast, Suspension range 07 installation control only- no requirement forecast, 4-cylinder SI engine 1.5 l unit 05E.D, Luggage compartment cover with convenient open feature- extractable- removable and stowable, Adaptive Cruise Control ACC stop & go incl. speed limiter, Without luggage compartment lighting, 7-speed automatic transmission or dual-clutch transmission DSG- note: PR family EDF, Storm Gray headliner, 3 single seats in 2nd row of seats with armrest- 2 single seats in 3rd row of seats with Easy Fold, Air Care Climatronic 3 zone automatic climate control w/ allergen filter- enhanced air filter a. controls in rear, Halogen headlamps and turn signal lamps under one clear lens, Without head-up display, LED light unit in front footwell, Instrument cluster with electronic speedometer- odometer and trip odometer- tachometer, Storage compartment with cover on dashboard, Auto-dimming interior rearview mirror, Without decals and emblems, MPV, Multifunction camera, Standard luggage compartment floor covering, Fuel tank, Glove compartment with cooling system, Child safety lock, Without child seat, Folding tables on the back of each front seat- articulated, Standard climatic zones, Without dynamic road sign display, Safety-optimized front head restraints- longitudinally and height adjustable, Initial standard fuel filling, Fuel system for fuel-injected SI engine, Rear view camera system, Black radiator grille with chrome trims on the fins, Refrigerant R1234yf, LED license plate lighting, Transport protection film (minimum protection) with additional transport protection measures, Standard paint coating, Luggage compartment floor, Ambient lighting (light strips on door trim inserts in front, front door handles and door armrests illuminated), Left-hand drive, Interior lights with switch-off delay and dimmer- 2 LED reading lights in front and rear, Electromechanical speed-sensitive power steering, Non-folding front passenger seat backrest, Without light control, Power-adjustable lumbar supports in front with massage feature, Leather multi-function steering wheel- heated, Driving on the right, 8 speakers, Headlight range control, Front center armrest- height- and longitudinally adjustable- w/ removable storage compartment- 2 vents in rear, Multi-color Digital Cockpit Pro- selection of different info profiles possible, Decorative inserts "Piano Black" for center console, Driver alert system, Not hot country, 4-cylinder SI engine 1.5 l TSI- 110 kW, Preparation for subsequent activation: Navigation feature "Discover Media" incl. Streaming & Internet, Rear fog lamp, Front fog lamps and cornering light, Online service- with OCU- with head unit coding- without engine immobilizer interconnection, Vehicles without special upgrade measures, Trims for alloy wheels, 4 alloy wheels "Karlstad" 6.5J x 16, Radio, Non-smoker's package: Storage compartment and 12 V outlet in front, Regional code " ECE " for radio, Tire Pressure Monitoring System, Tires 205/60 R16 low rolling resistance, Tires without specification of tire brand, Tire Mobility Set: 12-volt compressor and tire sealant, Wheelbase, 3-point seat belts in front with height adjustment and seat belt pretensioners, eCall Emergency System, Curtain airbag system for front and rear passengers incl. side airbags in front, Gearshift knob in leather, Rear combination lamp- standard design, Easy Open & Close - sensor controlled luggage compartment opening and closing with remote unlocking, Service indicator 30 000 km or 2 years (variable), Warning tone and warning lamp for front seat belts not fastened- warning lamp for rear seat belts not fastened, 3-point seat belts with seat belt pretensioners in rear, Gearshift boot for automatic transmission, Inserts in ArtVelours microfleece, ergoActive seats with height adjustment in front- adjustable seat and backrest angle, Heated front seats, Start-stop system with regenerative braking, Illuminated vanity mirrors in sun visors, Without voice control, Lane change system Side Assist and Rear Traffic Alert, Lane keeping system Lane Assist, Privacy glass for rear side windows and rear window, Without roll-up sunshade, 12 V outlet in center console in rear and in luggage compartment, Body-colored bumpers- front with lower decorative trim in chrome, Rear stabilizer bar, Front stabilizer bar, Without drawers under front seats, Headlamp washer system, Rain sensor, Elimination of nameplate for engine designation on luggage compartment lid, Keyless locking and starting system Keyless Access without SAFELOCK, Type approval country Denmark, Carrier frequency 433.92 MHz-434.42 Mhz, Without partition, Door and side trim panel in foam film and woven fabric, Digital radio reception DAB+, Without additional front underbody guard, Special identification label for EC for M1 passenger vehicles, Without delivery equipment, Warning triangle, Without preparation for two-way radio installation, Premium comfort seats in front, Without preparation for rotating beacon/siren combination, Mobile phone interface, LongLife Service Regime, Without heat accumulator/auxiliary heater, Laminated safety glass windshield- sound-insulating and heated, Warning lamp for washer fluid level, Without additional tires, Carpet mats in front and rear, Chrome trims on the side windows, Without additional side body covers (stone guard), ISOFIX anchorage points (mounting fixture for child seats on rear seats), Without electronic steering column lock, Without auxiliary heater/parking heater, Without additional instruments for distance measurement, Equipment options subset for Denmark

PICTURES



Picture viewer: https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=77fb6166-00f2-4a5e-aff6-c0f3784e50e7&carid=21202266

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	L. Rear Door	Scratch	C4	Reporting needed		Group 1
						
2	L. Rear Quarter Panel	Scratch	C4	Reporting needed		Group 1
						
3	Hood	Scratch	C4	Reporting needed		
						
4	Front Bumper	Scratch	C4	Reporting needed		
						
5	Rear Bumper	Scratch	C4	Reporting needed		
						

Severity explanation:
C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	