VEHICLE DESCRIPTION - Cupra León 2.0 TSI VZ







First registration date 10/2023	**VIN:** VSSZZZKL8RR027057
Colour: null Metalic Normal gloss	**Mileage (km):** 60.342
Gear: Automatic (7 Gears)	**Fuel type:** Gasoline
Body type: Estate Wagon	**Number of doors:** 5
Drive type: 4WD	**Model year:** 2020-2024
Engine power: 228 kW	**Number of seats:** 5
Engine size (cc) 1984	**Interior:** Black Partial leatherette

VEHICLE DETAILS

Number of keys: 2	**Number of license plates:** 2	**Registration certificate:** Part 1 & 2 present	**Service documentation:** Yes
Inspection date: 09-10-2026	**Last service (year/month):** 2023/10	**Mileage (km) at last service:** 6	

SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition: Yes	**Legal tire tread (minimum 1.6 mm):** Yes

WHEELS


TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Alloy rim	19''	4 mm
Fitted	Summer tires		Rear Right	Alloy rim	19''	4 mm
Fitted	Summer tires		Rear Left	Alloy rim	19''	4 mm
Fitted	Summer tires		Front Right	Alloy rim	19''	4 mm

Legal tire tread (minimum 1.6 mm):
Yes

ACCESSORIES

Manually adjustable lumbar support in front seats, Without headlamp washer system- without washer fluid level indicator, Adaptive chassis control with continuous operation, Without fire extinguisher, Without floor mats, Standard dashboard, Variable luggage/load compartment floor, Alloy wheels 8J x 19, Visual and acoustic seat belt reminder- electric contact in front and rear, Without additional front underbody guard, Black Exterior Brightware, Scuff plates in door apertures (illuminated), Heat insulating windshield, Without antenna amplifier, Without heat accumulator/auxiliary heater, Four-wheel drive, Driving on the right, Rear shock absorption for sports version, Fuel system f. fuel-injected SI engine- injection system without fuel return- most powerful engine variant, Center armrest in front, Digital radio reception, Weight range 7 installation control only- no requirement forecast, Emission standard EU6 AP, Black roof rails, Without customized installation, Tires without specification of tire brand, Adaptive cruise control (with "follow-to-stop") and speed limiter, In-plant control of self-collection, Head restraint for front seat, Unsplit molded headliner, Without electric motor (hybrid), Speed-sensitive power steering (Servotronic) w/ limited steering lift mechanism), Side windows in heat-insulating glass- from B-pillar and rear window dark tinted, Standard climatic zones, N/A, Disc brakes in front, Airbag on driver and front passenger side- without knee airbag- with front passenger airbag deactivation, Pedal cluster, Without roof insert (standard roof), Rear window wiper and washer system with intermittent control, Without seat ventilation/massage seat, Luggage compartment cover- sliding, Navigation system - High, 3-point seat belt for center rear seat, Electronic immobilizer, LongLife Service Regime, Without alternative drive system, Operating voltage 12 V, Without charging cable, Without special specifications, Without additional tires, Luggage pockets on backrest, Online service- with OCU- with head unit coding- without engine immobilizer interconnection, Without hill start assist/hill descent control/comfort driving assist, Disc brakes in rear, Exterior mirrors- power-folding/adjustable- heated- w/ front passenger exterior mirror lowering function, Sun visors with mirror- illuminated- with airbag label on sun visor and B-pillar, Standard electric, Basic equipment variant, Type approval country Denmark, Rear spoiler, Without preparation for VTS (vehicle tracking system), With welcome light (mirror), Manual in Danish, Without mass damper for steering wheel, Service indicator 30 000 km or 2 years (variable), No special edition, Without backrest release for front seats, Without surface protection- with additional transport protection measures, Without gearshift knob/handle, Electronic differential lock XDS- dynamic traction support, Keyless locking and starting system Keyless Advanced without SAFELOCK, 4-link rear suspension, Control of series production, UWB-capable country and carrier frequency- 433.92 to 434.42 MHz, Interior ambient lighting- type 2, Sports seats in front, Suspension range 33 installation control only- no requirement forecast, Folding grab handles- multi-piece, External- USB type C data socket(s) and charging socket(s), Vision Plus package: rear view camera system + park assist (including sensors in front and rear), Standard battery/alternator capacity, Mobile phone interface, Without Connect package 1, Without auxiliary heater/parking heater, Brembo Brakes package for CUPRA (brake calipers), 7-speed automatic transmission- four- wheel drive A7A, Windshield wiper intermittent control with light/rain sensor, 4-cylinder gasoline engine 2.0 l/228 kW FSI base engine: TT6/T3W- TSI, Power windows with comfort operation and circuit breaker, Wheelbase, Type sign and company logo, Without delivery equipment, Without drawers under front seats, Freely programmable instrument cluster Medium, Without first aid kit and warning triangle, Tailgate/trunk lid unlocking from outside, Two reading lights in front- two in rear, Speakers in front and rear, Battery 420 A (70 Ah), Mechanical rear seat release, Breakaway interior rearview mirror- auto-dimming, Part set without country-specific prescriptive standard, Refrigerant R1234yf, With emergency steering support with turn assist, Seat trim covers in fabric, Breakdown kit, 3-point seat belts- front, Sports bumpers, Vehicles without special upgrade measures, Without additional side body covers (stone guard), Matrix LED, 4-cylinder SI engine 2.0 l unit 06Q.C 888evo4, Without special body measures, Without partition, Separate daytime running light with automatic headlight control and automat. Coming and Leaving Home feature, Climatronic (3-zone) with air conditioning control panel in rear, With dynamic road sign display, Without mode 3 charging cable, Installation differentiation for transmission DQ381 -- vehicle components --, No special purpose vehicle- standard equipment, Sports equipment Leon VZ, Parking brake, Chrome package, Without head-up display, Single-tone horn, Without socket, Rear traffic alert and lane change system and exit warning system, Vehicle class differentiation - 5FN-, Part-leather door and side trim panel, Seat heater for front seats separately controlled, Without additional noise suppression measures for passenger compartment, Matrix beam, Without heated washer nozzles, Without second battery, Three rear head restraints, Operating permit- alteration, Front stabilizer bar, LED headlamps with variable light distribution, Shock absorption in front, Exterior mirrors: convex on driver side- convex on front passenger side, Supersports steering wheel with tiptronic- heated, Tool kit, Station wagon LEON Sportstourer, Activated carbon canister (Evaporative Emission Control System (EVAP)), Non-smoker's package, Brake control system for vehicles without electric drive (ESC and electromechanical brake booster), Side airbag in front with curtain airbag and interaction airbag in front, Unsplit rear seat bench- split folding backrest- with center armrest, Mirror Link plus Wireless "App" plus RSE (preparation), Without Car2X, Front license plate carrier (large), Data storage device for EU- integrated, Not hot country, Driver alert system, Pan-European emergency call service, Infotainment system with scalable module options (Optionsinfotainment) (MIB3) (version 2), LED rear combination lamp- dynamic turn signal, Alternator 140 A, Special identification label for EC for M1 passenger vehicles, Child seat anchors f. child seat system i-Size- 2x top tether and child seat anchors in front on front passenger side, Rear fog lamp, Voice control, 3-point seat belts- outer rear with ECE label, Initial standard fuel filling, Antenna for FM reception only- diversity, Emblems, Standard wheel bolts, Exterior mirror housings painted, With rear view camera system (type 2), Tire pressure monitoring system, Regional code " ECE " for radio, With multifunction camera, Forward collision warning with warning and braking reaction to vehicles- pedestrians and cyclists, Rear floor panel module- type 4, Dynamic headlight range control (self-adjusting while driving), Rear stabilizer bar, Manual height adjustment for front seats, Without nameplate set (without model designation), Park assist, Tires 235/35 R19 91Y, Lane keeping system plus semi-automatic vehicle control in a medical emergency and traffic jam assist, Trailer hitch preparation, Front fog lamps, Left-hand drive, Start-stop system with regenerative braking, Instrument cluster- km/h speedometer, Without extended safety system, Without locking and starting systems, Luggage compartment trim- with storage compartments, Standard electronic engine sound, Decorative inserts for console, Standard manufacturing sequence, Equipment options subset for Denmark

PICTURES



Picture viewer: https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=3f9bbf87-12c9-46d2-9b32-45cb59ead9c9&carid=21240034

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	R. Front Rim	Scratch	C5	Reporting needed		
	 					
2	Rear Bumper	Dent	C3			
	  					
3	L. Rear Door Trim	Scratch	C3			
	 					
4	Rear Hood	Dent	C3			
	 					

Severity explanation:
C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	