VEHICLE DESCRIPTION - Škoda Kamiq Monte Carlo 1.0 TSI







First registration date 9/2025	**VIN:** TMBGR9NWXS3139477
Colour: Black Metalic Normal gloss	**Mileage (km):** 17.723
Gear: Automatic (7 Gears)	**Fuel type:** Gasoline
Body type: SUV	**Number of doors:** 5
Drive type: FWD	**Model year:** 2024
Engine power: 85 kW	**Number of seats:** 5
Engine size (cc) 999	**Interior:** Black Fabric

VEHICLE DETAILS

Number of keys: 2	**Number of license plates:** 2	**Registration certificate:** Part 1 & 2 present	**Service documentation:** Yes
Inspection date: 09-10-2026	**Last service (year/month):** 2025/9	**Mileage (km) at last service:** 1	

SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition: Yes	**Legal tire tread (minimum 1.6 mm):** Yes

WHEELS

TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Alloy rim	17''	7 mm
Fitted	Summer tires		Rear Right	Alloy rim	17''	7 mm
Fitted	Summer tires		Rear Left	Alloy rim	17''	7 mm
Fitted	Summer tires		Front Right	Alloy rim	17''	7 mm


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES

Vehicle class differentiation -655-, Battery 320 A (49 Ah), Scuff plates in door apertures, Without heat accumulator/auxiliary heater, Without two-sided floor surface, Axial and vertical adjustable steering column, Matrix beam, Initial standard fuel filling, Fuel system for fuel-injected SI engine (tropicalized), Front fog lamp and cornering lamp, Radiator grille - black, With umbrella, Side airbag in front and rear with curtain airbag, Without headlamp washer system, Rear floor panel module- type 1, Interior ambient lighting- type 1, Without bracket, Without overhead storage compartment, Mounting fixture in luggage compartment, Service indicator 30 000 km or 2 years (variable), Heat-reflecting windshield, Climatronic with impact pressure control- CFC-free, Electronic stability control (ESC), Regional code " ECE " for radio, Alternator 140 A, Entry-level infotainment system radio upgrade (UNECE), Rear shock absorption, Standard climatic zones, Nameplate set, Disc brakes in front (Geomet D), Monte Carlo, Without additional noise suppression measures for passenger compartment, Single-tone horn, With trim panel, Non-smoker's package, Tool kit, Crew Protect Assist, Interiorbars and air vents frame Red, Right exterior mirror- convex, Bluetooth, With dynamic road sign display, Dynamic headlight range control (self-adjusting while driving), Without adapter, Luggage net, Without waste bin, Central locking system Keyless Entry without SAFELOCK, Transport protection film with additional transport protection measures, Antifreeze up to -25 degree Celsius tolerance up to -30 degree C, Seat trim covers in fabric, External- USB type C data socket(s) and charging socket(s) with increased charging capacity, 4 doors, Extended and proactive pedestrian and cyclist protection, Rear overhang- short, Additional front underbody guard, Panoramic sunroof, Center armrest in front "Jumbo Box", Weight range 13 installation control only- no requirement forecast, Seat heater for front seats separately controlled, Drum brakes in rear, Basic equipment variant, Special edition, Left exterior mirror- convex, Without luggage/load compartment floor, Glove compartment door with light, Fresh air intake system with combination filter, Rear and front parking sensors, Key for locking system with remote control, Not hot country, Without heated washer nozzles, With multifunction camera, Power windows with comfort operation and circuit breaker, Standard decorative trims, Without backrest release for front seats, Additional body cover on sill without wheel arch, Manually adjustable lumbar support in front seats, Without trailer hitch, Wheelbase, Without decorative films/emblems, Front stabilizer bar, Without protective side molding, Carrier frequency 433.92 MHz- 434.42 Mhz, door panels with leatherette, Without electronic steering column lock, Alloy wheels 6.5J x 17" "KAJAM Aero" black, Full LED Headlights, Left-hand drive, Remote Access / Pro-active service, Black ceiling, Without lane change assist, Antenna for FM reception only- diversity, 3-cylinder SI engine 1.0 l unit 05C.B, Fuel filler cap, 8 speakers (passive), Without folding table on front seat backrest, Without alternative drive system, Without navigation device, Three rear head restraints, Without auxiliary heater/parking heater, Outside door mirrors in black color, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Activated carbon canister (Evaporative Emission Control System (EVAP)), Aluminium pedals, Child seat anchors f. child seat system i-Size- 2x top tether and child seat anchors in front on front passenger side, 3-cylinder SI engine 1.0 l/85 kW TSI base engine is TJ4/T0R/T26/T0M/T1D/T6A, Tires 205/55 R17 91V Low Rolling Resistance, Advanced driver attention & drowsiness monitor, Suspension range 25 installation control only- no requirement forecast, Shock absorption in front, Sunset, Power steering, 3-point seat belts in front- with tensioner and height adjustment, Electronic immobilizer, Crossover, Adaptive cruise control (for DSG) with Speedlimiter, Driving on the right, With rear view camera system (type 2), Without storage compartment package/box, Head restraints for front seats, Freely programmable instrument cluster Basic, Breakaway interior rearview mirror- auto-dimming, Drive Mode Select without Chassis Presets, Floor mats in front and rear, Sport Seats, Special identification label for EC for M1 passenger vehicles, Standard tailgate, 12-volt socket in luggage boot, Hub cap, exterior mirrors- dimmable on driver side- power folding- adjustable- heated, Without refrigerator/glove compartment cooling system, Rear axle weight- type 1, 3-point seat belts- outer rear with ECE label, DAB - Digital radio reception, ECO function, Without drawers under front seats, Black roof rails, Gearshift knob/handle in leather, 7-speed automatic transmission, Rear window wiper and washer system with intermittent control, Tire pressure monitoring system, "Standard Plus" version, Lane assist +, Instrument cluster- km/h speedometer, Tailgate without electrical opening, Without delivery equipment, Breakdown kit, Operating permit- alteration, Without fire extinguisher, Type approval country Denmark, 3-point seat belt for center rear seat, Front-wheel drive, Wired & Wireless Smart Link+, Unsplit rear seat bench- split folding backrest- with center armrest, Driver knee airbag, Without partition, Installation differentiation for transmission DQ200 -- vehicle components --, Curb weight range 1, Refrigerant R1234yf, Part set without country-specific prescriptive standard, No special purpose vehicle- standard equipment, Standard rear axle, Manual height adjustment for front seats, LongLife Service Regime, With UNECE CS (R155) without SU (R156), Visual and acoustic seat belt reminder- electric contact, Hill hold control, Sun visors with mirror and airbag label on front passenger side, Windshield wiper intermittent control with light/rain sensor, Center console, Start-stop system with regenerative braking, Additional exterior noise suppression, Standard wheel bolts, Manual in Danish, Tires without specification of tire brand, Emergency call system eCall+, Standard manufacturing sequence, Emission standard- WLTP3 M1- N1-I//EU6EB, Leather multi-function steering wheel with tiptronic- heated, LED rear combination lamp- dynamic turn signal- special styling, Net under the luggage compartment cover, Without additional malfunction display, Washer fluid level indicator, Without second battery, Remote Access 3 years, Standard paint coating, Decorative inserts, Without voice control, Body-colored bumpers, "FRONT ASSIST" incl. adaptive cruise control, Equipment options subset for Denmark

PICTURES



Picture viewer: https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=a487d044-4e00-40b2-88b8-200f45466570&carid=25524034

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	R. Front Rim	Scratch	C5	Reporting needed		
	 					
2	L. Rear Quarter Panel	Scratch	C4	Reporting needed		Group 1
	 					
3	Rear Bumper	Scratch	C4	Reporting needed		Group 1
	  					
4	Hood	Stone Chips	C3			
						
5	R. Rocker Panel, Inside	Scratch	C3			
						
6	Rear Hood	Scratch	C3			
						
7	L. Rear Door	Scratch	C3			
	 					
8	L. Rocker Panel, Inside	Scratch	C3			
						
9	Trunk Cover, Mats	Discoloration	C3			
						

Severity explanation:
C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	