

VEHICLE DESCRIPTION - Škoda Karoq Style 1.5 TSI



First registration date:
3/2022

VIN:
TMBJR7NU6N5028460

Colour:
Black Metallic Normal gloss

Mileage (km):
90.623

Gear:
Automatic (7 Gears)

Fuel type:
Gasoline

Body type:
SUV

Number of doors:
5

Drive type:
FWD

Model year:
2017-2022

Engine power:
110 kW

Number of seats:
5

Engine size (cc):
1498

Interior:
Grey Fabric

VEHICLE DETAILS

Number of keys:
2

Number of license plates:
2

Registration certificate:
Part 1 & 2 present

Service documentation:
Yes

Inspection date:
09-04-2026

Last service (year/month):
2024/6

Mileage (km) at last service:
52.557

SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition:
Yes

Legal tire tread (minimum 1.6 mm):
Yes

WHEELS

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Winter tires		Rear Left	Steel rim	16"	6 mm
Fitted	Winter tires		Front Right	Steel rim	16"	6 mm
Fitted	Winter tires		Front Left	Steel rim	16"	6 mm
Fitted	Winter tires		Rear Right	Steel rim	16"	6 mm
Extra Wheel	Summer tires		Rear Left	Alloy rim	18"	5 mm
Extra Wheel	Summer tires		Front Right	Alloy rim	18"	5 mm
Extra Wheel	Summer tires		Front Left	Alloy rim	18"	5 mm
Extra Wheel	Summer tires		Rear Right	Alloy rim	18"	5 mm


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES












Driving on the right, Luxury equipment, Part set without country-specific prescriptive standard, Type approval country Denmark, Operating permit- alteration, 4-cylinder SI engine 1.5 l/110 kW TSI base engine is TJ7/N09/T9F/T57/T0D, Without ECO function, Without emblem package, Remote Access / Remote Access + Online Infotainment, "DRIVER ALERT" - driver alert system, Regional code " ECE " for radio, Without vehicle inlet, No special edition, Standard paint coating, Basic equipment variant, No special purpose vehicle- standard equipment, Standard electronic engine sound, Shock absorption in front, 7-speed automatic transmission, Without bracket, Curb weight range 1, Rear axle weight- type 1, Battery 420 A (70 Ah), Without camera systems/accident sensors, Refrigerant R1234yf, MPV, Left-hand drive, Suspension range 10 installation control only- no requirement forecast, Without adapter, Standard battery/alternator capacity, Emergency call system eCall+, Seat trim covers in fabric, Storage compartment package 3, LongLife Service Regime, Voice control, Service indicator 30 000 km or 2 years (variable), Chrome package (type 2), With multifunction camera, Interior ambient lighting- type 2, Without dynamic road sign display, DAB - Digital radio reception, Comfort seats in front, Tires 215/50 R18 92W low rolling resistance, Control of logistics 2, Control (in-plant), 4-cylinder SI engine 1.5 l unit 05E.A, Rear shock absorption- chassis with increased ride height, Hill start assist, Parking brake, Mechanical rear seat release, Alloy wheels "BRAGA" silver 7J x 18" - 4 pcs, Instrument cluster- km/h speedometer, External- USB type C- only data socket(s), Standard pedal cluster, Extended and proactive pedestrian protection, Tires without specification of tire brand, Remote Access 1 year, Front stabilizer bar, 4 doors, Without rear stabilizer bar, Wheelbase, Installation differentiation for transmission DQ200 -- vehicle components --, Standard manufacturing sequence, Without alternative drive system, Nameplate set in basic style, Standard rear axle, Rear exhaust tailpipe (standard), Textile floor mats, Manual in Danish, Weight range 6 installation control only- no requirement forecast, Standard climatic zones, Electronic stability control (ESC), Fuel system for fuel-injected SI engine, Trailer hitch preparation, Special identification label for EC for M1 passenger vehicles, Activated carbon canister (Evaporative Emission Control System (EVAP)), Breakdown kit, Air cleaner for dusty regions, Trims for alloy wheels, Speed-related variable steering assist (Servotronic), Standard wheel bolts, Without additional front underbody guard, Tool kit, Without folding table on front seat backrest, Front-wheel drive, Disc brakes in front (Geomet D), Initial standard fuel filling, Without delivery equipment, Additional exterior noise suppression, Disc brakes in rear, 3 spoke sport multi-function leather steering wheel with DSG paddles, Without locking and starting systems, Without "drive select", Standard bumpers, Labels in Danish- Finish and Swedish, Fuel filler cap, Without electric motor (hybrid), Child seat anchors for child seat system ISOFIX, Without partition, Without roof insert (standard roof), Without luggage/load compartment floor, Without child seat anchor in front (ISOFIX), Without backrest release for front seats, Door and side trim panel, Manual height adjustment for front seats, Unsplit rear seat bench- split folding backrest- with center armrest, Without storage compartments in trunk, 3-point seat belts in front- with tensioner and height adjustment, Bright roof rails, 3rd rear headrest, Without additional noise suppression measures for passenger compartment, Without load-through hatch, 3-point seat belts- outer rear with ECE label, Heated front seats, Emission standard EU6 AP, Tailgate/trunk lid release from inside (electrically), Heat-reflecting windshield, Manual child safety lock, "KESSY FULL" without SAFE system, "SUNSET", Inside rear view mirror automatically dimming, Rear floor panel module- type 7, Power windows with comfort operation and circuit breaker, Driver knee airbag, Curtain airbags and side airbags front, Bright decorative trims, Without special body measures, Carrier frequency 433.92 MHz-434.42 Mhz, Roof spoiler, Transport protection film with additional transport protection measures, Decorative insert "CHROM/DARK BRUSHED", Folding grab handles- multi-piece, Right exterior mirror- convex, Left exterior mirror- convex, Sun visors with illuminated vanity mirror on driver and front passenger side, Front head restraints, Without additional side body covers (stone guard), Front armrest "JUMBO BOX", Exterior mirror housings and various add-on parts in body color, Without decorative films/emblems, Lane Assist (without HOD), Radiator grille, Forward collision warning incl. autonomous emergency braking- for adaptive cruise control "high", Without tie down straps/net/pocket, Without mud flap, Gearshift knob/handle in leather, Luggage compartment floor covering in flat needle-punched nonwoven, Interior light in footwell in front and rear, Exterior mirrors- auto-dimming- power-folding/adjustable/heated, Electronic immobilizer, 12-volt socket in luggage boot, Without heat accumulator/auxiliary heater, Tyre pressure monitoring, Vehicle class differentiation -5EP-, Start-stop system with regenerative braking, Plastic scuff plates in door apertures, Glasses storage compartment, Driver and passenger seat with lumbar support, Radio Bolero, Without extended safety system, Park distance control system (parking sensors rear), "SIDE ASSIST" - blind spot information system, Infotainment Bolero/Amundsen/Columbus (MIB3), Alternator 140 A, High-beam control, LED headlamps with cornering light (separate daytime running lamps with special class-A surface), Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Rear window wiper and washer system with intermittent control, Windshield wiper intermittent control with light/rain sensor, Key for locking system with remote control, Dynamic headlight range control- with cornering light (AFS 1), Additional 4 loudspeakers rear, 2 reading lights in front, Rear fog lamp, Adaptive cruise control (with "follow-to-stop") and speed limiter, Front fog lamp and cornering lamp, Washer fluid level indicator, Headlamp washer system, Two-tone horn, Antenna for FM reception only- diversity, Not hot country, Climatronic with impact pressure control- CFC-free, Without additional malfunction display, Comfort telephony with LTE and wireless charging, Non-smoker's package, Without supertone system and tone sequence control, Without auxiliary heater/parking heater, Passenger seat-belt warning light (for all passengers), Colour "MAXI DOT", Additional retro-reflectors (door area), Heated windscreen washer nozzles, Brake pad wear indicator, "SMART LINK" (wireless for Apple), Operating voltage 12 V, Equipment options subset for Denmark









PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=448fdd29-1ef8-409d-ac57-642a71f0aad4&carid=19186306>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	Hatch Cover	Scratch	C5		Reporting needed	
						
2	L. Rear Door Trim	Scratch	C5		Reporting needed	
						
3	L. Roof Pillar, C-Pillar	Scratch	C5		Reporting needed	
						
4	Passenger Seat, Back	Scratch	C5		Reporting needed	
						
5	Rear R. Door Trim	Scratch	C5		Reporting needed	
						
6	L. Rear Light	Scratch	C5		Reporting needed	Group 1
						
7	Rear Hood	Scratch	C4		Reporting needed	Group 1
						
8	R. Front Door	Dent	C4		Reporting needed	
						
9	L. Rear Door	Dent	C4		Reporting needed	
						
10	R. Front Door Trim	Scratch	C4		Reporting needed	
						
11	L. Roof Pillar, C-Pillar	Scratch	C4		Reporting needed	
						

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
12	R. Rear Door	Dent	C3			
						
13	L. Rear Quarter Panel	Dent	C3			
						
14	L. Rear Quarter Panel	Scratch	C3			
						
15	R. Rear Door	Scratch	C3			
		 				
16	R. Rear Quarter Panel	Paint Flaking	C3			
		 				
17	R. Rear Quarter Panel	Scratch	C3			
						

Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	
2	Warning Indicators, Service	Lights	