



→ VEHICLE DESCRIPTION - Seat León FR 1.5 TSI







| First registration date 12/2022 | VIN: VSSZZZKLOPR003834 |
|---------------------------------|---------------------------|
| Colour: | Mileage (km): |
| Black Metalic Normal gloss | 43.896 |
| Gear: | Fuel type: |
| Automatic (7 Gears) | Gasoline |
| Body type: | Number of doors: |
| Estate Wagon | 5 |
| Drive type: | Model year: |
| FWD | 2020 |
| Engine power: | Number of seats: |
| 110 kW | 5 |
| Engine size (cc) | Interior: |
| 1498 | |

19-12-2025

Number of license plates: Registration certificate: Number of keys: Service documentation: 2 2 Part 1 & 2 present No

Inspection date: Last service (year/month):

Mileage (km) at last service:

SUMMARY OF THE VEHICLE'S CONDITION

Legal tire tread (minimum 1.6 Is the car in a driveable condition: mm):

Yes

Yes



Group

WHEELS

| Fitted | | | RIM | SIZE | TREAD |
|-------------|--------------|-------------|-----------|------|-------|
| | Winter tires | Rear Left | Steel rim | 16'' | 6 mm |
| itted | Winter tires | Front Right | Steel rim | 16'' | 6 mm |
| itted | Winter tires | Front Left | Steel rim | 16'' | 6 mm |
| itted | Winter tires | Rear Right | Steel rim | 16'' | 6 mm |
| xtra Wheel | Summer tires | Rear Left | Alloy rim | 17'' | 5 mm |
| Extra Wheel | Summer tires | Front Right | Alloy rim | 17'' | 5 mm |
| extra Wheel | Summer tires | Front Left | Alloy rim | 17'' | 5 mm |
| Extra Wheel | Summer tires | Rear Right | Alloy rim | 17'' | 5 mm |




ACCESSORIES

Trailer hitch aftermarket equipment- power-folding, Driving on the right, In-plant control of self-collection, Exclusive sports equipment FR, Part set without countryspecific prescriptive standard, Type approval country Denmark, Alloy wheels 7.5J x 17, Operating permit- alteration, 4-cylinder gasoline engine 1.5 I/110 kW mild hybrid- TSI base engine: TJ7- eTSI, Online service- with OCU- with head unit coding- without engine immobilizer interconnection, Driver alert system, Regional code " ECE " for radio, Without charging cable, No special edition, Control of series production, Without customized installation, Basic equipment variant, No special purpose vehicle- standard equipment, Antenna amplifier type 1, Standard electronic engine sound, Vehicles without special upgrade measures, Without Car2X, Shock absorption in front, 7-speed automatic transmission "A7", Tires 225/45 R17 91W, Without Connect package 1, Battery 420 A (70 Ah), Without camera systems/accident sensors, Climatronic (3-zone) with air conditioning control panel in rear, Refrigerant R1234yf, Without head-up display, Station wagon LEON Sportstourer, Left-hand drive, Suspension range 13 installation control only- no requirement forecast, Standard battery/alternator capacity, Private emergency call system, Seat trim covers in fabric, Connectivity Box: inductive charging station + mobile phone signal booster, Sensor-controlled luggage compartment opening and closing, Safe & Driving package XL (for navigation system), LED Interior Lighting package: glove comp.- sun visor- footwell-stor. comp.- multicolor ambient lighting all around, Keyless locking and starting system Keyless Access without SAFELOCK, Trailer hitch preparation, Full LED - LED headl./rear comb. lamps- automatic headlight range control-(Welcome Light- Coming/Leaving Home), LongLife Service Regime, Voice control, Service indicator 30 000 km or 2 years (variable), Chrome package, With multifunction camera, Drawer under left front seat, Interior ambient lighting- type 2, With dynamic road sign display, Digital radio reception, Standard seats in front, Decorative inserts for console, Control PR code for vehicle tracking, 4-cylinder SI engine 1.5 I unit 05E.A, Without hill start assist/hill descent control/comfort driving assist, Parking brake, Mechanical rear seat release, Instrument cluster- km/h speedometer, External- USB type C data socket(s) and charging socket(s), Standard pedal cluster, 48-V electric system, Scuff plates in door apertures (illuminated), Tires without specification of tire brand, Front stabilizer bar, Without rear stabilizer bar, Wheelbase, Installation differentiation for transmission DQ200 -- vehicle components --, Standard manufacturing sequence, Hybrid drive MHEV "eTSI", Nameplate set in basic style, Standard rear axle, Without floor mats, Without information kit, Weight range 7 installation control only- no requirement forecast, Standard climatic zones, Without special specifications, Brake control system for vehicles with electric drive (ESC and electromechanical brake booster), Fuel system for fuel-injected SI engine, Special identification label for EC for M1 passenger vehicles, Activated carbon canister (Evaporative Emission Control System (EVAP)), Breakdown kit, Rear shock absorption- sports version, With welcome light (mirror), Disc brakes in rear, Speed-related variable steering assist (Servotronic), Standard wheel bolts, Without mass damper for steering wheel, Without additional front underbody guard, Tool kit, Without first aid kit and warning triangle, Front-wheel drive, Electronic differential lock XDS- dynamic traction support, Disc brakes in front (Geomet D), Initial standard fuel filling, Without delivery equipment, Vehicle class differentiation -5FN-, Leather-wrapped multi-function steering wheel- heated- with tiptronic, Without locking and starting systems, Driving profile selection and conventional shock absorber, Sports bumpers, Labels in Danish- Finish and Swedish, Without additional tires, Type sign and company logo, Without electric motor (hybrid), Child seat anchors f. child seat system i-Size- 2x top tether and child seat anchors in front on front passenger side, Without partition, 3-point seat belt for center rear seat, Without roof insert (standard roof), Variable luggage/load compartment floor, Without backrest release for front seats, Part-leather door and side trim panel, Manual height adjustment for front seats, Unsplit rear seat bench- split folding backrest- with center armrest, 3-point seat belts- front, Black roof rails, Three rear head restraints, Luggage compartment cover- sliding, Without additional noise suppression measures for passenger compartment, 3-point seat beltsouter rear with ECE label, Front license plate carrier (large), Seat heater for front seats separately controlled, Emission standard EU6 AP, Without seat ventilation/massage seat, Sensor-controlled luggage compartment opener, Heat-reflecting windshield, With emergency steering support with turn assist, Side windows in heat-insulating glass- from B-pillar and rear window dark tinted, Keyless locking and starting system Keyless Advanced without SAFELOCK, Breakaway interior rearview mirror- auto-dimming, Standard dashboard, Rear floor panel module- type 4, Power windows with comfort operation and circuit breaker, Airbag on driver and front passenger side- without knee airbag- with front passenger airbag deactivation, Luggage pockets on backrest, Standard decorative trims, Luggage compartment trim- with storage compartments, Without special body measures, UWB-capable country and carrier frequency- 433.92 to 434.42 MHz, Exterior mirrors: convex on driver side- convex on front passenger side, Rear spoiler, Transport protection film (minimum protection) with additional transport protection measures, Folding grab handles- multi-piece, Sun visors with mirror- illuminated- with airbag label on sun visor and B-pillar, Front head restraints, Without fire extinguisher, Side airbag in front with curtain airbagand interaction airbag in front, Without additional side body covers (stone guard), Center armrest in front, Exterior mirror housings painted, Emblems, Lane keeping system plus semi-automatic vehicle control in a medical emergency and traffic jam assist, Unsplit molded headliner, Without gearshift knob/handle, Exterior mirrors- power-folding/ adjustable- heated- w/ front passenger exterior mirror lowering function, Electronic immobilizer, 12-volt socket in luggage boot, Without heat accumulator/auxiliary heater, Without preparation for VTS (vehicle tracking system), Freely programmable instrument cluster Medium, Tire pressure monitoring system, Start-stop system with regenerative braking, Manually adjustable lumbar support in front seats, Navigation system - High, Without extended safety system, Park distance control, Without mode 3 charging cable, Data storage device for EU- integrated, Rear traffic alert and lane change system and exit warning system, Optional infotainment system (MIB3), Without second battery, High-beam control, LED headlamps with lens, Forward collision warning with warning and braking reaction to vehicles- pedestrians and cyclists, Rear window wiper and washer system with intermittent control, Windshield wiper intermittent control with light/rain sensor, Dynamic headlight range control (self-adjusting while driving), Speakers in front and rear, LED rear combination lamp, Two reading lights in front- two in rear, Rear fog lamp, Adaptive cruise control (with "follow-to-stop") and speed limiter, Front fog lamps, Without headlamp washer system- without washer fluid level indicator, Single-tone horn, Antenna for FM reception only- diversity, Not hot country, Belt-driven integrated starter alternator 48 V 110 - 250 A, Comfort telephony with LTE and wireless charging, Separate daytime running light with automatic headlight control and automat. Coming and Leaving Home feature, Non-smoker's package, Without auxiliary heater/parking heater, Visual and acoustic seat belt reminder- electric contact in front and rear, Without heated washer nozzles, Mirror Link plus Wireless "App" plus RSE (preparation), Operating voltage 12 V, Equipment options subset for Denmark



PICTURES



Picture viewer: https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=167cd261-1e3e-40c7-ac97-34116adc6f09&carid=19804066



Group

OVERVIEW OF DAMAGES AND SHORTAGES

| N° LOCATION | TYPE | SEVERITY | INSURANCE | NOTES | DAMAGE GROUP |
|------------------|---------|----------|----------------|-------|--------------|
| 1 L. Roof Pillar | Dent | C5 | Reporting done | | Group 1 |
| 2 Roof | Dent | C4 | Reporting done | | Group 1 |
| 3 Front Bumper | Scratch | C4 | Reporting done | | |
| 4 L. Rear Door | Scratch | C3 | | | |
| 5 Rear Hood | Dent | C3 | | | |

Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

| N° LOCATION | TYPE | NOTES |
|-----------------------|------|-------|
| 1 Is the car drivable | Yes | |
| | | |