

VEHICLE DESCRIPTION - Škoda Superb Style 1.5 TSI ACT



First registration date:
1/2023

VIN:
TMBJN7NP2P7025598

Colour:
null Metallic Normal gloss

Mileage (km):
83.855

Gear:
Automatic (7 Gears)

Fuel type:
Gasoline

Body type:
Estate Wagon

Number of doors:
5

Drive type:
FWD

Model year:
2019-2024

Engine power:
110 kW

Number of seats:
5

Engine size (cc):
1498

Interior:
Black Fabric

VEHICLE DETAILS

Number of keys:
2

Number of license plates:
2

Registration certificate:
Part 1 & 2 present

Service documentation:
Yes

Inspection date:
02-03-2026

Last service (year/month):
2026/1

Mileage (km) at last service:
83.437

SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition:
Yes

Legal tire tread (minimum 1.6 mm):
Yes

WHEELS

|  TYPE | SEASON | BRAND | POSITION | RIM | SIZE | TREAD |
|---|--------------|-------|-------------|-----------|------|-------|
| Fitted | Winter tires | | Front Left | Steel rim | 16" | 4 mm |
| Fitted | Winter tires | | Rear Right | Steel rim | 16" | 7 mm |
| Fitted | Winter tires | | Rear Left | Steel rim | 16" | 7 mm |
| Fitted | Winter tires | | Front Right | Steel rim | 16" | 4 mm |
| Extra Wheel | Summer tires | | Rear Left | Alloy rim | 17" | 5 mm |
| Extra Wheel | Summer tires | | Front Right | Alloy rim | 17" | 5 mm |
| Extra Wheel | Summer tires | | Front Left | Alloy rim | 17" | 5 mm |
| Extra Wheel | Summer tires | | Rear Right | Alloy rim | 17" | 5 mm |


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES











Driving on the right, Equipment level - Style, Part set without country-specific prescriptive standard, Type approval country Denmark, Alloy wheels "STRATOS" 7jx17", Operating permit- alteration, 4-cylinder SI engine 1.5 l/110 kW TSI base engine is TJ7/N09/T9F/T57/T0D, Without ECO function, Remote Access / Remote Access + Online Infotainment, "DRIVER ALERT" - driver alert system, Regional code " ECE " for radio, Without vehicle inlet, Without charging cable, No special edition, Standard paint coating, Basic equipment variant, No special purpose vehicle- standard equipment, Standard electronic engine sound, Vehicles with special upgrade measures, Shock absorption in front, 7-speed automatic transmission, Without bracket, Curb weight range 1, Battery 420 A (70 Ah), Tires 215/55 R17 94V super-low rolling resistance- generation 2 (polymer coating), "REAR VIEW CAMERA MID", Climatronic (3-zone) with air conditioning control panel in rear, Refrigerant R1234yf, Without head-up display, Wagon/Avant, Left-hand drive, Suspension range 05 installation control only- no requirement forecast, Without adapter, Standard battery/alternator capacity, Emergency call system eCall+, Seat trim covers in fabric, Without child seat, LongLife Service Regime, Voice control, Service indicator 30 000 km or 2 years (variable), Chrome package (type 2), With multifunction camera, Interior ambient lighting- type 2, Without compass/road sign display/ dynamic road sign display, DAB - Digital radio reception, Comfort seats in front, Navigation system "AMUNDSEN" with voice control + WLAN + Web Radio + "SMART LINK"(wireless for Apple devices), 4-cylinder SI engine 1.5 l unit 05E.A, Hill hold control, Parking brake, Standard rear seat release, Without clock, Instrument cluster- km/h speedometer, 2x USB front, Without garage door opener, Standard pedal cluster, Extended and proactive pedestrian protection, Tires without specification of tire brand, Remote Access + Infotainment Online 1 year, Wheelbase, Installation differentiation for transmission DQ200 -- vehicle components --, Standard manufacturing sequence, Without alternative drive system, Fuel tank, Nameplate set in basic style, Rear exhaust tailpipe (standard), With electronic steering column lock, Textile floor mats, Manual in Danish, Weight range 3 installation control only- no requirement forecast, Standard climatic zones, Brake control system for vehicles without electric drive (ESC and electromechanical brake booster), Fuel system for fuel-injected SI engine, Tow bar- swiveling, Special identification label for EC for M1 passenger vehicles, Activated carbon canister (Evaporative Emission Control System (EVAP)), Breakdown kit, Rear shock absorption- basic version 1, Trims for alloy wheels, Speed-related variable steering assist (Servotronic), Standard wheel bolts, Without mass damper for steering wheel, Without additional front underbody guard, Tool kit, Front-wheel drive, Disc brakes in front, Initial standard fuel filling, Without delivery equipment, Disc brakes in rear, Without locking and starting systems, Without "drive select", Body-colored bumpers, Without additional tires, 2 spoke multifunction leather steering wheel- black stitching, Without electric motor (hybrid), Child seat anchors for child seat system ISOFIX, Without partition, 3-point seat belt for center rear seat, Center console, Without roof insert (standard roof), Without luggage/load compartment floor, Without child seat anchora in front (ISOFIX), Without backrest release for front seats, Door and side trim panel in foam film and woven fabric, Power seats in front- driver seat with memory feature, Unsplit rear seat bench- split folding backrest- with center armrest, Storage box with cover in luggage compartment side panel (covers on both sides) plus cargoelement, 3-point seat belts in front- with tensioner and height adjustment, Roof rails- anodised, Three rear head restraints, Luggage compartment cover- folding, Additional interior noise suppression, Without load-through hatch, Without roll-up sunshade, 3-point seat belts- outer rear with ECE label, Heated front seats, Emission standard EU6 AP, Without seat ventilation/massage seat, Electrically opening and closing tailgate/trunk lid (Tailgate/trunk lid electrically operated wo. Virtual pedal), Heat-reflecting windshield, Power-operated child safety lock, "KESY FULL" without "SAFE" system, Side and rear windows in heat-insulatingglass, Breakaway interior rearview mirror- auto-dimming, Driver knee airbag, Front passenger seat control, Side airbag in front with curtain airbag, Chrom trimming around side windows, Without special body measures, Carrier frequency 433.92 MHz-434.42 Mhz, Roof spoiler, Transport protection film with additional transport protection measures, Right exterior mirror- convex, Left exterior mirror- convex, Decor moulding Argenzo Zebrano with chrom and ambient lighting, Sun visor with make-up mirror and LED illumination and airbagschield, Front head restraints, Without fire extinguisher, Center armrest in front, Exterior mirror housings and various add-on parts in body color, Without lane keeping system, Radiator grille with chrome molding, "FRONT ASSIST" - radar scanning of the space in front of the car- incl. City ANB- wo. "ADAPTIVE CRUISE ASSISTANT", Without tie down straps/net/pocket, Unsplit molded headliner, Without mud flap, Gearshift knob/handle in leather, Interior light in footwell in front and rear, Ext. mirrors with memory feature- auto- dimming on driver's side- el.folding/ adjustable- separately heated, Electronic immobilizer, 12-volt socket(s), Without heat accumulator/auxiliary heater, Tire pressure monitoring system, Start-stop system with regenerative braking, Decorative door sills front and rear, Power-adjustable lumbar support in frontseats, Without CD/DVD for navigation, Navi Amundsen + Web radio, Standard engine starter, Without extended safety system, PDC with "MANOEUVRE ASSIST" - parking sensors front & rear with aut. braking, Without lane change assist, Vehicle class differentiation -3V0-, Optional infotainment system (MIB3), Without second battery, Alternator 140 A, High-beam control, Low LED Basic headlamps + LED Daylight, "LIGHT ASSISTANT" ("COMMING HOME"- "LEAVING HOME"- "TUNNEL LIGHT"- "DAY LIGHT"), Rear window wiper "AERO", Windshield wiper intermittent control with light/rain sensor, Key for locking system with remote control, Headlight range control, 8 speakers (passive), LED taillights, Rear fog lamp, "CRUISE CONTROL" - with Speedlimiter, Front fog lamp and cornering lamp, Telescopic headlamps washers, Two-tone horn, Antenna for FM reception only- diversity, Not hot country, Without preparation for two-way radio installation, Without additional malfunction display, Comfort telephony with LTE and wireless charging, Non-smoker's package, Without auxiliary heater/parking heater, Passenger seat-belt warning light (for all passenger), "Virtual Cockpit", Additional warning lights (door area), Heated windscreen washer nozzles, "SMART LINK" (wireless for Apple), Operating voltage 12 V, Equipment options subset for Denmark





PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=582386c7-f89d-4f07-8039-031b973a9086&carid=19804337>

OVERVIEW OF DAMAGES AND SHORTAGES

| N° | LOCATION | TYPE | SEVERITY | INSURANCE | NOTES | DAMAGE GROUP |
|----|--------------------------|---|----------|-----------|--|--------------|
| 1 | | Mangler | | | Indlevering af genstande (Ekstra hjul) | |
| 2 | Front Windscreen | Rep Defect C5 | | | Reporting done | |
| | |  | | | | |
| 3 | Hatch Cover | Scratch | C5 | | Reporting needed | |
| | |  | | | | |
| 4 | Front Bumper | Scratch | C4 | | Reporting needed | |
| | |  | | | | |
| 5 | R. Rear Quarter Panel | Dent | C3 | | | |
| | |  | | | | |
| 6 | R. Rear Door | Scratch | C3 | | | |
| | |  | | | | |
| 7 | L. Roof Pillar, C-Pillar | Scratch | C3 | | | |
| | |  | | | | |
| 8 | R. Front Rim | Paint Flaking | C3 | | Hjulkapsel | |
| | |  | | | | |
| 9 | L. Rear Rim | Paint Flaking | C3 | | Hjulkapsel | |
| | |  | | | | |
| 10 | L. Rear Quarter Panel | Scratch | C3 | | | |
| | |  | | | | |
| 11 | L. Roof Pillar, C-Pillar | Scratch | C3 | | | |
| | |  | | | | |

| N° | LOCATION | TYPE | SEVERITY | INSURANCE | NOTES | DAMAGE GROUP |
|----|---|---|----------|-----------|------------|--------------|
| 12 | L. Front door | Dent | C3 | | | |
| |  |  | | | | |
| 13 | R. Rear Rim | Paint Flaking | C3 | | Hjulkapsel | |
| |  |  | | | | |

Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

| N° | LOCATION | TYPE | NOTES |
|----|---------------------|------|-------|
| 1 | Is the car drivable | Yes | |