

🚗 VEHICLE DESCRIPTION - Seat Arona Style 1.0 TSI**First registration date**

1/2023

VIN:

VSSZZZKJ4PR036494

Colour:

Silver Metalic Normal gloss

Mileage (km):

43.931

Gear:

Manual (6 Gears)

Fuel type:

Gasoline

Body type:

SUV

Number of doors:

5

Drive type:

FWD

Model year:

2021-2025

Engine power:

81 kW

Number of seats:

5

Engine size (cc)

999

Interior:

Dark grey Fabric

🚗 VEHICLE DETAILS**Number of keys:**

1

Number of license plates:

2

Registration certificate:

Part 1 & 2 present

Service documentation:

No

Inspection date:

29-12-2025

Last service (year/month):**Mileage (km) at last service:****🚗 SUMMARY OF THE VEHICLE'S CONDITION****Is the car in a driveable condition:**

Yes

Legal tire tread (minimum 1.6 mm):

Yes

WHEELS


TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	All year tires		Front Left	Alloy rim	16"	4 mm
Fitted	All year tires		Rear Right	Alloy rim	16"	6 mm
Fitted	All year tires		Rear Left	Alloy rim	16"	6 mm
Fitted	All year tires		Front Right	Alloy rim	16"	4 mm

Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES

Driving on the right, "Standard Plus" version, In-plant control of self-collection, Luxury equipment, Part set without country-specific prescriptive standard, Type approval country Denmark, Alloy wheels 6j x 16, Operating permit- alteration, 3-cylinder gasoline engine 1.0 l/81 kW TSI base engine: TJ4/TC5- "TSI"- "eTSI", Without ECO function, Online service- with OCU- without head unit coding- without engine immobilizer interconnection, Driver alert system, Regional code " ECE " for radio, No special edition, Control of series production, Standard paint coating, Without customized installation, Variant, No special purpose vehicle- standard equipment, Vehicles with special upgrade measures, Without applications, 6-speed manual transmission "M6", Shock absorption in front, Entry-level infotainment system Radio 2 (MB3) 8.25-inch, Battery 320 A (49 Ah), Tires 205/60 R16 92V super-low rolling resistance- generation 2, Without camera systems/accident sensors, Refrigerant R1234yf, LED license plate lighting, MPV, Left-hand drive, Suspension range 30 installation control only- no requirement forecast, Private emergency call system, Seat trim covers in fabric, Safe & Driving package M (in combination with "Media System"), Park distance control using ultrasonic sensors, Digital Cockpit, Keyless locking and starting system Keyless Access without SAFELOCK, Reduced price package, LongLife Service Regime, Without voice control, Service indicator 30 000 km or 2 years (variable), Chrome package, With multifunction camera, Without drawers under front seats, Without add. lights (interior lighting), Without dynamic road sign display, Digital radio reception, Standard seats in front, Special price, 3-cylinder SI engine 1.0 l unit 05C.A, Rear shock absorption, Hill start assist, Instrument cluster- km/h speedometer, External- USB type C- only data socket(s), Standard pedal cluster, Extended and proactive pedestrian and cyclist protection, Tires without specification of tire brand, Front stabilizer bar, 4 doors, Wheelbase, Installation differentiation for transmission MQ 200_GA -- vehicle components --, Standard manufacturing sequence, Without alternative drive system, Nameplate set in basic style, Standard rear axle, Rear exhaust tailpipe (standard), Without floor mats, Without special color trim, Without information kit, Weight range 9 installation control only- no requirement forecast, Standard climatic zones, Rear overhang- short, Without special specifications, Electronic stability control (ESC), Fuel system for fuel-injected SI engine (tropicalized), Antifreeze up to -25 degree Celsius tolerance up to -30 degree C, Without trailer hitch, Special identification label for EC for M1 passenger vehicles, Activated carbon canister (Evaporative Emission Control System (EVAP)), Breakdown kit, Disc brakes in rear (Geomet D), Standard air cleaner, Trims for alloy wheels, Power steering, Standard wheel bolts, Without additional front underbody guard, Tool kit, Vehicle class differentiation -6F0-, Without first aid kit and warning triangle, Front-wheel drive, Without differential lock, Disc brakes in front (Geomet D), Initial standard fuel filling, Without delivery equipment, Axial and vertical adjustable steering column, Leather-wrapped multi-function sports steering wheel, Without "drive select", Painted bumpers with protective moldings, Labels in Danish- Finish and Swedish, Standard design, Dust and pollen filter, Without additional tires, Type sign and company logo, Child seat anchors for child seat system ISOFIX, 3-point seat belt for center rear seat, Without roof insert (standard roof), Plane luggage/load compartment floor in rear, Without backrest release for front seats, Door and side trim panel, Manual height adjustment for front seats, Unsplit rear seat bench- split folding backrest, Without mounting fixture in luggage compartment, 3-point seat belts in front- with belt clamping device- without height adjustment, Three rear head restraints, Black roof rails, Luggage compartment cover- folding, Without additional noise suppression measures for passenger compartment, 3-point seat belts- outer rear with ECE label, Seat heater for front seats separately controlled, Emission standard EU6 AP, Protective side molding, Heat-reflecting windshield, Central locking system Keyless Entry without SAFELOCK, Side and rear windows in heat-insulatingglass, Breakaway interior rearview mirror- dimming, Standard dashboard, Rear floor panel module- type 1, Power windows with comfort operation andcircuit breaker, Airbag on driver and front passenger side- without knee airbag- with front passenger airbag deactivation, Without luggage nets/pockets on backrests, Side airbag in front with curtain airbag, Standard decorative trims, Luggage compartment trim (design 1), Without special body measures, Carrier frequency 433.92 MHz-434.42 Mhz, Rear spoiler, Transport protection film (minimum protection) with additional transport protection measures, Decorative inserts, Right exterior mirror- convex, Left exterior mirror- convex, Sun visors with mirror-airbag label on front passenger sun visor, Front head restraints, Without fire extinguisher, Additional body cover on wheel arch and side sill, Without center armrest in front, Exterior mirror housings and various add-on parts in body color, Without decorative films/emblems, Lane keeping system, Forward collision warning incl. autonomous emergency braking- for adaptive cruise control "high", Vent, Unsplit molded headliner, Hand brake lever handle in leather, Gearshift knob/handle in leather, Without interior light in footwell, Exterior mirrors- power-folding/ adjustment- heated, Electronic immobilizer, Without CD changer/CD player, Without heat accumulator/auxiliary heater, Tire pressure monitoring system, Start-stop system with regenerative braking, Without lumbar support in seat backrests, Without CD/DVD for navigation, Without navigation device, Without extended safety system, Park distance control, Without lane change assist, Without second battery, Alternator 140 A, High-beam control, LED headlamps, Rear window wiper and washer system with intermittent control, Windshield wiper intermittent control with light sensor, Headlight range control, 6 speakers (passive), Rear combination lamp- standard design, 2 reading lights in front, Rear fog lamp, Adaptive cruise control (without "follow-to-stop") and speed limiter, Front fog lamp and cornering lamp, Without washer fluid level indicator, Without headlamp washer system, Single-tone horn, Antenna for AM/FM reception, Not hot country, Manually controlled air conditioning system, Separate daytime running light with automatic headlight control, Non-smoker's package, Without auxiliary heater/parking heater, Visual and acoustic seat belt reminder- electric contact in front and rear, Multi-function display/trip computer active info display "Entry", Without heated washer nozzles, Wired & Wireless App-Connect, Mobile phone interface, Equipment options subset for Denmark

PICTURES

Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=38bdb04b-0d4c-48bb-bf94-febf2849d232&carid=19804797>

OVERVIEW OF DAMAGES AND SHORTAGES

Nº	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	R. Rear Quarter Panel	Dent	C4		Reporting needed	



Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

Nº	LOCATION	TYPE	NOTES
1	Is the car drivable		Yes
2	Key		Missing