

**VEHICLE DESCRIPTION - VW T-Cross Life Plus 1.0 TSI**



**First registration date:**  
4/2023

**VIN:**  
WVGZZC1ZPY021240

**Colour:**  
Black Metallic Normal gloss

**Mileage (km):**  
41.293

**Gear:**  
Automatic (7 Gears)

**Fuel type:**  
Gasoline

**Body type:**  
SUV

**Number of doors:**  
5

**Drive type:**  
FWD

**Model year:**  
2018-2024

**Engine power:**  
81 kW

**Number of seats:**  
5

**Engine size (cc):**  
999

**Interior:**

**VEHICLE DETAILS**

**Number of keys:**  
2

**Number of license plates:**  
2

**Registration certificate:**  
Part 1 & 2 present

**Service documentation:**  
No

**Inspection date:**  
14-04-2026

**Last service (year/month):**

**Mileage (km) at last service:**

**SUMMARY OF THE VEHICLE'S CONDITION**

**Is the car in a driveable condition:**  
Yes

**Legal tire tread (minimum 1.6 mm):**  
Yes

**WHEELS**

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Winter tires		Rear Left	Steel rim	16"	5 mm
Fitted	Winter tires		Front Right	Steel rim	16"	5 mm
Fitted	Winter tires		Front Left	Steel rim	16"	5 mm
Fitted	Winter tires		Rear Right	Steel rim	16"	5 mm
Extra Wheel	Summer tires		Rear Left	Alloy rim	16"	5 mm
Extra Wheel	Summer tires		Front Right	Alloy rim	16"	5 mm
Extra Wheel	Summer tires		Front Left	Alloy rim	16"	5 mm
Extra Wheel	Summer tires		Rear Right	Alloy rim	16"	5 mm

**Legal tire tread (minimum 1.6 mm):**

Yes

## ACCESSORIES





Driving on the right, "Standard Plus" version, Category 0, Executive equipment, Part set without country-specific prescriptive standard, Type approval country Denmark, Operating permit- alteration, 3-cylinder SI engine 1.0 I TSI- 81 kW, Without ECO function, Online service- with OCU- with head unit coding- without engine immobilizer interconnection, Driver alert system, Regional code " ECE " for radio, No special edition, No special purpose vehicle- standard equipment, Vehicles without special upgrade measures, Shock absorption in front, 7-speed automatic transmission or dual-clutch transmission DSG- note: PR family EDF, Battery 320 A (49 Ah), Tires 205/60 R16- low rolling resistance, Rear view camera system, Refrigerant R1234yf, Hatchback, Left-hand drive, Suspension range 26 installation control only- no requirement forecast, Standard battery/alternator capacity, Emergency call service, no registration required- service is activated upon delivery, Inserts of front seats and outer rear seats in fabric "Life", Proactive passenger protection system, Adaptive Cruise Control ACC up to 210 km/h and Autonomous Emergency Braking Front Assist, Lights & Vision package, LongLife Service Regime, Without voice control, Service indicator 30 000 km or 2 years (variable), Without aluminum/chrome package, Multifunction camera, Drawer under right front seat, Without add. lights (interior lighting), Without dynamic road sign display, Digital radio reception DAB+, Standard seats in front, Radio "Ready 2 Discover" incl. "Streaming & Internet", Control of campaigns, 3-cylinder SI engine 1.0 I, Hill start assist, Instrument cluster with electronic speedometer- odometer and trip odometer- tachometer, 2 USB-C ports in the front- 2 USB-C charging sockets on the center console in the rear, Standard pedal cluster, Pedestrian and cyclist monitoring, Tires without specification of tire brand, Winter package, Denmark: DK Package TL forces PLA-VW1-PH3 CL/HL forces PLA-KA1-PH3, Preparation for We Connect and We Connect Plus, Front stabilizer bar, 4 doors, Wheelbase, Dual-clutch transmission DSG DQ200, Pamplona manufacturing sequence, Without decals and emblems, Without alternative drive system, Elimination of nameplate for engine designation on luggage compartment lid, Standard rear axle, Rear exhaust tailpipe (standard), Without floor mats, Manual in Danish, Weight range 14 installation control only- no requirement forecast, Standard climatic zones, Rear overhang- short, Electronic Stability Control w/ driver steering recommendation- ABS- ASR- EDL- EDTC and trailer stabilization, Fuel system for fuel-injected SI engine (tropicalized), Without trailer hitch, Special identification label for EC for M1 passenger vehicles, Activated carbon canister (Evaporative Emission Control System (EVAP)), Tire Mobility Set: 12-volt compressor and tire sealant, Rear shock absorption- heavy-duty version, Disc brakes in rear, Trims for alloy wheels, Power steering, Standard wheel bolts, Without additional front underbody guard, Without tool kit and jack, Warning triangle, Front-wheel drive, Disc brakes in front, Initial standard fuel filling, Without delivery equipment, Vehicle class differentiation -2GC-, Height and longitudinally adjustable steering column, Leather-wrapped multi-function steering wheel with shifting paddles, Without Adaptive Chassis Control, Body-colored bumpers- radiator grille with chrome trim and fin, Fresh air intake system with combinationfilter, Without additional tires, ISOFIX anchors for child seats on outer rear bench seats and on front passenger seat- compatible for i-Size, 3-point seat belt for center rear seat, Without roof insert (standard roof), Luggage compartment floor adjustable in 2 heights, Completely folding front passenger seat backrest, Front seats with height adjustment, Unsplit rear bench seat- sliding- asymmetric split folding backrest, 3 head restraints in rear, Black decorative trims, Glove compartment door with light, 4 alloy wheels "Belmont" 6J x 16, Carrier frequency 433.92 MHz- 434.42 Mhz, Transport protection film (minimum protection) with additional transport protection measures, Decorative inserts "Pineapple" for dashboard, Right exterior mirror- convex, Aspherical exterior mirror on driver side, Vanity mirrors in sun visors, Safety-optimized front head restraints, Without adhesive film, Front center armrest- longitudinally adjustable- with storage compartment- 2 USB charging sockets in rear, Body-colored exterior mirror housings and door handles, Lane keeping system Lane Assist, Autonomous Emergency Braking Front Assist (for Adaptive Cruise Control ACC up to 210 km/h), Headliner, Hand brake lever handle in leather, Gearshift knob in leather, Without interior light in footwell, Without additional seals outside, Multi-color Digital Cockpit- selection of different info profiles possible, Exterior mirrors- power-adjustable- folding and heated- w/ front passenger exterior mirror lowering function, Electronic immobilizer, Without heat accumulator/auxiliary heater, Tire Pressure Monitoring System, Start-stop system with regenerative braking, Without protective film for scuff plate, Without lumbar support in seat backrests, Preparation for subsequent activation: Navigation feature "Discover Media" incl. Streaming & Internet, Proactive passenger protection system in combination with Front Assist, Park Distance Control - warning signals for obstacles in the front and rear, Without lane change assist, Radio, Without second battery, Alternator 140 A, Without light control, Halogen headlamps and turn signal lamps under one clear lens, Aut. headlight control with separate daytime running light- entry lighting and manual exit lighting, Rear window wiper with intermittent control, Rain sensor, Headlight range control, 6 speakers, Interior lights with switch-off delay and dimmer- 2 reading lights in front and rear, Rear fog light on one side- back-up light on both sides, Adaptive Cruise Control ACC stop & go incl. speed limiter, LED rear combination lamps (except turn signals and back-up lamps), Without front fog lamps, Warning lamp for washer fluid level, Without headlamp washer system, Single-tone horn, Diversity antenna for FM reception, Not hot country, Air Care Climatronic 2 zone automatic climate control with enhanced air filterwith activated carbon, Luggage compartment lighting, Non-smoker's package: 12-V outlet in front, Warning signal and warning light for front and rear seat belts not fastened, Automatically-heated washer nozzles in front, App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto, Mobile phone interface, Equipment options subset for Denmark

**PICTURES**



**Picture viewer:** <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=819005b1-751c-4c75-aa20-91e3496a846a&carid=20218485>

## OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	Front Windscreen 	Stone Chips 	C5		Reporting needed	
2	R. Rear Door 	Dent 	C4		Reporting done	

Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

## ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	
2	TPMS lamp	Lights	