

**VEHICLE DESCRIPTION - VW Polo Life 1.0 TSI**



|   |                                      |
|---|--------------------------------------|
| <b>First registration date:</b><br>4/2023 | <b>VIN:</b><br>WWWZZAWZPU032531      |
| <b>Colour:</b><br>White Faded             | <b>Mileage (km):</b><br>31.344       |
| <b>Gear:</b><br>Manual (5 Gears)          | <b>Fuel type:</b><br>Gasoline        |
| <b>Body type:</b><br>Hatchback            | <b>Number of doors:</b><br>5         |
| <b>Drive type:</b><br>FWD                 | <b>Model year:</b><br>2021           |
| <b>Engine power:</b><br>70 kW             | <b>Number of seats:</b><br>5         |
| <b>Engine size (cc):</b><br>999           | <b>Interior:</b><br>Dark grey Fabric |

**VEHICLE DETAILS**

|                                       |   |  |                                      |
|---------------------------------------|---|--|--------------------------------------|
| <b>Number of keys:</b><br>2           | <b>Number of license plates:</b><br>2       | <b>Registration certificate:</b><br>Part 1 & 2 present | <b>Service documentation:</b><br>Yes |
| <b>Inspection date:</b><br>29-04-2026 | <b>Last service (year/month):</b><br>2024/4 | <b>Mileage (km) at last service:</b><br>28.545         |                                      |

**SUMMARY OF THE VEHICLE'S CONDITION**

|  |  |
|--|--|
| <b>Is the car in a driveable condition:</b><br>Yes | <b>Legal tire tread (minimum 1.6 mm):</b><br>Yes |
|--|--|

## WHEELS

| TYPE   | SEASON       | BRAND | POSITION    | RIM       | SIZE | TREAD |
|--------|--------------|-------|-------------|-----------|------|-------|
| Fitted | Summer tires |       | Front Left  | Steel rim | 15"  | 5 mm  |
| Fitted | Summer tires |       | Rear Right  | Steel rim | 15"  | 5 mm  |
| Fitted | Summer tires |       | Rear Left   | Steel rim | 15"  | 5 mm  |
| Fitted | Summer tires |       | Front Right | Steel rim | 15"  | 5 mm  |

### Legal tire tread (minimum 1.6 mm):

Yes

## ACCESSORIES













Driving on the right, Standard version, Life, Part set without country-specific prescriptive standard, Type approval country Denmark, Operating permit- alteration, 3-cylinder SI engine 1.0 I TSI- 70 kW, Without ECO function, Online service- with OCU- with head unit coding- without engine immobilizer interconnection, Driver alert system, Regional code " ECE " for radio, No special edition, No special purpose vehicle- standard equipment, Vehicles with special upgrade measures, 5-speed manual transmission, Shock absorption in front, Battery 320 A (49 Ah), Tires 185/65 R15 low rolling resistance, Without camera systems/accident sensors, Refrigerant R1234yf, Hatchback, Left-hand drive, Suspension range 04 installation control only- no requirement forecast, Standard battery/alternator capacity, Emergency call service, no registration required- service is activated upon delivery, Inserts of front seats and outer rear seats in fabric "Life", Assistance package Park & Convenience, IQ.DRIVE assistance systems package, LongLife Service Regime, Without voice control, Service indicator 30 000 km or 2 years (variable), Chrome package, Multifunction camera, Storage compartment for Manual under left front seat, Without add. lights (interior lighting), Without dynamic road sign display, Digital radio reception DAB+, Standard seats in front, Radio "Ready 2 Discover" incl. "Streaming & Internet", 3-cylinder SI engine 1.0 I, Without exterior ambient lighting, Hill start assist, Instrument cluster with electronic speedometer- odometer and trip odometer- tachometer, 2 USB-C ports in the front- 2 USB-C charging sockets on the center console in the rear, Standard pedal cluster, Pedestrian and cyclist monitoring, Tires without specification of tire brand, Lights & Vision package incl. high-beam control Light Assist, Denmark: DK package Basic forces: WLA-WF1-4KF, Style/GTI: WLB-9AK-4KF, Life/R-Line: WLA-9AK-4KF, Preparation for We Connect and We Connect Plus, Front stabilizer bar, 4 doors, Wheelbase, Manual transmission MQ200, South Africa manufacturing sequence, Without decals and emblems, Without alternative drive system, Elimination of nameplate for engine designation on luggage compartment lid, Standard rear axle, Rear exhaust tailpipe (standard), Without floor mats, Manual in Danish, Weight range 8 installation control only- no requirement forecast, Standard climatic zones, Rear overhang- short, Electronic Stability Control w/ driver steering recommendation- ABS- ASR- EDL and EDTC, Fuel system for fuel-injected SI engine, Without trailer hitch, Special identification label for EC for M1 passenger vehicles, Activated carbon canister (Evaporative Emission Control System (EVAP)), Tire Mobility Set: 12-volt compressor and tire sealant, Rear shock absorption, Drum brakes in rear, Wheel trims, Power steering, Standard wheel bolts, Without additional front underbody guard, Tool kit and jack, Vehicle class differentiation - 2G0- for build status Europe, Warning triangle, Front-wheel drive, Without differential lock, Disc brakes in front (Geomet D), Initial standard fuel filling, Delivery equipment- water border, Height and longitudinally adjustable steering column, Leather-wrapped multi-function steering wheel, Without Adaptive Chassis Control, Body-colored bumpers- radiator grille with chrome trim, Fresh air intake system with combinationfilter, Without additional tires, ISOFIX anchors for child seats on outer rear bench seats and on front passenger seat- compatible for i-Size, 3-point seat belt for center rear seat, Without roof insert (standard roof), Luggage compartment floor, Non-folding front passenger seat backrest, Front seats with height adjustment, Unsplit rear bench seat- asymmetric split folding backrest, 3-point seat belts in front with height adjustment and seat belt pretensioners, 3 head restraints in rear, Luggage compartment cover, 3-point seat belts with seat belt pretensioners for the outer rear seats, License plate carrier in front and rear (ECE), Door and side trim panel, Heated front seats, Emission standard EU6 AP, Laminated safety glass windshield- heat-insulating, Central locking system without SAFELock- with radio remote control and 2 remote control folding keys, Privacy glass for rear side windows and rear window, Auto-dimming interior rearview mirror, Foamed dashboard, Rear floor panel module- type 1, Power windows, Driver and front passenger airbag with front passenger airbag deactivation, Map pockets on the back of each front seat, 4 Steel wheels 5.5J x 15, Without special body measures, Carrier frequency 433.92 MHz-434.42 Mhz, Transport protection film (minimum protection) with additional transport protection measures, Decorative inserts "Lava Stone Black" for dashboard and front door trim panels, Right exterior mirror- convex, Aspherical exterior mirror on driver side, Illuminated vanity mirrors in sun visors, Safety-optimized front head restraints, Without adhesive film, Curtain airbags in front and rear- side airbags in front- center airbag, Front center armrest- longitudinally adjustable- with storage compartment, Body-colored exterior mirror housings and door handles, Semi-automated driving assistance Travel Assist and lane keeping system Lane Assist, Autonomous Emergency Braking Front Assist (for Adaptive Cruise Control ACC up to 210 km/h), Ceramique headliner, Hand brake lever handle in leather, Gearshift knob in leather, Without interior light in footwell, Exterior mirrors- power-adjustable- folding and heated- w/ front passenger exterior mirror lowering function, Electronic immobilizer, Without heat accumulator/auxiliary heater, Multi-color Digital Cockpit- selection of different info profiles possible, Tire Pressure Monitoring System, Start-stop system with regenerative braking, Without protective film for scuff plate, Without lumbar support in seat backrests, Preparation for subsequent activation: Navigation feature "Discover Media" incl. Streaming & Internet, Proactive passenger protection system in combination with Front Assist, Park Assist with Park Distance Control, Lane change system Side Assist and Rear Traffic Alert, Radio, Without second battery, Alternator 140 A, High-beam control Light Assist, LED headlamps with LED separate daytime running light, Rear window wiper with intermittent control, Rain sensor, Headlight range control, 6 speakers, Interior lights with switch-off delay and dimmer- 2 reading lights in front and 2 in rear, Rear fog lamp for driving on the right, Adaptive Cruise Control ACC incl. speed limiter, LED rear combination lamps, Without front fog lamps, Warning lamp for washer fluid level, Without headlamp washer system, Single-tone horn, Diversity antenna for FM reception, Not hot country, Air Care Climatronic 2 zone automatic climate control with enhanced air filterwith activated carbon, Luggage compartment lighting, Automatic headlight control with exit and entry lighting, Non-smoker's package: Storage compartment and 12-V outlet in front, Without auxiliary heater/parking heater, Warning signal and warning light for front and rear seat belts not fastened, Without heated washer nozzles, App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto, Mobile phone interface, Equipment options subset for Denmark

**PICTURES**



**Picture viewer:** <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=6df8f0a9-63d8-4815-a442-69df3cd4eea7&carid=20259382>

## OVERVIEW OF DAMAGES AND SHORTAGES

| N° | LOCATION  | TYPE  | SEVERITY | INSURANCE | NOTES   | DAMAGE GROUP  |
|----|---|---|----------|-----------|---|---|
| 1  | Front Windscreen  | Stone Chips   | C5       |           | Reporting needed  |   |
|    |    |  |          |           |   |   |
| 2  | Front Bumper  | Scratch   | C4       |           | Reporting needed  |   |
|    |    |  |          |           |   |   |
| 3  | Other   | Cleaning  | C4       |           | Reporting needed røglugt og beskidt   |   |
|    |    |  |          |           |  |  |
| 4  | Roof  | Discoloration   | C3       |           |   |   |
|    |    |   |          |           |   |   |
| 5  | Rear Bumper   | Scratch   | C3       |           |   |   |
|    |  |   |          |           |   |   |
| 6  | R. Rear Light   | Scratch   | C3       |           |   |   |
|    |  |   |          |           |   |   |
| 7  | R. Rear Quarter Panel   | Discoloration   | C3       |           |   |   |
|    |  |   |          |           |   |   |

Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

## ELECTRICAL AND MECHANICAL CONDITION

| N° | LOCATION            | TYPE | NOTES |
|----|---------------------|------|-------|
| 1  | Is the car drivable | Yes  |       |