

**VEHICLE DESCRIPTION - Škoda Fabia Ambition 1.0 TSI**



**First registration date:**  
5/2023

**VIN:**  
TMBEP9PJ1P4050879

**Colour:**  
Black Metallic Normal gloss

**Mileage (km):**  
26.723

**Gear:**  
Manual (5 Gears)

**Fuel type:**  
Gasoline

**Body type:**  
Hatchback

**Number of doors:**  
5

**Drive type:**  
FWD

**Model year:**  
2021

**Engine power:**  
70 kW

**Number of seats:**  
5

**Engine size (cc):**  
999

**Interior:**

**VEHICLE DETAILS**

**Number of keys:**  
2

**Number of license plates:**  
2

**Registration certificate:**  
Part 1 & 2 present

**Service documentation:**  
No

**Inspection date:**  
08-06-2026

**Last service (year/month):**


**Mileage (km) at last service:**

**SUMMARY OF THE VEHICLE'S CONDITION**

**Is the car in a driveable condition:**  
Yes

**Legal tire tread (minimum 1.6 mm):**  
Yes

## WHEELS

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Winter tires		Front Left	Alloy rim	15"	4 mm
Fitted	Winter tires		Rear Right	Alloy rim	15"	4 mm
Fitted	Winter tires		Rear Left	Alloy rim	15"	4 mm
Fitted	Winter tires		Front Right	Alloy rim	15"	4 mm

### Legal tire tread (minimum 1.6 mm):

Yes

## ACCESSORIES
















Remote Access 1 year, No special edition, Wheel bolts with anti-theft protection (unlockable), Without adapter, Vehicle class differentiation -6VN-, Rear exhaust tailpipe (standard), Without hill start assist/hill descent control/comfort driving assist, Emission standard EU6 AP, Preparation for tow bar, Airbag on driver and front passenger side- knee airbag on driver side- with front passenger airbag deactivation, Activated carbon canister (Evaporative Emission Control System (EVAP)), Without storage compartment, Without storage compartment package/box, Spectacle storage compartment/bracket, Antenna for FM reception only, Exterior mirrors- electr. adjustable- heated - painted in exterior colour (for MC colored black), Exterior mirrors: convex on driver side- convex on front passenger side, Without alternative drive system, Front-wheel drive, "SMART LINK", Comfort equipment, Forward collision warning incl. autonomous emergency braking- without adaptive cruise control, Disk brakes rear, Battery 380 A (59 Ah) EFB+, Disc brakes in front (Geomet D), Outside door mirrors and door handles in body color, Part set without country-specific prescriptive standard, without USB in interior rear view mirror, Without tool kit and jack, Electronic stability control (ESC), Manual in Danish, Heated washer nozzles in front, Without "drive select", Chrome package, Operating permit- alteration, Preparation for roof load rack, Without roof insert (standard roof), Rear shock absorption, Without decorative films/emblems, Shock absorption in front, Without ECO function, Installation differentiation for transmission MQ 200 -- vehicle components --, Electronic immobilizer, Decorative inserts, Without protective film for scuff plate, Lower decorative inserts, PARK DISTANCE CONTROL (Parking sensors front + rear), Without extended safety system, 2x USB front (typ C data), Standard manufacturing sequence, Front and rear windows electric (auto up/down function for all windows), Without fire extinguisher, Without additional malfunction display, Extended and proactive pedestrian and cyclist protection, Standard pedal cluster, Vent, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Fresh air intake system with combination filter, Antifreeze up to -25 degree Celsius tolerance up to -30 degree C, No special purpose vehicle- standard equipment, Acoustics package "Standard", Alternator 140 A, Weight range 8 installation control only- no requirement forecast, Suspension range 04 installation control only- no requirement forecast, 3-cylinder SI engine 1.0 l unit 05C.A, Luggage compartment cover- folding, Without tie down straps/net/pocket, Cruise control with Speedlimiter, Luggage compartment lighting, 5-speed manual transmission, Standard glove compartment, Without bracket, Hand brake lever handle in leather, Rear spoiler, Rear window wiper and washer system with intermittent control, Folding grab handles at roof frame, Standard rear axle, Rear axle weight- type 1, Rear seat backrest split 60:40- unsplit rear seat bench, Climatronic with impact pressure control- CFC-free, LED headlamps, Instrument cluster- km/h speedometer, Breakaway interior rearview mirror- auto-dimming, Hatchback, With multifunction camera, Without luggage compartment floor covering, Fuel tank, Without storage compartments in trunk, Standard climatic zones, Without dynamic road sign display, 3rd head restraint rest, Front head restraints, Initial standard fuel filling, Fuel system for fuel-injected SI engine (tropicalized), Rear view camera - with washer nozzle, Radiator grille with chrome molding, Refrigerant R1234yf, Transport protection film with additional transport protection measures, Standard paint coating, Without luggage/load compartment floor, Without add. lights (interior lighting), Left-hand drive, Two reading lights in front- two in rear, Power steering, Without backrest release for front seats, Curb weight range 1, Without light control, Without lumbar support in seat backrests, Multi-function steering wheel, Driving on the right, 4 speakers front + 2 rear incl. Ākoda Surround, Axial and vertical adjustable steering column, Headlight range control, Center armrest in front, Variant, "MAXI DOT" (KI Mid), Central console - cuholder "Snowman", DRIVER ALERT SYSTEM, Not hot country, 3-cylinder SI engine 1.0 l/70 kW TSI base engine is TJ4/TC5/T26/T0M/T6A, Standard version, Without navigation device, Rear fog lamp for driving on the right, Without front fog lamps, Remote Access / Pro-active service, Rear floor panel module- type 1, Trims for alloy wheels, Alloy wheels "ROTARE" silver 5-5J x 15" - 4 pcs, Radio Bolero 8", Non-smoker's package, Regional code " ECE " for radio, Tire pressure monitoring system, With umbrella, Tires 185/65 R15 88H super-low rolling resistance- generation 2, Tires without specification of tire brand, Breakdown kit, Wheelbase, 3-point seat belts in front- with pretensioner/lap belt pretensioner and height adjustment, E-Call+, Side airbag in front and rear with curtain airbag, Gearshift knob/handle in leather, Rear combination lamp, Service indicator 30 000 km or 2 years ( variable ), Standard bumpers, Seatbelt warning - front + rear seats, 3-point seat belts- outer rear with ECE label, Seat trim covers in fabric, Height - adjustable driver and co-driver seat, Seat heater for front seats separately controlled, Key for locking system with remote control, Start-stop system with regenerative braking, Single-tone horn, Optimization of family MDS, Sun visors with mirror- airbag label on front passenger sun visor, Without voice control, Without lane change assist, Lane Assist, Side and rear windows in heat-insulating glass, Without socket, Body-colored bumpers, Front stabilizer bar, Without drawers under front seats, Without headlamp washer system, Windshield wiper intermittent control with light sensor, Nameplate set in basic style, Fuel filler cap, Central locking w/ radio remote control- interior controls- without SAFELock, Type approval country Denmark, Carrier frequency 433.92 MHz-434.42 Mhz, Without partition, Door and side trim panel, 4 doors, DAB - Digital radio reception, Additional front underbody guard, Special identification label for EC for M1 passenger vehicles, Without delivery equipment, Rear overhang- short, Standard seats in front, Bluetooth, LongLife Service Regime, Without heat accumulator/auxiliary heater, Heat-reflecting windshield, Washer fluid level indicator, Without second battery, Without floor mats, Standard decorative trims, Without additional side body covers (stone guard), Child seat anchors f. child seat system i- Size- 2x top tether and child seat anchors in front on front passenger side, Without additional seals outside, Without auxiliary heater/parking heater, N/A

**PICTURES**



**Picture viewer:** <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=d3d3c3f6-7d09-4c60-8497-d1eddf504ada&carid=20372113>

**OVERVIEW OF DAMAGES AND SHORTAGES**

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP		
1	Curtain Luggage Compartment	Missing	C5		Reporting needed			
2	Curtain Luggage Compartment	Missing	C5		Reporting needed			
3	Instrument panel	Scratch	C4		Reporting needed			
								
4	Rear Bumper	Scratch	C4		Reporting needed			
								
5	Cabin	Cleaning	C4		Reporting needed			
								

Severity explanation:  
C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

**ELECTRICAL AND MECHANICAL CONDITION**

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	