

VEHICLE DESCRIPTION - Škoda Kamiq Life 1.0 TSI



First registration date:
5/2023

VIN:
TMBGR7NW4P3133685

Colour:
Gray Metallic Normal gloss

Mileage (km):
28.717

Gear:
Manual (6 Gears)

Fuel type:
Gasoline

Body type:
SUV

Number of doors:
5

Drive type:
FWD

Model year:
2019-2024

Engine power:
81 kW

Number of seats:
5

Engine size (cc):
999

Interior:

VEHICLE DETAILS

Number of keys:
2

Number of license plates:
2

Registration certificate:
Part 1 & 2 present

Service documentation:
Yes

Inspection date:
03-06-2026

Last service (year/month):
2025/6


Mileage (km) at last service:
21.643

SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition:
Yes

Legal tire tread (minimum 1.6 mm):
Yes

WHEELS

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Alloy rim	16"	7 mm
Fitted	Summer tires		Rear Right	Alloy rim	16"	7 mm
Fitted	Summer tires		Rear Left	Alloy rim	16"	7 mm
Fitted	Summer tires		Front Right	Alloy rim	16"	7 mm


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES







Rear overhang- short, 4 doors, Front stabilizer bar, Wheelbase, Installation differentiation for transmission MQ 200_GA -- vehicle components --, Standard manufacturing sequence, Without alternative drive system, Standard rear axle, Nameplate set in basic style, Without electronic steering column lock, Without floor mats, Manual in Danish, Standard climatic zones, Weight range 12 installation control only- no requirement forecast, Fuel system for fuel-injected SI engine (tropicalized), Electronic stability control (ESC), Antifreeze up to -25 degree Celsius tolerance up to -30 degree C, Trailer hitch preparation, Activated carbon canister (Evaporative Emission Control System (EVAP)), Special identification label for EC for M1 passenger vehicles, Breakdown kit, Disc brakes in rear (Geomet D), Power steering, Trims for alloy wheels, Standard wheel bolts, Tool kit, Additional front underbody guard, Without folding table on front seat backrest, Without refrigerator/glove compartment cooling system, Front-wheel drive, Initial standard fuel filling, Disc brakes in front (Geomet D), Without delivery equipment, Additional exterior noise suppression, Axial and vertical adjustable steering column, Without "drive select", Body-colored bumpers, Fresh air intake system with combination filter, Multi-function steering wheel, Child seat anchors f. child seat system i-Size- 2x top tether and child seat anchors in front on front passenger side, 3-point seat belt for center rear seat, Without partition, Center console, Without roof insert (standard roof), Without luggage/load compartment floor, Without backrest release for front seats, Hight-adjustable head restraints for front seats, Manual height adjustment for front seats, Door panels with upholstery, Mounting fixture in luggage compartment, Unsplit rear seat bench- split folding backrest, Three rear head restraints, 3-point seat belts in front- with tensioner and height adjustment, Standard tailgate, Black roof rails, Luggage compartment cover, Without additional noise suppression measures for passenger compartment, 3-point seat belts- outer rear with ECE label, Seat heater for front seats separately controlled, Without protective side molding, Emission standard EU6 AP, Tailgate without electrical opening, Heat-reflecting windshield, Central locking w/ radio remote control- interior controls- without SAFELock, Sunset, Breakaway interior rearview mirror- auto-dimming, Rear floor panel module- type 1, Power windows with comfort operation and circuit breaker, Driver knee airbag, Side airbag in front with curtain airbag, Without waste bin, Glove compartment door with light, Standard decorative trims, Carrier frequency 433.92 MHz-434.42 Mhz, Transport protection film with additional transport protection measures, Decorative inserts Grained Black, Right exterior mirror- convex, Left exterior mirror- convex, Sun visors with mirror and airbag label on front passenger side, Without fire extinguisher, Center armrest in front "Jumbo Box", Without additional side body covers (stone guard), Without decorative films/emblems, Outside door mirrors and door handles in body color, Spurhalte assist, "FRONT ASSIST" - radar scan.of the space in front of the car- incl.City ANB- without "ADAPTIVE CRUISE ASSISTANT", Radiator grille with chrome molding, Interiorbars and air vents frame Black glossy, Luggage net, Grey ceiling, Gearshift knob/handle in leather, Without two-sided floor surface, Exterior mirrors- power-adjustable/heated, Electronic immobilizer, Without socket, Without heat accumulator/auxiliary heater, Tire pressure monitoring system, Start-stop system with regenerative braking, Vehicle class differentiation -655-, Without protective film for scuff plate, Spectacle storage compartment/bracket, Manually adjustable lumbar support in front seats, Without navigation device, Without extended safety system, Rear parking sensors, Without lane change assist, Without second battery, Without light control, Alternator 140 A, LED headlamps with lens, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Rear window wiper and washer system with intermittent control, Windshield wiper intermittent control with light/rain sensor, Dynamic headlight range control (self-adjusting while driving), Key for locking system with remote control, 8 speakers (passive), Electronic cruise control + Speedlimiter, LED rear combination lamp- dynamic turn signal- special styling, Without washer fluid level indicator, Integrated front fog lamps, Without headlamp washer system, Single-tone horn, Not hot country, Antenna for FM reception only- diversity, Manually controlled air conditioning system, Without additional malfunction display, Non-smoker's package, Without auxiliary heater/parking heater, Visual and acoustic seat belt reminder- electric contact, Boardcomputer Maxidot, Heated washer nozzles in front, MirrorLink, Bluetooth, Ambition, Driving on the right, Standard version, Type approval country Denmark, Part set without country-specific prescriptive standard, Operating permit- alteration, Alloy wheels 6J x 16, 3-cylinder SI engine 1.0 l/81 kW TSI base engine is TJ4/TC5, No special edition, Without ECO function, Remote Access / Pro-active service, Driver alert system, Regional code " ECE " for radio, No special purpose vehicle-standard equipment, Standard paint coating, Basic equipment variant, Shock absorption in front, 6-speed manual transmission, Tires 205/60 R16 92V, Radio Bolero 8", Without bracket, Curb weight range 1, Rear axle weight- type 1, Battery 380 A (59 Ah) EFB+, Crossover, Without camera systems/accident sensors, Refrigerant R1234yf, With trim panel, Left-hand drive, Suspension range 24 installation control only- no requirement forecast, Seat Ambition, Without adapter, With umbrella, Emergency call system eCall+, Standard Seats, LongLife Service Regime, Without voice control, Service indicator 30 000 km or 2 years (variable), Black Piano, With multifunction camera, Without drawers under front seats, Without add. lights (interior lighting), Without dynamic road sign display, DAB - Digital radio reception, 3-cylinder SI engine 1.0 l unit 05C.A, Instrument cluster- km/h speedometer, 2 USB Typ-C vorne, Rear shock absorption, Without hill hold control, Tires without specification of tire brand, Standard pedal cluster, Extended and proactive pedestrian and cyclist protection, Pack 1 Kamiq, Care connect 1 year, Equipment options subset for Denmark

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=599dc995-dd2e-4c22-a7f4-e933afd73b27&carid=20469375>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	Rear Bumper 	Scratch 	C4		Reporting needed	
2	R. Rear Quarter Panel 	Scratch 	C4		Reporting needed	
3	R. Front Quarter Panel 	Dent 	C3			

Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	