

VEHICLE DESCRIPTION - Škoda Karoq Style 1.5 TSI



First registration date:
5/2023

VIN:
TMBJR7NU5P5055653

Colour:
Black Metallic Normal gloss

Mileage (km):
67.565

Gear:
Automatic (7 Gears)

Fuel type:
Gasoline

Body type:
SUV

Number of doors:
5

Drive type:
FWD

Model year:
2022

Engine power:
110 kW

Number of seats:
5

Engine size (cc):
1498

Interior:
Dark grey Fabric

VEHICLE DETAILS

Number of keys:
2

Number of license plates:
2

Registration certificate:
Part 1 present

Service documentation:
Yes

Inspection date:
09-06-2026

Last service (year/month):
2026/5

Mileage (km) at last service:
66.956

SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition:
Yes

Legal tire tread (minimum 1.6 mm):
Yes

WHEELS

TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Alloy rim	18"	5 mm
Fitted	Summer tires		Rear Right	Alloy rim	18"	4 mm
Fitted	Summer tires		Rear Left	Alloy rim	18"	4 mm
Fitted	Summer tires		Front Right	Alloy rim	18"	5 mm

Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES













Remote Access 1 year, No special edition, Standard wheel bolts, Without adapter, Vehicle class differentiation -SEP-, Rear exhaust tailpipe (standard), Hill start assist, Emission standard EU6 AP, Trailer hitch preparation, Driver knee airbag, Activated carbon canister (Evaporative Emission Control System (EVAP)), Storage compartment package 3, Glasses storage compartment, Antenna for FM reception only- diversity, Exterior mirrors- auto-dimming- power-folding/adjustable/heated, Left exterior mirror- convex, Standard electronic engine sound, Right exterior mirror- convex, Without alternative drive system, Front-wheel drive, "SMART LINK" (wireless for Apple), Luxury equipment, Forward collision warning incl. autonomous emergency braking- for adaptive cruise control "high", Disc brakes in rear, Battery 420 A (70 Ah), Disc brakes in front, Exterior mirror housings and various add-on parts in body color, Standard battery/alternator capacity, Part set without country-specific prescriptive standard, Tool kit, Electronic stability control (ESC), Manual in Danish, Operating voltage 12 V, Brake pad wear indicator, Heated windscreen washer nozzles, Driving profile selection and conventional shock absorber, Chrome package (type 2), Operating permit- alteration, Bright roof rails, Without roof insert (standard roof), Rear shock absorption- chassis with increased ride height, Without decorative films/emblems, Shock absorption in front, Without load-through hatch, ECO function, Installation differentiation for transmission DQ200 -- vehicle components --, Electronic immobilizer, Decorative inserts, Door sills (front), Without emblem package, Park distance control system (parking sensors rear), Without extended safety system, External- USB type C- only data socket(s), Standard manufacturing sequence, Power windows with comfort operation and circuit breaker, Without additional malfunction display, Extended and proactive pedestrian protection, Standard pedal cluster, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Parking brake, No special purpose vehicle- standard equipment, Without additional noise suppression measures for passenger compartment, Alternator 140 A, Weight range 6 installation control only- no requirement forecast, Suspension range 10 installation control only- no requirement forecast, 4-cylinder SI engine 1.5 l unit 05E.D, Without tie down straps/net/pocket, Adaptive cruise control (with "follow-to-stop") and speed limiter, Additional exterior noise suppression, 7-speed automatic transmission, Without bracket, Rear spoiler, Rear window wiper and washer system with intermittent control, Folding grab handles- multi-piece, Standard rear axle, Rear axle weight- type 1, Unsplit rear seat bench- split folding backrest- with center armrest, Climatronic with impact pressure control- CFC-free, LED headlamps, Without electric motor (hybrid), Without interior light in footwell, Instrument cluster- km/h speedometer, Inside rear view mirror automatically dimming, MPV, With multifunction camera, Luggage compartment floor covering in flat needle-punched nonwoven, Manual child safety lock, Without storage compartments in trunk, Without folding table on front seat backrest, Standard climatic zones, Without dynamic road sign display, 3rd rear headrest, Front head restraints, Initial standard fuel filling, Fuel system for fuel-injected SI engine, Without special body measures, Without child seat anchora in front (ISOFIX), Without camera systems/accident sensors, Radiator grille, Refrigerant R1234yf, Transport protection film with additional transport protection measures, Standard paint coating, Without luggage/load compartment floor, Without add. lights (interior lighting), Without vehicle inlet, Left-hand drive, Two reading lights in front- two in rear, Speed-related variable steering assist (Servotronic), Without backrest release for front seats, Curb weight range 1, Without light control, Driver and passenger seat with lumbar support, 2 spoke multi-function leather steering wheel with heating and with DSG paddles, Driving on the right, Additional 4 loudspeakers rear, Air cleaner for dusty regions, Headlight range control, Front armrest "JUMBO BOX", Basic equipment variant, "Virtual Cockpit", "DRIVER ALERT" - driver alert system, Not hot country, 4-cylinder SI engine 1.5 l/110 kW TSI base engine is TJ7/N09/T9F/T57/T0D, Radio Bolero, Rear fog lamp, Front fog lights, Remote Access / Remote Access + Online Infotainment, Rear floor panel module- type 7, Aero hubcaps black, Alloy wheels "PROCYON" 7J x 18" - 4 pcs, Infotainment Bolero/Amundsen/Columbus (MIB3), Non-smoker's package, Regional code " ECE " for radio, Tyre pressure monitoring, Tires 215/50 R18 92W, Tires without specification of tire brand, Breakdown kit, Wheelbase, 3-point seat belts in front- with tensioner and height adjustment, Emergency call system eCall+, Curtain airbags and side airbags front, Gearshift knob/handle in leather, LED rear combination lamp- variable lighting functions- special styling, Virtual pedal, Service indicator 30 000 km or 2 years (variable), Passenger seat-belt warning light (for all passengers), 3-point seat belts- outer rear with ECE label, Seat trim covers in fabric, Manual height adjustment for front seats, Heated front seats, Key for locking system with remote control, Start-stop system with regenerative braking, Two-tone horn, Sun visors with illuminated vanity mirror on driver and front passenger side, Voice control, Without lane change assist, Lane Assist (without HOD), "SUNSET", Without supertone system and tone sequence control, 12-volt socket in luggage boot, Standard bumpers, Without rear stabilizer bar, Front stabilizer bar, Headlamp washer system, Windshield wiper intermittent control with light/rain sensor, Without mud flap, Nameplate set in basic style, Fuel filler cap, "KESSY FULL" without SAFE system, Type approval country Denmark, Carrier frequency 433.92 MHz-434.42 Mhz, Without partition, Door and side trim panel, 4 doors, DAB - Digital radio reception, Without additional front underbody guard, Special identification label for EC for M1 passenger vehicles, Without delivery equipment, Comfort seats in front, Mechanical rear seat release, Comfort telephony with LTE and wireless charging, Additional retro-reflectors (door area), LongLife Service Regime, Without heat accumulator/auxiliary heater, Heat-reflecting windshield, Washer fluid level indicator, Textile floor mats, Bright decorative trims, Wheel arches, Child seat anchors for child seat system ISOFIX, Without auxiliary heater/parking heater, Equipment options subset for Denmark

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=058879eb-9ff2-4d8a-a7d9-0b633ea23896&carid=20485243>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	L. Rear Door	Scratch	C4		Reporting needed	
						
2	Rear Hood	Dent	C4		Reporting needed	
						
3	Rear Bumper	Scratch	C4		Reporting needed	
						
4	R. Rear Door	Scratch	C4		Reporting needed	
						
5	R. Rocker Panel, Inside	Scratch	C4		Reporting needed	
						
6	R. Front Door	Dent	C3			
						

Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	