

VEHICLE DESCRIPTION - Škoda Superb Style 1.5 TSI ACT



First registration date:
6/2023

VIN:
TMBJN7NP6P7059012

Colour:
Gray Metallic Normal gloss

Mileage (km):
29.902

Gear:
Automatic (7 Gears)

Fuel type:
Gasoline

Body type:
Estate Wagon

Number of doors:
5

Drive type:
FWD

Model year:
2019-2024

Engine power:
110 kW

Number of seats:
5

Engine size (cc):
1498

Interior:

VEHICLE DETAILS

Number of keys:
2

Number of license plates:
2

Registration certificate:
Part 2 present

Service documentation:
No

Inspection date:
30-06-2026

Last service (year/month):

Mileage (km) at last service:

SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition:
Yes

Legal tire tread (minimum 1.6 mm):
Yes

WHEELS

| TYPE | SEASON | BRAND | POSITION | RIM | SIZE | TREAD |
|--------|--------------|-------|-------------|-----------|------|-------|
| Fitted | Summer tires | | Front Left | Alloy rim | 17" | 5 mm |
| Fitted | Summer tires | | Rear Right | Alloy rim | 17" | 5 mm |
| Fitted | Summer tires | | Rear Left | Alloy rim | 17" | 5 mm |
| Fitted | Summer tires | | Front Right | Alloy rim | 17" | 5 mm |


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES
















Wheelbase, Installation differentiation for transmission DQ200 -- vehicle components --, Standard manufacturing sequence, Without alternative drive system, Fuel tank, Nameplate set in basic style, Rear exhaust tailpipe (standard), With electronic steering column lock, Textile floor mats, Manual in Danish, Standard climatic zones, Weight range 3 installation control only- no requirement forecast, Fuel system for fuel-injected SI engine, Brake control system for vehicles without electric drive (ESC and electromechanical brake booster), Preparation for tow bar, Activated carbon canister (Evaporative Emission Control System (EVAP)), Special identification label for EC for M1 passenger vehicles, Breakdown kit, Rear shock absorption- basic version 1, Speed-related variable steering assist (Servotronic), Trims for alloy wheels, Standard wheel bolts, Without mass damper for steering wheel, Tool kit, Without additional front underbody guard, Front-wheel drive, Initial standard fuel filling, Disc brakes in front, Without electric motor (hybrid), Without delivery equipment, Disc brakes in rear, Without locking and starting systems, Without "drive select", Body-colored bumpers, Without additional tires, 2 spoke multifunction leather steering wheel- black stitching, Child seat anchors for child seat system ISOFIX, 3-point seat belt for center rear seat, Without partition, Center console, Without roof insert (standard roof), Without child seat anchor in front (ISOFIX), Without luggage/load compartment floor, Without backrest release for front seats, Power seats in front- driver seat with memory feature, Door and side trim panel in foam film and woven fabric, Storage box with cover in luggage compartment side panel (covers on both sides) plus cargoelement, Unsplit rear seat bench-split folding backrest- with center armrest, 3-point seat belts in front- with tensioner and height adjustment, Roof rails- anodised, Three rear head restraints, Luggage compartment cover- folding, Additional interior noise suppression, Without load-through hatch, Without roll-up sunshade, 3-point seat belts- outer rear with ECE label, Heated front seats, Emission standard EU6 AP, Without seat ventilation/massage seat, Tailgate/trunk lid release, Heat-reflecting windshield, Power-operated child safety lock, "KESSY FULL" without "SAFE" system, Side and rear windows in heat-insulating glass, Breakaway interior rearview mirror- auto-dimming, Driver knee airbag, Front passenger seat control, Side airbag in front with curtain airbag, Chrom trimming around side windows, Without special body measures, Carrier frequency 433.92 MHz-434.42 Mhz, Roof spoiler, Transport protection film with additional transport protection measures, Right exterior mirror- convex, Left exterior mirror- convex, Decor moulding Argenzo Zebrano with chrom and ambient lighting, Sun visor with make-up mirror and LED illumination and airbagschield, Front head restraints, Without fire extinguisher, Center armrest in front, Exterior mirror housings and various add-on parts in body color, Without lane keeping system, "FRONT ASSIST" - radar scanning of the space in front of the car- incl. City ANB- wo. "ADAPTIVE CRUISE ASSISTANT", Radiator grille with chrome molding, Without tie down straps/net/pocket, Without mud flap, Unsplit molded headliner, Gearshift knob/handle in leather, Interior light in footwell in front and rear, Ext. mirrors with memory feature- auto- dimming on driver's side- el.folding/adjustable- separately heated, Electronic immobilizer, 12-volt socket(s), Without heat accumulator/auxiliary heater, Tire pressure monitoring system, Start-stop system with regenerative braking, Decorative door sills front and rear, Power-adjustable lumbar support in front seats, Without CD/DVD for navigation, Standard engine starter, Radio Bolero, Without extended safety system, PDC with "MANOEUVRE ASSIST" - parking sensors front & rear with aut. braking, Without lane change assist, Vehicle class differentiation -3V0-, Optional infotainment system (MIB3), Without second battery, High-beam control, Alternator 140 A, Low LED Basic headlamps + LED Daylight, "LIGHT ASSISTANT" ("COMMING HOME"- "LEAVING HOME"- "TUNNEL LIGHT"- "DAY LIGHT"), Rear window wiper "AERO", Windshield wiper intermittent control with light/rain sensor, Headlight range control, Key for locking system with remote control, 8 speakers (passive), LED taillights, "CRUISE CONTROL" - with Speedlimiter, Rear fog lamp, Front fog lamp and cornering lamp, Telescopic headlamps washers, Two-tone horn, Not hot country, Antenna for FM reception only- diversity, Without preparation for two-way radio installation, Without additional malfunction display, Comfort telephony with LTE and wireless charging, Non-smoker's package, Without auxiliary heater/parking heater, Passenger seat-belt warning light (for all passenger), "Virtual Cockpit", Heated windscreen washer nozzles, Additional warning lights (door area), "SMART LINK" (wireless for Apple), Operating voltage 12 V, Equipment level - Style, Driving on the right, Type approval country Denmark, Part set without country-specific prescriptive standard, Operating permit-alteration, Alloy wheels "STRATOS" 7jx17", 4-cylinder SI engine 1.5 l/110 kW TSI base engine is TJ7/N09/T9F/T57/T0D, No special edition, Without ECO function, Remote Access / Remote Access + Online Infotainment, "DRIVER ALERT" - driver alert system, Regional code " ECE " for radio, Without vehicle inlet, Without charging cable, No special purpose vehicle- standard equipment, Standard paint coating, Basic equipment variant, Shock absorption in front, 7-speed automatic transmission, Standard electronic engine sound, Vehicles with special upgrade measures, Without bracket, Curb weight range 1, Battery 420 A (70 Ah), Tires 215/55 R17 94V super-low rolling resistance- generation 2 (polymer coating), Wagon/Avant, Without camera systems/accident sensors, Climatronic (3-zone) with air conditioning control panel in rear, Refrigerant R1234yf, Without head-up display, Suspension range 05 installation control only- no requirement forecast, Left-hand drive, Seat trim covers in fabric, Without adapter, Standard battery/alternator capacity, Emergency call system eCall+, Comfort seats in front, Without child seat, LongLife Service Regime, Voice control, Service indicator 30 000 km or 2 years (variable), Chrome package (type 2), With multifunction camera, Interior ambient lighting- type 2, Without compass/road sign display/dynamic road sign display, DAB - Digital radio reception, 4-cylinder SI engine 1.5 l unit 05E.A, Instrument cluster- km/h speedometer, 2x USB front, Hill hold control, Parking brake, Standard rear seat release, Without clock, Tires without specification of tire brand, Without garage door opener, Standard pedal cluster, Extended and proactive pedestrian protection, Remote Access 1 year, Equipment options subset for Denmark

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=5d7c0f03-9510-4dcf-bba0-f9fc9514352d&carid=20652710>

OVERVIEW OF DAMAGES AND SHORTAGES

| N° | LOCATION | TYPE | SEVERITY | INSURANCE | NOTES | DAMAGE GROUP |
|----|---|---|---|------------------|-------------------|--------------|
| 1 | | Mangler | | | Indlevering nøgle | |
| 2 | R. Rear Quarter Panel | Dent | C4 | Reporting needed | | Group 1 |
| |  |  | | | | |
| 3 | Rear Bumper | Scratch | C4 | Reporting needed | | |
| |  |  | | | | |
| 4 | R. Rear Door, List | Scratch | C4 | Reporting needed | | Group 1 |
| |  |  | | | | |
| 5 | Cabin | Cleaning | C4 | Reporting needed | | |
| |  |  |  | | | |
| 6 | R. Front Rim | Scratch | C4 | Reporting needed | | |
| |  |  | | | | |
| 7 | R. Rear Door | Scratch | C3 | | | |
| |  |  | | | | |
| 8 | R. Rear Rim | Scratch | C3 | | | |
| |  |  | | | | |

Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

| N° | LOCATION | TYPE | NOTES |
|----|---------------------|------|-------|
| 1 | Is the car drivable | Yes | |