

 VEHICLE DESCRIPTION - Škoda Fabia Ambition 1.0 TSI



First registration date 6/2023	VIN: TMBER9PJ2P4073128
Colour: Blue Metallic Normal gloss	Mileage (km): 23.093
Gear: Automatic (7 Gears)	Fuel type: Gasoline
Body type: Hatchback	Number of doors: 5
Drive type: FWD	Model year: 2021
Engine power: 81 kW	Number of seats: 5
Engine size (cc) 999	Interior:

 VEHICLE DETAILS

Number of keys: 2	Number of license plates: 2	Registration certificate: Part 1 & 2 present	Service documentation: Yes
Inspection date: 29-06-2026	Last service (year/month): 2025/6	Mileage (km) at last service: 17.854	

 SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition: Yes	Legal tire tread (minimum 1.6 mm): Yes
--	--

WHEELS

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Alloy rim	16"	6 mm
Fitted	Summer tires		Rear Right	Alloy rim	16"	6 mm
Fitted	Summer tires		Rear Left	Alloy rim	16"	6 mm
Fitted	Summer tires		Front Right	Alloy rim	16"	6 mm


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES

Rear overhang- short, 4 doors, Front stabilizer bar, Wheelbase, Installation differentiation for transmission DQ200 -- vehicle components --, Standard manufacturing sequence, Fuel tank, Without alternative drive system, Standard rear axle, Nameplate set in basic style, Rear exhaust tailpipe (standard), Without floor mats, Manual in Danish, Standard climatic zones, Weight range 9 installation control only- no requirement forecast, Fuel system for fuel-injected SI engine (tropicalized), Electronic stability control (ESC), Antifreeze up to -25 degree Celsius tolerance up to -30 degree C, Tow bar (removable), Activated carbon canister (Evaporative Emission Control System (EVAP)), Special identification label for EC for M1 passenger vehicles, Breakdown kit, Rear shock absorption, Disk brakes rear, Power steering, Trims for alloy wheels, Wheel bolts with anti-theft protection (unlockable), Without tool kit and jack, Additional front underbody guard, Front-wheel drive, Initial standard fuel filling, Disc brakes in front (Geomet D), Without delivery equipment, Axial and vertical adjustable steering column, Vehicle class differentiation -6VN-, Leather multi-function steering wheel with tiptronic, Without "drive select", Body-colored bumpers, Standard bumpers, Fresh air intake system with combination filter, Fuel filler cap, Child seat anchors f. child seat system i-Size- 2x top tether and child seat anchors in front on front passenger side, Without partition, Central console - cuholder "Snowman", Without roof insert (standard roof), Without luggage/load compartment floor, Without backrest release for front seats, Height - adjustable driver and co-driver seat, Door and side trim panel, Without storage compartments in trunk, Rear seat backrest split 60:40- unsplit rear seat bench, 3rd head restrain rest, 3-point seat belts in front- with pretensioner/lap belt pretensioner and height adjustment, Preparation for roof load rack, Luggage compartment cover- folding, Acoustics package "Standard", Without storage compartment, 3-point seat belts- outer rear with ECE label, Alloy wheels "ROTARE" silver 5-5J x 15" - 4 pcs, Seat heater for front seats separately controlled, Emission standard EU6 AP, Heat-reflecting windshield, Central locking w/ radio remote control- interior controls- without SAFELock, Side and rear windows in heat-insulating glass, Breakaway interior rearview mirror- auto-dimming, Rear floor panel module- type 1, Front and rear windows electric (auto up/down function for all windows), Airbag on driver and front passenger side- knee airbag on driver side- with front passenger airbag deactivation, Side airbag in front and rear with curtain airbag, Standard glove compartment, Standard decorative trims, Carrier frequency 433.92 MHz-434.42 Mhz, Rear spoiler, Exterior mirrors: convex on driver side- convex on front passenger side, Transport protection film with additional transport protection measures, Decorative inserts, Folding grab handles at roof frame, Sun visors with mirror- airbag label on front passenger sun visor, Front head restraints, Without fire extinguisher, Center armrest in front, Without additional side body covers (stone guard), Without decorative films/emblems, Outside door mirrors and door handles in body color, Lane Assist, Forward collision warning incl. autonomous emergency braking- for adaptive cruise control "high", Radiator grille, Vent, Without tie down straps/net/pocket, Hand brake lever handle in leather, Gearshift knob/handle in leather, Without luggage compartment floor covering, Without additional seals outside, Exterior mirrors- electr. adjustable- heated - painted in exterior colour (for MC colored black), Electronic immobilizer, Without socket, Without heat accumulator/auxiliary heater, Tire pressure monitoring system, Start-stop system with regenerative braking, Without protective film for scuff plate, Spectacle storage compartment/bracket, Without lumbar support in seat backrests, Without navigation device, Without extended safety system, Parking sensors rear, Without lane change assist, Without second battery, Without light control, Alternator 140 A, LED headlamps, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Rear window wiper and washer system with intermittent control, Windshield wiper intermittent control with light/rain sensor, Headlight range control, Key for locking system with remote control, 4 speakers front + 2 rear incl. "koda Surround, Two reading lights in front- two in rear, Adaptive cruise control (with "follow-to-stop") and speed limiter, Rear fog lamp for driving on the right, Rear combination lamp, Washer fluid level indicator, Without front fog lamps, Without headlamp washer system, Single-tone horn, Not hot country, Antenna for FM reception only, Climatronic with impact pressure control- CFC-free, Luggage compartment lighting, Without additional malfunction display, Non-smoker's package, Without auxiliary heater/parking heater, Seatbelt warning - front + rear seats, "MAXI DOT" (KI Mid), Heated washer nozzles in front, "SMART LINK", Bluetooth, Comfort equipment, Driving on the right, "Standard Plus" version, Type approval country Denmark, Part set without country-specific prescriptive standard, Operating permit- alteration, 3-cylinder SI engine 1.0 l/81 kW TSI base engine is TJ4/TC5, No special edition, Without ECO function, Remote Access / Pro-active service, DRIVER ALERT SYSTEM, Regional code " ECE " for radio, No special purpose vehicle-standard equipment, Standard paint coating, CO2 variant, Shock absorption in front, 7-speed automatic transmission, Radio Bolero 8", Without bracket, Curb weight range 1, Rear axle weight- type 1, Battery 380 A (59 Ah) EFB+, Tires 185/65 R15 88H super-low rolling resistance- generation 2, Hatchback, Rear view camera - with washer nozzle, Refrigerant R1234yf, without USB in interior rear view mirror, Suspension range 05 installation control only- no requirement forecast, Left-hand drive, Seat trim covers in fabric, Adapter, With umbrella, E-Call+, FRONT ASSIST with ACC, LIGHT AND RAIN ASSIST(a. light switching +rain sensor+automatically dimming rear view mirror+TUNNEL LIGHT+CO/LE HOME), Tow bar- removable with adapter, Standard seats in front, Lower decorative inserts, Without storage compartment package/box, LongLife Service Regime, Without voice control, Service indicator 30 000 km or 2 years (variable), Chrome package, With multifunction camera, Without drawers under front seats, Without add. lights (interior lighting), Without dynamic road sign display, DAB - Digital radio reception, Control of logistics 2, 3-cylinder SI engine 1.0 l unit 05C.A, Instrument cluster- km/h speedometer, 2x USB front (typ C data), Hill start assist, Tires without specification of tire brand, Standard pedal cluster, Extended and proactive pedestrian and cyclist protection, Remote Access 1 year, Equipment options subset for Denmark

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=11695b0d-f705-444c-802a-83f0617d2e38&carid=20655776>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	Hood	Stone Chips	C3			
						

Severity explanation:
C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	