

VEHICLE DESCRIPTION - Škoda Superb Style 1.5 TSI ACT



First registration date	VIN:
6/2023	TMBJN7NP0P7061869
Colour:	Mileage (km):
null Metallic Normal gloss	42.217
Gear:	Fuel type:
Automatic (7 Gears)	Gasoline
Body type:	Number of doors:
Estate Wagon	5
Drive type:	Model year:
FWD	2019-2024
Engine power:	Number of seats:
110 kW	5
Engine size (cc)	Interior:
1498	

VEHICLE DETAILS

Number of keys:	Number of license plates:	Registration certificate:	Service documentation:
2	2	Part 2 present	Yes
Inspection date:	Last service (year/month):	Mileage (km) at last service:	
25-06-2026	2025/8	26.315	

SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition:	Legal tire tread (minimum 1.6 mm):
Yes	Yes

WHEELS

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Alloy rim	17"	5 mm
Fitted	Summer tires		Rear Right	Alloy rim	17"	5 mm
Fitted	Summer tires		Rear Left	Alloy rim	17"	5 mm
Fitted	Summer tires		Front Right	Alloy rim	17"	5 mm


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES

Remote Access 1 year, No special edition, Standard wheel bolts, Without adapter, Vehicle class differentiation -3V0-, Rear exhaust tailpipe (standard), Hill hold control, Emission standard EU6 AP, Preparation for tow bar, Driver knee airbag, Activated carbon canister (Evaporative Emission Control System (EVAP)), Antenna for FM reception only- diversity, Ext. mirrors with memory feature- auto- dimming on driver's side- el.folding/adjustable- separately heated, Left exterior mirror- convex, Standard electronic engine sound, Right exterior mirror- convex, Without alternative drive system, Front-wheel drive, "SMART LINK" (wireless for Apple), Equipment level - Style, "FRONT ASSIST" - radar scanning of the space in front of the car- incl. City ANB- wo. "ADAPTIVE CRUISE ASSISTANT", Disc brakes in rear, Battery 420 A (70 Ah), Disc brakes in front, Exterior mirror housings and various add-on parts in body color, Standard battery/alternator capacity, Part set without country-specific prescriptive standard, Tool kit, Brake control system for vehicles without electric drive (ESC and electromechanical brake booster), Front passenger seat control, Manual in Danish, Operating voltage 12 V, Heated windscreen washer nozzles, Without CD/DVD for navigation, Without "drive select", Chrome package (type 2), Operating permit- alteration, Roof rails- anodised, Without roof insert (standard roof), Rear shock absorption- basic version 1, Shock absorption in front, Without load-through hatch, Without ECO function, Installation differentiation for transmission DQ200 -- vehicle components --, Electronic immobilizer, Decor moulding Argenzo Zebrano with chrom and ambient lighting, Decorative door sills front and rear, PDC with "MANOEUVRE ASSIST" - parking sensors front & rear with aut. braking, Without extended safety system, 2x USB front, Standard manufacturing sequence, Without fire extinguisher, Without additional malfunction display, Extended and proactive pedestrian protection, Standard pedal cluster, "LIGHT ASSISTANT" ("COMMING HOME"- "LEAVING HOME"- "TUNNEL LIGHT"- "DAY LIGHT"), Parking brake, No special purpose vehicle- standard equipment, Additional interior noise suppression, Alternator 140 A, Weight range 3 installation control only- no requirement forecast, Suspension range 05 installation control only- no requirement forecast, 4-cylinder SI engine 1.5 l unit 05E.A, Luggage compartment cover- folding, Without tie down straps/net/pocket, "CRUISE CONTROL" - with Speedlimiter, Without garage door opener, 7-speed automatic transmission, Without bracket, Roof spoiler, Rear window wiper "AERO", Unsplit molded headliner, Unsplit rear seat bench- split folding backrest- with center armrest, Climatronic (3-zone) with air conditioning control panel in rear, Low LED Basic headlamps + LED Daylight, Without head-up display, Without electric motor (hybrid), Interior light in footwell in front and rear, Instrument cluster- km/h speedometer, Breakaway interior rearview mirror- auto-dimming, Wagon/Avant, With multifunction camera, Fuel tank, Power-operated child safety lock, Without child seat, Storage box with cover in luggage compartment side panel (covers on both sides) plus cargoelement, Standard climatic zones, Without compass/road sign display/dynamic road sign display, Without seat ventilation/massage seat, Three rear head restraints, Front head restraints, Initial standard fuel filling, Fuel system for fuel-injected SI engine, Without special body measures, Preparation for child seats anchor with safety system "ISOFIX" on passenger seat, Without camera systems/accident sensors, Radiator grille with chrome molding, Refrigerant R1234yf, Transport protection film with additional transport protection measures, Standard paint coating, Without luggage/load compartment floor, Interior ambient lighting- type 2, Without vehicle inlet, Left-hand drive, Speed-related variable steering assist (Servotronic), Without backrest release for front seats, Curb weight range 1, High-beam control, Without charging cable, Power-adjustable lumbar support in front seats, 2 spoke multifunction leather steering wheel- black stitching, Driving on the right, 8 speakers (passive), Headlight range control, Center armrest in front, Basic equipment variant, "Virtual Cockpit", Center console, "DRIVER ALERT" - driver alert system, Not hot country, 4-cylinder SI engine 1.5 l/110 kW TSI base engine is TJ7/N09/T9F/T57/T0D, Radio Bolero, Rear fog lamp, Front fog lamp and cornering lamp, Remote Access / Remote Access + Online Infotainment, Vehicles with special upgrade measures, Trims for alloy wheels, Alloy wheels "STRATOS" 7Jx17", Optional infotainment system (MIB3), Non-smoker's package, Regional code " ECE " for radio, Tire pressure monitoring system, Tires 215/55 R17 94V super-low rolling resistance- generation 2 (polymer coating), Tires without specification of tire brand, Breakdown kit, Wheelbase, 3-point seat belts in front- with tensioner and height adjustment, Emergency call system eCall+, Side airbag in front with curtain airbag, Gearshift knob/handle in leather, LED taillights, Tailgate/trunk lid release, Service indicator 30 000 km or 2 years (variable), Without locking and starting systems, Passenger seat-belt warning light (for all passenger), 3-point seat belts- outer rear with ECE label, 3-point seat belt for center rear seat, Seat trim covers in fabric, Power seats in front- driver seat with memory feature, Heated front seats, Key for locking system with remote control, Start-stop system with regenerative braking, Two-tone horn, Sun visor with make-up mirror and LED illumination and airbagschield, Voice control, Without lane change assist, Without lane keeping system, Side and rear windows in heat-insulating glass, Without roll-up sunshade, 12-volt socket(s), Body-colored bumpers, Standard engine starter, Telescopic headlamps washers, Windshield wiper intermittent control with light/rain sensor, Without mud flap, Nameplate set in basic style, Without mass damper for steering wheel, "KESSY FULL" without "SAFE" system, Type approval country Denmark, Carrier frequency 433.92 MHz-434.42 Mhz, Without partition, Door and side trim panel in foam film and woven fabric, DAB - Digital radio reception, Without additional front underbody guard, Special identification label for EC for M1 passenger vehicles, Without delivery equipment, Without preparation for two-way radio installation, Comfort seats in front, Standard rear seat release, Comfort telephony with LTE and wireless charging, Additional warning lights (door area), LongLife Service Regime, Without heat accumulator/auxiliary heater, Heat-reflecting windshield, Without second battery, Without additional tires, Textile floor mats, Chrom trimming around side windows, Child seat anchors for child seat system ISOFIX, With electronic steering column lock, Without auxiliary heater/parking heater, Without clock, Equipment options subset for Denmark

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=e6cbdbff-cb2e-4ec3-a3df-ec4fdd6818af&carid=20689086>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	Front Windscreen	Rep Defect	C5		Reporting needed	
						
2	R. Front Rim	Scratch	C4		Reporting needed	
						

Severity explanation:
C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	