



VEHICLE DESCRIPTION - Audi A4 S Line Plus 2.0 40 TFSI MHEV



|                                |                         |
|--------------------------------|-------------------------|
| <b>First registration date</b> | <b>VIN:</b>             |
| 6/2023                         | WAUZZZF42PA035345       |
| <b>Colour:</b>                 | <b>Mileage (km):</b>    |
| null Metallic Normal gloss     | 29.728                  |
| <b>Gear:</b>                   | <b>Fuel type:</b>       |
| Automatic (7 Gears)            | Hybrid petrol           |
| <b>Body type:</b>              | <b>Number of doors:</b> |
| Estate Wagon                   | 5                       |
| <b>Drive type:</b>             | <b>Model year:</b>      |
| FWD                            | 2019-2024               |
| <b>Engine power:</b>           | <b>Number of seats:</b> |
| 150 kW                         | 5                       |
| <b>Engine size (cc)</b>        | <b>Interior:</b>        |
| 1984                           |                         |



VEHICLE DETAILS

|                         |                                   |                                      |                               |
|-------------------------|-----------------------------------|--------------------------------------|-------------------------------|
| <b>Number of keys:</b>  | <b>Number of license plates:</b>  | <b>Registration certificate:</b>     | <b>Service documentation:</b> |
| 2                       | 2                                 | Part 1 present                       | Yes                           |
| <b>Inspection date:</b> | <b>Last service (year/month):</b> | <b>Mileage (km) at last service:</b> |                               |
| 28-07-2026              | 2025/2                            | 14.646                               |                               |



SUMMARY OF THE VEHICLE'S CONDITION

|                                             |                                           |
|---------------------------------------------|-------------------------------------------|
| <b>Is the car in a driveable condition:</b> | <b>Legal tire tread (minimum 1.6 mm):</b> |
| Yes                                         | Yes                                       |

WHEELS

|  TYPE | SEASON       | BRAND | POSITION    | RIM       | SIZE | TREAD |
|---------------------------------------------------------------------------------------|--------------|-------|-------------|-----------|------|-------|
| Fitted                                                                                | Summer tires |       | Front Left  | Alloy rim | 18"  | 5 mm  |
| Fitted                                                                                | Summer tires |       | Rear Right  | Alloy rim | 18"  | 5 mm  |
| Fitted                                                                                | Summer tires |       | Rear Left   | Alloy rim | 18"  | 5 mm  |
| Fitted                                                                                | Summer tires |       | Front Right | Alloy rim | 18"  | 5 mm  |


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES

Basic, Standard, Standard manufacturing sequence, tiptronic, Weight category front axle weight range 8, Mild hybrid, With special labels safety certificates for Denmark, Fuel tank with increased capacity, Standard exhaust system, Without ignition/starter switch locking system- without steering lock, Floor mats- front and rear, Without special color trim, Manual in Danish, Standard climatic zones, Weight range 7 installation control only- no requirement forecast, Fuel system for SI engine with direct injection (FSI), Sport suspension, Preparation for trailer hitch, Special identification label (EU), Tire repair kit, Disk brakes- rear- 16-inch (ECE), Disk brakes- front- 16-inch (ECE), Standard wheel bolts, Vehicle tool kit, Without additional front underbody guard, First-aid kit with warning triangle and high-visibility vests, Installation parts for four-cylinder engine, Front-wheel drive, Leather steering wheel- 3-spoke with multifunction plus, Initial standard fuel filling, Without locking and starting systems, Insert for the filling up of unleaded fuel, Audi drive select, Bumpers- S line, Labels in English and German, Without additional tires, Model name as per new output designation, ISOFIX child seat mounting and top tether for the outer rear seats, Without roof insert (standard roof), Without child seat anchora in front (ISOFIX), Loading floor, Without backrest release for front seats, Front seats- manually adjustable, Passenger car design, Split-folding rear seat backrest, Roof rails in aluminum, Without roll-up sunshade, Seat heating- front, Emission standard EU6 AP, Without seat ventilation/massage seat, Luggage compartment lid- electrically opening and closing, Windshield with heat-reflecting glass and acoustic glass, Child-proof lock, Remote control key- without Safelock, Rear and side windows with heat-insulating glazing, Interior mirror- automatically dimming- frameless, Airbags- front, front passenger airbag can be deactivated, Side airbags- front and head airbag system, Gloss package, Luggage compartment trim (design 2), Without special body measures, Carrier frequency 433.92 MHz- 434.42 Mhz, Without rear spoiler, Adhesive film, Without front spoiler, Exterior mirrors on the right- (large field of view)- convex, Left exterior mirror- aspherical, Inlays- Matt Brushed Aluminum, Sun visors- front, Head restraints- front, Without fire extinguisher, Comfort center armrest- front, Additional stone guard body covers, Emblems, Exterior mirror housings in body color, Roof in body color, Audi active lane assist, Body-colored door handles, Audi pre sense city, Headlining in cloth- Black, Luggage compartment mat, Rear trim panel (ECE), Front license plate carrier, Exterior mirrors- electrically adjustable and heated, Cancellation of 210-km/h top speed limit, Electronic immobilizer, Without heat accumulator/auxiliary heater, Without preparation for VTS (vehicle tracking system), Without leather, Vehicle class differentiation -8W0/8WA-, Tire pressure loss indicator, Start-stop system, Without wind deflector, MMI navigation plus with MMI touch, Without extended safety system, Parking system plus, Without lane change assist, High beam assistant, Lumbar support- pneumatically adjustable with massage function for the front seats, LED headlights, Separate daytime running light, 8 loudspeakers, Audi adaptive cruise control, LED rear lights plus, Without headlamp washer system, Two-tone horn, Not hot country, 3-zone deluxe automatic air conditioning, Without integrated toll system, Belt-driven integrated starter alternator 12 V- 130 - 200 A, Non-smoker version, Without neck heating, Without auxiliary heater/parking heater, Seat belt reminder, Audi virtual cockpit plus, Without additional warning lights, Without "Multimedia" in vehicle, Audi phone box light, No self-collection, Audi AG, Category 0, S line, Standard-production quality, Driving on the right, Type approval country Denmark, Part set without country-specific prescriptive standard, Operating permit- alteration, 4-cyl. SI eng. 2.0 l/150 kW (16V) turbo FSI- homogen.- base eng. TR6/T2A/T2C/TC3/TI2/T66/T4X/TI2/T5V/TC1/T1F/T4E/T4M, No special edition, Regional code " ECE " for radio, No special purpose vehicle- standard equipment, Control of series production, Without AdBlue tank, Basic equipment variant, Preparation for functions on demand, Production wheels, Country group A, Seat belts in Black, S tronic, Without preconditioning, Without antenna amplifier, Without rear differential, Vehicles with special upgrade measures, Accent surfaces- Gloss Black, Without Car2X, Tires 245/40 R18 93Y, Audi connect navigation & infotainment, Preparation for smartphone interface, Audi connect emergency call & service with Audi connect remote & control, SI engine, Battery 380 A (68 Ah), Data module- Europe, Wagon/Avant, Without camera systems/accident sensors, Refrigerant R1234yf, Without head-up display, Left-hand drive, Sequence cloth/leather combination, Engine cover, Transit coating (type 1), Standard battery/alternator capacity, Assist package Tour, Deselection of tires with optimized rolling resistance- cancellation of speed limitation (18-inch), LED headlights and LED rear lights with dynamic turn signal in rear, Sport seats- front, Without Storage package, Service indicator 30 000 km or 2 years ( variable ), With multifunction camera, Rear window- rear door and side windows in clear glass, Interior lighting, Camera-based traffic sign recognition, Digital Audio Broadcasting, Electromechanical power steering, Control of special edition prices, 4-cylinder SI engine 2.0 l unit 06N.A 888evo4, Instrument cluster- km/h speedometer, Electromechanical parking brake, Tires without specification of tire brand, Wheels- 5-Y-spoke- S design- 8.0J x 18- 245/40 R18 tires, Without garage door opener, Stainless steel pedals and footrest, Standard electric, Extended pedestrian protection, Door sill trims with aluminum inlays- front- illuminated- S logo, Equipment package for Denmark, Equipment package for Denmark, Interior S line, Internal control code, Internal control code, Internal control code, Internal control code, Equipment options subset for Denmark

## PICTURES



**Picture viewer:** <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=213e3092-0188-4d74-8f67-8dbe743ad07c&carid=20758682>



OVERVIEW OF DAMAGES AND SHORTAGES

| N° | LOCATION                                                                            | TYPE                                                                                | SEVERITY                                                                            | INSURANCE                                                                           | NOTES | DAMAGE GROUP |
|----|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------|--------------|
| 1  | Front Bumper, Grill                                                                 | Cracked                                                                             | C5                                                                                  | Reporting needed                                                                    |       | Group 2      |
|    |    |    |                                                                                     |                                                                                     |       |              |
| 2  | L. Front Quarter Panel                                                              | Dent                                                                                | C4                                                                                  | Reporting needed                                                                    |       | Group 1      |
|    |    |    |    |    |       |              |
| 3  | Front Bumper, Spoiler                                                               | Dent                                                                                | C4                                                                                  | Reporting needed                                                                    |       | Group 2      |
|    |    |    |    |    |       |              |
| 4  | R. Front Rim                                                                        | Scratch                                                                             | C4                                                                                  | Reporting needed                                                                    |       |              |
|    |    |    |                                                                                     |                                                                                     |       |              |
| 5  | Front Bumper                                                                        | Scratch                                                                             | C4                                                                                  | Reporting needed                                                                    |       | Group 1      |
|    |  |  |  |  |       |              |
| 6  | R. Rear Door                                                                        | Dent                                                                                | C3                                                                                  |                                                                                     |       |              |
|    |  |  |                                                                                     |                                                                                     |       |              |
| 7  | R. Front Door                                                                       | Dent                                                                                | C3                                                                                  |                                                                                     |       |              |
|    |  |  |                                                                                     |                                                                                     |       |              |
| 8  | Roof                                                                                | Scratch                                                                             | C3                                                                                  |                                                                                     |       |              |
|    |  |  |  |                                                                                     |       |              |
| 9  | Hood                                                                                | Dent                                                                                | C3                                                                                  |                                                                                     |       |              |
|    |  |  |                                                                                     |                                                                                     |       |              |
| 10 | L. Rear Quarter Panel                                                               | Dent                                                                                | C3                                                                                  |                                                                                     |       |              |
|    |  |  |                                                                                     |                                                                                     |       |              |
| 11 | L. Front Door, Handle                                                               | Scratch                                                                             | C3                                                                                  |                                                                                     |       |              |
|    |  |  |                                                                                     |                                                                                     |       |              |

| N° | LOCATION                                                                          | TYPE                                                                              | SEVERITY                                                                          | INSURANCE | NOTES | DAMAGE GROUP |
|----|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------|-------|--------------|
| 12 | L. Rear Door                                                                      | Dent                                                                              | C3                                                                                |           |       |              |
|    |  |  |                                                                                   |           |       |              |
| 13 | L. Front door                                                                     | Dent                                                                              | C3                                                                                |           |       |              |
|    |  |  |                                                                                   |           |       |              |
| 14 | Rear Bumper                                                                       | Scratch                                                                           | C3                                                                                |           |       |              |
|    |  |  |  |           |       |              |

Severity explanation:  
C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

| N° | LOCATION            | TYPE | NOTES |
|----|---------------------|------|-------|
| 1  | Is the car drivable | Yes  |       |