

**VEHICLE DESCRIPTION - Škoda Kodiaq Style 2.0 TDI**



**First registration date:**  
7/2023

**VIN:**  
TMBJJ7NS9P8046989

**Colour:**  
Black Metallic Normal gloss

**Mileage (km):**  
56.556

**Gear:**  
Automatic (7 Gears)

**Fuel type:**  
Diesel

**Body type:**  
SUV

**Number of doors:**  
5

**Drive type:**  
FWD

**Model year:**  
2021-2024

**Engine power:**  
110 kW

**Number of seats:**  
7

**Engine size (cc):**  
1968

**Interior:**  
Black Partial leatherette

**VEHICLE DETAILS**

**Number of keys:**  
2

**Number of license plates:**  
2

**Registration certificate:**  
Part 1 & 2 present

**Service documentation:**  
Yes

**Inspection date:**  
16-06-2026

**Last service (year/month):**  
2026/4

**Mileage (km) at last service:**  
53.945

**SUMMARY OF THE VEHICLE'S CONDITION**

**Is the car in a driveable condition:**  
Yes

**Legal tire tread (minimum 1.6 mm):**  
Yes

**WHEELS**

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Alloy rim	19"	5 mm
Fitted	Summer tires		Front Right	Alloy rim	19"	5 mm
Fitted	Summer tires		Rear Left	Alloy rim	19"	5 mm
Fitted	Summer tires		Rear Right	Alloy rim	19"	5 mm
Extra Wheel	Winter tires		Front Left	Steel rim	17"	6 mm
Extra Wheel	Winter tires		Front Right	Steel rim	17"	6 mm
Extra Wheel	Winter tires		Rear Left	Steel rim	17"	6 mm
Extra Wheel	Winter tires		Rear Right	Steel rim	17"	6 mm

**Legal tire tread (minimum 1.6 mm):**

Yes

## ACCESSORIES




Variable boot floor, Heated windscreen + rain sensor with Light Assist, Remote Access 1 year, No special edition, Standard wheel bolts, Without adapter, Vehicle class differentiation -55A-, Hill start assist, Emission standard EU6 AP, Trailer hitch mechanically swiveling and power-detachable, Driver knee airbag, Without activated carbon canister with SCR, Without trash bin, Overhead storage compartment, Antenna for FM reception only- diversity, Exterior mirrors- auto-dimming- power-folding/adjustable/heated, Left exterior mirror- convex, Without electronic engine sound measures, Right exterior mirror- convex, Without alternative drive system, Front-wheel drive, "SMART LINK" (wireless for Apple), Sports equipment, Forward collision warning incl. autonomous emergency braking- for adaptive cruise control "high", Disc brakes in rear, Battery 420 A (70 Ah), Disc brakes in front, Exterior mirror housings and various add-on parts in body color, Standard battery/alternator capacity, Part set without country-specific prescriptive standard, Tool kit, Electronic stability control (ESC), Manual in Danish, Operating voltage 12 V, Heated washer nozzles in front, Without "drive select", Chrome package, Operating permit- alteration, Bright roof rails, Without roof insert (standard roof), Rear shock absorption-basic version 1, Shock absorption in front, Without load-through hatch, Without ECO function, Installation differentiation for transmission DQ381 -- vehicle components --, Electronic immobilizer, Decorative inserts, Scuff plates in door apertures, Park distance control in front and rear, Without extended safety system, USB front, Standard manufacturing sequence, Without fire extinguisher, Without additional malfunction display, Extended and proactive pedestrian protection, Standard pedal cluster, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Parking brake, No special purpose vehicle- standard equipment, Special interior noise suppression, Alternator 180 A, Weight range 12 installation control only- no requirement forecast, Suspension range 05 installation control only- no requirement forecast, 4-cylinder diesel engine 2.0 l unit 05L.D, Luggage pockets on backrest, Luggage compartment cover- sliding, Without tie down straps/net/pocket, Adaptive cruise control (with "follow-to-stop") and speed limiter, Luggage compartment lamp, Additional exterior noise suppression, 7-speed automatic transmission, Without bracket, Roof spoiler, Rear axle weight- type 1, Unsplit molded headliner, Rear seat bench/backrest- split folding, Climatronic (3-zone) with air conditioning control panel in rear, LED headlamps, Without head-up display, Interior light in footwell in front and rear, Instrument cluster- km/h speedometer, Breakaway interior rearview mirror- auto-dimming, Without decals and emblems, Hatchback, Without multifunction camera, Luggage compartment floor covering in needle-punched nonwoven, Manual child safety lock, Storage compartments with cover in trunk side panel, Without folding table on front seat backrest, Standard climatic zones, Without dynamic road sign display, Without seat ventilation/massage seat, Three rear head restraints, Front head restraints, Initial standard fuel filling, Fuel system for diesel engine, Without special body measures, Without child seat anchora in front (ISOFIX), With rear view camera system (type 2), Refrigerant R1234yf, Transport protection film with additional transport protection measures, Standard paint coating, Raised luggage/load compartment floor in rear, Interior ambient lighting- type 1, Left-hand drive, 2 reading lights in front, Speed-related variable steering assist (Servotronic), Without backrest release for front seats, Curb weight range 1, High-beam control, Manually adjustable lumbar support in front seats, Leather-wrapped multi-function steering wheel- heated- with tiptronic, Driving on the right, 8 speakers (passive), Headlight range control, Center armrest in front, Variant, Virtual Cockpit, Driver alert system, Not hot country, 4-cyl. turbo diesel 2.0l/110kW(4V) TDI CR, b.eng. T37/T3Y/TS1/T4P/T98/T4S/TR1 T0N/T13/T29/TD1/T19/T3C/T1N/T27/T1Q/T5M, Radio Bolero, Rear fog lamp, Front fog lamps, Remote Access / Remote Access + Online Infotainment, Trims for alloy wheels, Alloy wheels 7J x 19 "TRIGLAV", Optional infotainment system (MIB3), Non-smoker's package, Regional code " ECE " for radio, Tire pressure monitoring system, Tires 235/50 R19 99V, Tires without specification of tire brand, Breakdown kit, Wheelbase, 3-point seat belts in front- with tensioner and height adjustment, Emergency call system eCall+, Side airbag in front with curtain airbag, Gearshift knob/handle in leather, LED rear combination lamp- variable lighting functions- special styling, Tailgate/trunk lid power closing, Service indicator 30 000 km or 2 years ( variable ), Without locking and starting systems, Visual and acoustic seat belt reminder- electric contact, 3-point seat belts- outer rear with ECE label, 3-point seat belt for center rear seat, Seat trim covers in fabric + leather, Manual height adjustment for front seats, Seat heater for front seats separately controlled, Key for locking system with remote control, Start-stop system with regenerative braking, Two-tone horn, Sun visors with mirror- illuminated, Voice control, Without lane change assist, Without lane keeping system, "SUNSET", Without protective side molding, Without roll-up sunshade, 12-volt socket(s), Standard bumpers, Rear stabilizer bar, Front stabilizer bar, Control of series production, Drawers under front seats, Headlamp washer system, Windshield wiper intermittent control with light/rain sensor, Without mud flap, Nameplate set in basic style, Fuel filler cap, Central locking system Keyless Entry without SAFELock, Type approval country Denmark, Carrier frequency 433.92 MHz-434.42 Mhz, Without partition, Door and side trim panel in leather, DAB - Digital radio reception, Without additional front underbody guard, Special identification label for EC for M1 passenger vehicles, Without delivery equipment, Comfort seats in front, Mechanical rear seat release, Comfort telephony with LTE and wireless charging, Additional retro-reflectors (door area), LongLife Service Regime, Electric auxiliary air heater, Heat insulating windshield, Washer fluid level indicator, Without second battery, Without additional tires, Floor mats in front and rear, Bright decorative trims, Child seat anchors for child seat system ISOFIX, With electronic steering column lock, Without auxiliary heater/parking heater, Equipment options subset for Denmark

**PICTURES**



**Picture viewer:** <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=2a8c2ddb-8710-454f-af13-33d6607c4e84&carid=20904144>

## OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	L. Rear Door	Dent	C4		Reporting needed	
						
2	Front Bumper	Scratch	C4		Reporting needed	
						
3	R. Rear Door	Dent	C3			
						

Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

## ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	