

 VEHICLE DESCRIPTION - Škoda Scala Ambition 1.0 TSI



First registration date 8/2023	VIN: TMBER7NW7P3145918
Colour: Black Metallic Normal gloss	Mileage (km): 56.144
Gear: Manual (6 Gears)	Fuel type: Gasoline
Body type: Hatchback	Number of doors: 5
Drive type: FWD	Model year: 2018-2024
Engine power: 81 kW	Number of seats: 5
Engine size (cc) 999	Interior: Black Fabric

 VEHICLE DETAILS

Number of keys: 2	Number of license plates: 2	Registration certificate: Part 1 & 2 present	Service documentation: Yes
Inspection date: 17-08-2026	Last service (year/month): 2025/3	Mileage (km) at last service: 29.229	

 SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition: Yes	Legal tire tread (minimum 1.6 mm): Yes
--	--

WHEELS

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	All year tires		Front Left	Steel rim	16"	5 mm
Fitted	All year tires		Rear Right	Steel rim	16"	7 mm
Fitted	All year tires		Rear Left	Steel rim	16"	7 mm
Fitted	All year tires		Front Right	Steel rim	16"	5 mm


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES

Rear overhang- medium, 4 doors, Front stabilizer bar, Wheelbase, Installation differentiation for transmission MQ 200_GA -- vehicle components --, Standard manufacturing sequence, Without alternative drive system, Standard rear axle, Nameplate set in basic style, Without electronic steering column lock, Without floor mats, Manual in Danish, Standard climatic zones, Weight range 13 installation control only- no requirement forecast, Fuel system for fuel-injected SI engine (tropicalized), Electronic stability control (ESC), Antifreeze up to -25 degree Celsius tolerance up to -30 degree C, Activated carbon canister (Evaporative Emission Control System (EVAP)), Special identification label for EC for M1 passenger vehicles, Breakdown kit, Rear shock absorption- basic version 1, Disc brakes in rear (Geomet D), Trailer hitch mechanically swiveling and power-detachable, Power steering, Steel wheels cover Tecton 16", Standard wheel bolts, Tool kit, Additional front underbody guard, Without folding table on front seat backrest, Without refrigerator/glove compartment cooling system, Front-wheel drive, Initial standard fuel filling, Disc brakes in front (Geomet D), Without delivery equipment, Additional exterior noise suppression, Axial and vertical adjustable steering column, Without "drive select", Body-colored bumpers, Fresh air intake system with combination filter, Multi-function steering wheel, Child seat anchors f. child seat system i-Size- 2x top tether and child seat anchors in front on front passenger side, 3-point seat belt for center rear seat, Without partition, Center console, Without roof insert (standard roof), Without luggage/load compartment floor, Without backrest release for front seats, Hight-adjustable head restraints for front seats, Manual height adjustment for front seats, Door panels with upholstery, Mounting fixture in luggage compartment, Unsplit rear seat bench- split folding backrest, Three rear head restraints, 3-point seat belts in front- with tensioner and height adjustment, Long rear window with spoiler, Without roof rails/roof load rack, Luggage compartment cover, Without additional noise suppression measures for passenger compartment, 3-point seat belts- outer rear with ECE label, Seat heater for front seats separately controlled, Without protective side molding, Emission standard EU6 AP, Tailgate without electrical opening, Heat-reflecting windshield, Central locking w/ radio remote control- interior controls- without SAFELOCK, Side and rear windows in heat-insulating glass, Breakaway interior rearview mirror- auto-dimming, Rear floor panel module- type 3, Power windows with comfort operation and circuit breaker, Driver knee airbag, Side airbag in front with curtain airbag, Without waste bin, Glove compartment door with light, Standard decorative trims, Carrier frequency 433.92 MHz-434.42 Mhz, Transport protection film with additional transport protection measures, Decorative inserts Grained Black, Right exterior mirror- convex, Left exterior mirror- convex, Sun visors with mirror and airbag label on front passenger side, Without fire extinguisher, Center armrest in front "Jumbo Box", Without additional side body covers (stone guard), Without decorative films/emblems, Outside door mirrors and door handles in body color, Spurhalte assist, "FRONT ASSIST" - radar scan.of the space in front of the car- incl.City ANB- without "ADAPTIVE CRUISE ASSISTANT", Radiator grille with chrome molding, Interiorbars and air vents frame Black glossy, Luggage net, Grey ceiling, Gearshift knob/handle in leather, Without two-sided floor surface, Exterior mirrors- power-adjustable/heated, Electronic immobilizer, Without socket, Without heat accumulator/auxiliary heater, Tire pressure monitoring system, Start-stop system with regenerative braking, Vehicle class differentiation -655-, Without protective film for scuff plate, Spectacle storage compartment/bracket, Manually adjustable lumbar support in front seats, Without navigation device, Without extended safety system, Without park distance control, Without lane change assist, Basic LED Headlights, Without second battery, Without light control, Alternator 140 A, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Rear window wiper and washer system with intermittent control, Windshield wiper intermittent control with light sensor, Headlight range control, Key for locking system with remote control, 4 speakers (passive), Electronic cruise control + Speedlimiter, LED rear combination lamp- dynamic turn signal- special styling, Without washer fluid level indicator, Front fog lamps, Without headlamp washer system, Single-tone horn, Not hot country, Antenna for FM reception only- diversity, Climatronic with impact pressure control- CFC-free, Without additional malfunction display, Non-smoker's package, Without auxiliary heater/parking heater, Visual and acoustic seat belt reminder- electric contact, Boardcomputer Maxidot, Heated washer nozzles in front, Without "Multimedia" in vehicle, Bluetooth, Ambition, Driving on the right, Standard version, Type approval country Denmark, Part set without country-specific prescriptive standard, Operating permit- alteration, Steel wheels 6jx16" ET 40 "Tecton", 3-cylinder SI engine 1.0 l/81 kW TSI base engine is TJ4/TC5, No special edition, Without ECO function, Remote Access / Pro-active service, Driver alert system, Regional code " ECE " for radio, No special purpose vehicle- standard equipment, Standard paint coating, Basic equipment variant, Shock absorption in front, 6-speed manual transmission, Tires 205/55 R16 91V super-low rolling resistance, Radio Swing 6-5", Without bracket, Curb weight range 1, Rear axle weight- type 1, Battery 380 A (59 Ah) EFB+, Spaceback, Without camera systems/accident sensors, Refrigerant R1234yf, With trim panel, Suspension range 05 installation control only- no requirement forecast, Left-hand drive, Seat Ambition, Adapter, With umbrella, Emergency call system eCall+, Tow bar swiveling- el. unlockable and wi th adaptor, Standard Seats, LongLife Service Regime, Without voice control, Service indicator 30 000 km or 2 years (variable), Black Piano, With multifunction camera, Without drawers under front seats, Without add. lights (interior lighting), Without dynamic road sign display, DAB - Digital radio reception, 3-cylinder SI engine 1.0 l unit 05CA, Instrument cluster- km/h speedometer, 2 USB Typ-C vorne, Without hill hold control, Care connect 1 year, Tires without specification of tire brand, Standard pedal cluster, Extended and proactive pedestrian and cyclist protection, Equipment options subset for Denmark

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=fdee5c13-0299-49be-adeb-117b97f9088d&carid=20983543>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	Instrument panel, Center Console	Broken	C5		Reporting needed	
						
2	Drivers Seat	Discoloration	C4		Reporting needed	
						
3	Rear Bumper	Scratch	C4		Reporting done	
	  					
4	R. Rear Door	Dent	C3			
	  					
5	R. Rocker Panel, Inside	Scratch	C3			
						
6	L. Rear Door	Scratch	C3			
						
7	L. Rocker Panel, Inside	Scratch	C3			
	 					
8	L. Front Quarter Panel	Scratch	C3			
						
9	Rear Hood	Scratch	C3			
	 					

Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	