

VEHICLE DESCRIPTION - Seat Ibiza Style 1.0 MPI



First registration date 8/2023	VIN: VSSZZZKJ3RR013064
Colour: Red Normal gloss	Mileage (km): 44.414
Gear: Manual (5 Gears)	Fuel type: Gasoline
Body type: Hatchback	Number of doors: 5
Drive type: FWD	Model year: 2021-2025
Engine power: 59 kW	Number of seats: 5
Engine size (cc) 999	Interior: Black Fabric

VEHICLE DETAILS

Number of keys: 2	Number of license plates: 2	Registration certificate: Part 1 & 2 present	Service documentation: Yes
Inspection date: 27-08-2026	Last service (year/month): 2025/8	Mileage (km) at last service: 30.401	

SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition: Yes	Legal tire tread (minimum 1.6 mm): Yes
--	--

WHEELS

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Alloy rim	15"	7 mm
Fitted	Summer tires		Rear Right	Alloy rim	15"	6 mm
Fitted	Summer tires		Rear Left	Alloy rim	15"	6 mm
Fitted	Summer tires		Front Right	Alloy rim	15"	7 mm


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES

No special edition, Standard wheel bolts, Vehicle class differentiation -6F0-, Rear exhaust tailpipe (standard), Hill start assist, Emission standard EU6 AP, Without trailer hitch, Airbag on driver and front passenger side- without knee airbag- with front passenger airbag deactivation, Activated carbon canister (Evaporative Emission Control System (EVAP)), Antenna for AM/FM reception, Without applications, Exterior mirrors- power-folding/adjustment- heated, Left exterior mirror-convex, Right exterior mirror- convex, Without alternative drive system, Front-wheel drive, Wired & Wireless App-Connect, Luxury equipment, Forward collision warning incl. autonomous emergency braking- without adaptive cruise control, Drum brakes in rear, Battery 320 A (49 Ah), Disc brakes in front (Geomet D), Exterior mirror housings and various add-on parts in body color, Without special color trim, Part set without country-specific prescriptive standard, Tool kit, Electronic stability control (ESC), Manual in Danish, Without heated washer nozzles, Without CD/DVD for navigation, Without CD changer/CD player, Without "drive select", Chrome package, Operating permit- alteration, Without roof rails/roof load rack, Without roof insert (standard roof), Rear shock absorption, Without decorative films/emblems, Shock absorption in front, Without differential lock, Without UN-ECE cybersecurity & software update, Without ECO function, Installation differentiation for transmission MQ 200 -- vehicle components --, Electronic immobilizer, Decorative inserts, Without park distance control, Without extended safety system, External- USB type C- only data socket(s), Standard manufacturing sequence, Power windows with comfort operation and circuit breaker, Without fire extinguisher, Extended and proactive pedestrian and cyclist protection, Standard pedal cluster, Vent, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Fresh air intake system with combination filter, Antifreeze up to -25 degree Celsius tolerance up to -30 degree C, No special purpose vehicle- standard equipment, Without additional noise suppression measures for passenger compartment, Alternator 140 A, Weight range 4 installation control only- no requirement forecast, Suspension range 03 installation control only- no requirement forecast, 3-cylinder SI engine 1.0 l unit 05C.1, Without luggage nets/pockets on backrests, Luggage compartment cover- folding, Cruise control system and speed limiter, Luggage compartment trim (design 1), 5-speed manual transmission "M5", Hand brake lever handle in leather, Without rear spoiler, Rear window wiper and washer system with intermittent control, Standard rear axle, Unsplit molded headliner, Unsplit rear seat bench- split folding backrest, Climatronic with impact pressure control- CFC-free, LED headlamps, Without customized installation, Without interior light in footwell, Instrument cluster- km/h speedometer, Standard dashboard, Breakaway interior rearview mirror- auto-dimming, Hatchback, With multifunction camera, Without mounting fixture in luggage compartment, Standard climatic zones, Without dynamic road sign display, Three rear head restraints, Front head restraints, Initial standard fuel filling, Fuel system for fuel-injected SI engine (tropicalized), Without special body measures, Without camera systems/accident sensors, Refrigerant R1234yf, Standard license plate lighting, Without surface protection- with additional transport protection measures, Standard paint coating, Without luggage/load compartment floor, Without add. lights (interior lighting), Left-hand drive, 2 reading lights in front, Power steering, Without backrest release for front seats, Without light control, Without lumbar support in seat backrests, Leather-wrapped multi-function sports steering wheel, Driving on the right, 6 speakers (passive), Axial and vertical adjustable steering column, Standard air cleaner, Headlight range control, Without center armrest in front, Variant, Freely programmable instrument cluster Basic, Driver alert system, Not hot country, 3-cylinder gasoline engine 1.0 l/59 kW base engine: T5Y-"MPI", Standard version, Without navigation device, Rear fog lamp, Without front fog lamps, Online service- with OCU- without head unit coding- without engine immobilizer interconnection, Vehicles with special upgrade measures, Rear floor panel module- type 1, Trims for alloy wheels, Alloy wheels 5.5J x 15, Entry-level infotainment system Radio 2 (MIB3) 8.25-inch, Non-smoker's package, Regional code " ECE " for radio, Tire pressure monitoring system, Tires 185/65 R15 88H super-low rolling resistance- generation 2, Tires without specification of tire brand, Breakdown kit, Wheelbase, 3-point seat belts in front- with belt clamping device- without height adjustment, Pan-European emergency call service, Side airbag in front with curtain airbag, Gearshift knob/handle in leather, In-plant control of self-collection, Rear combination lamp- standard design, Service indicator 30 000 km or 2 years (variable), Visual and acoustic seat belt reminder- electric contact in front and rear, 3-point seat belts- outer rear with ECE label, 3-point seat belt for center rear seat, Seat trim covers in fabric, Manual height adjustment for front seats, Seat heater for front seats separately controlled, Start-stop system with regenerative braking, Single-tone horn, Sun visors with mirror- airbag label on front passenger sun visor, Without voice control, Without lane change assist, Lane keeping system, Side and rear windows in heat-insulating glass, Protective side molding, Without special specifications, Body-colored bumpers, Front stabilizer bar, Control of series production, Without drawers under front seats, Standard design, Without headlamp washer system, Windshield wiper intermittent control with light/rain sensor, Nameplate set in basic style, Central locking w/ radio remote control- interior controls- without SAFELock, Type approval country Denmark, Carrier frequency 433.92 MHz-434.42 Mhz, Door and side trim panel, 4 doors, Digital radio reception, Without additional front underbody guard, Special identification label for EC for M1 passenger vehicles, Type sign and company logo, Without delivery equipment, Rear overhang- short, Without first aid kit and warning triangle, Standard seats in front, Mobile phone interface, LongLife Service Regime, Without heat accumulator/auxiliary heater, Heat-reflecting windshield, Without washer fluid level indicator, Without second battery, Without additional tires, Without floor mats, Standard decorative trims, Without additional side body covers (stone guard), Child seat anchors for child seat system ISOFIX, Without auxiliary heater/parking heater, Equipment options subset for Denmark

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=7f38ecad-c667-4031-9d8b-31a1debbb552&carid=21009442>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	R. Rear Quarter Panel	Scratch	C4		Reporting needed	
2	R. Front Door, Handle	Scratch	C4		Reporting needed	
						
3	R. Rear Quarter Panel	Dent	C4		Reporting needed	
						
4	Rear Bumper	Scratch	C4		Reporting needed	
						
5	Hood	Stone Chips	C3			
						
6	R. Rear Door, Handle Scratch		C3			
						
7	L. Rear Door	Scratch	C3			
						
8	L. Front door	Scratch	C3			
						

Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	