

 VEHICLE DESCRIPTION - Audi Q3 S Line Plus 1.4 45 TFSI e PHEV



First registration date 8/2023	VIN: WAUZZZF35R1003628
Colour: null Metallic Normal gloss	Mileage (km): 52.882
Gear: Automatic (6 Gears)	Fuel type: Hybrid petrol
Body type: SUV	Number of doors: 5
Drive type: FWD	Model year: 2019-2025
Engine power: 180 kW	Number of seats: 5
Engine size (cc) 1395	Interior:

 VEHICLE DETAILS

Number of keys: 2	Number of license plates: 2	Registration certificate: Part 1 & 2 present	Service documentation: Yes
Inspection date: 21-07-2026	Last service (year/month):	Mileage (km) at last service:	

 SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition: Yes	Legal tire tread (minimum 1.6 mm): Yes
--	--

WHEELS

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Alloy rim	18"	4 mm
Fitted	Summer tires		Rear Right	Alloy rim	18"	4 mm
Fitted	Summer tires		Rear Left	Alloy rim	18"	4 mm
Fitted	Summer tires		Front Right	Alloy rim	18"	4 mm


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES

Adaptive cruise control, Preparation for MMI navigation plus, LED headlights and LED rear lights with dynamic turn signal in rear, Equipment package for Denmark, Equipment package for Denmark, Equipment package for Denmark, Interior S line, Internal control code, Internal control code, Internal control code, Special control I/VP, No special edition, Standard wheel bolts, Vehicle class differentiation -F30/F3A-, Standard exhaust system, Hill hold assist, Emission standard EU6 AP, Preparation for trailer hitch, Airbags- front, front passenger airbag can be deactivated, Activated carbon canister (Evaporative Emission Control System (EVAP)), Without Storage package, Exterior mirrors- electrically adjustable and heated, Left exterior mirror- aspherical, Acoustic vehicle alerting system, Exterior mirrors on the right- (large field of view)- convex, Hybrid propulsion system PHEV, Front-wheel drive, Without "Multimedia" in vehicle, S line, Audi pre sense front for adaptive cruise control, Disc brakes in rear, Battery 340 A (58 Ah), Disk brakes- front- 17-inch (ECE), Exterior mirror housings in body color, Standard battery/alternator capacity, Part set without country-specific prescriptive standard, Tool kit, Brake control system for vehicles with electric drive (ESC and electromechanical brake booster), Manual in Danish, Operating voltage 12 V, Audi drive select, Without interior trim, Operating permit- alteration, Audi connect navigation & infotainment, Without Connect package, Omission of roof rails, Without roof insert (standard roof), Accent surfaces- Gloss Black, Comfort suspension, Emblems, Shock absorption in front, SWIN management, ECO function, Installation differentiation for transmission DQ400 -- vehicle components --, Electronic immobilizer, Inlay- Matt Brushed Aluminum- Dark, Door sill trims with aluminum inlays- front- illuminated- S logo, Parking system- rear, Without extended safety system, Smartphone interface, Standard manufacturing sequence, Without fire extinguisher, Extended and proactive pedestrian and cyclist protection, Stainless steel pedals and footrest, Separate daytime running light, Electromechanical parking brake, Without front spoiler, No special purpose vehicle- standard equipment, Without alternator, Weight range 7 installation control only- no requirement forecast, Suspension range 04 installation control only- no requirement forecast, 4-cylinder SI engine 1.4 l unit 04E.C, Adaptive cruise control, Without garage door opener, S tronic, Speed limiter, Audi AG, Rear spoiler, Headlining in cloth- Black, Rear seat bench plus with center armrest and cup holder, 2-zone deluxe automatic air conditioning, LED headlights, Electric motor (hybrid) system output 180 kW unit 0ED.B/0EK.A/0T3.B, Instrument cluster- km/h speedometer, Interior mirror- automatically dimming- frameless, Without sound measures for the vehicle interior (for Audi/Seat only), Body style variant 1, With multifunction camera, Manual child safety lock, Without folding table on front seat backrest, Standard climatic zones, Without dynamic road sign display, Without seat ventilation/massage seat, Head restraints- rear (3), Without antenna amplifier, Head restraints- front, Increase in initial standard fuel filling, Fuel system for fuel-injected SI engine, Without special body measures, Without child seat mounting- front (ISOFIX), Without camera systems/accident sensors, Refrigerant R1234yf, Rear license plate carrier (ECE), Adhesive film, Interior lighting, e-tron charging system compact, Without wall mount, Left-hand drive, Progressive steering, Without backrest release for front seats, High beam assistant, Charging cable HH type K (DK), Charging cable with industrial connector CEE 16A / 230V / 6h- long and straight, Charging cable mode 3- type 2/3- 16 A, Loading sill protector- stainless steel, 4-way lumbar support for the front seats, Leather steering wheel- 3-spoke with multifunction plus and steering wheel heating, Driving on the right, 6 loudspeakers, Door armrest in artificial leather, Headlight range control, Engine cover, Comfort center armrest- front, Basic equipment, Audi virtual cockpit, Driver alert system, Not hot country, SI engine, 4-cylinder SI engine 1.4 l/110 kW TSI- hybrid base engine is TH8/T9D, Preparation for MMI navigation plus, Without front fog lamps, N.N.N. Type 1, Audi connect remote & control (for MMI navigation plus), Vehicles without special upgrade measures, Production wheels, Standard-production quality, Trims for alloy wheels, Wheels- 5-V-spoke- S design- 7.0J x 18- 235/55 R18 tires, Top infotainment system High (MIB3), Non-smoker version, Regional code " ECE " for radio, Tire pressure loss indicator, Tires 235/55 R18 100V super-low rolling resistance- generation 2 (polymer coating), Tires without specification of tire brand, Tire repair kit, Wheelbase, Statutory emergency call, Side airbags- front and head airbag system, No self-collection, Labels in English and German, LED rear lights plus, Rear window- rear door and side windows in clear glass, Luggage compartment lid- electrically opening and closing, Service indicator 15 000 km or 1 year (fix), Seat occupancy sensor, 3-point seat belts- outer rear with ECE label, Pulse cloth/mono.pur 550 artificial leather combination with S embossing, Front seats- manually adjustable, Seat heating- front, With special labels safety certificates for Denmark, Start-stop system with recuperation, Two-tone horn, Control of special edition prices, Speech dialog system, Without lane change assist, Lane departure warning, Without socket, Bumpers- S line- in contrasting paint finish, Rear stabilizer bar, Front stabilizer bar, Control of series production, Without headlamp washer system, Light/rain sensor, Without special measures, Remote control key- without Safelock, Type approval country Denmark, Carrier frequency 433.92 MHz-434.42 Mhz, Without partition, Transit coating (type 1), Digital Audio Broadcasting, Installation parts for four-cylinder engine, Without additional front underbody guard, Special identification label (EU), Model name as per new output designation, First-aid kit with warning triangle, Sport seats- front, Standard rear seat release, Bluetooth interface, Without logo projection, LongLife Service Regime, Without heat accumulator/auxiliary heater, Windshield with heat-reflecting glass and acoustic glass, Washer fluid level indicator, Installation of SLI battery in rear- without second battery, Without additional tires, Floor mats- front and rear, Gloss package, ISOFIX and top tether for outer rear seats, Without electronic steering column lock, Without auxiliary heater/parking heater, Equipment options subset for Denmark

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=e5fa07a0-f08e-404f-876e-e1f795fdb579&carid=21011848>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	Front Bumper, Grill	Cracked	C5	Reporting needed		Group 2
						
2	R. Rear Door, List	Scratch	C4	Reporting done		Group 1
						
3	Front Bumper, Spoiler	Scratch	C4	Reporting needed		Group 2
						
4	R. Rear Quarter Panel, List	Scratch	C4	Reporting done		Group 1
						
5	R. Rear Door	Scratch	C4	Reporting done		Group 1
						
6	R. Front Door, List	Scratch	C4	Reporting done		Group 1
						
7	Front Bumper	Scratch	C4	Reporting done		Group 1
						
8	L. Front door	Dent	C3			
						
9	R. Rear Door	Dent	C3			
						

Severity explanation:
C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
----	----------	------	-------

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	