

 VEHICLE DESCRIPTION - Seat Ibiza Style 1.0 MPI



|                                               |                                  |
|-----------------------------------------------|----------------------------------|
| <b>First registration date</b><br>10/2023     | <b>VIN:</b><br>VSSZZZKJ8RR026148 |
| <b>Colour:</b><br>Black Metallic Normal gloss | <b>Mileage (km):</b><br>36.165   |
| <b>Gear:</b><br>Manual (5 Gears)              | <b>Fuel type:</b><br>Gasoline    |
| <b>Body type:</b><br>Hatchback                | <b>Number of doors:</b><br>5     |
| <b>Drive type:</b><br>FWD                     | <b>Model year:</b><br>2021       |
| <b>Engine power:</b><br>59 kW                 | <b>Number of seats:</b><br>5     |
| <b>Engine size (cc)</b><br>999                | <b>Interior:</b>                 |

 VEHICLE DETAILS

|                                       |                                       |                                                        |                                     |
|---------------------------------------|---------------------------------------|--------------------------------------------------------|-------------------------------------|
| <b>Number of keys:</b><br>2           | <b>Number of license plates:</b><br>2 | <b>Registration certificate:</b><br>Part 1 & 2 present | <b>Service documentation:</b><br>No |
| <b>Inspection date:</b><br>30-09-2025 | <b>Last service (year/month):</b>     | <b>Mileage (km) at last service:</b>                   |                                     |

 SUMMARY OF THE VEHICLE'S CONDITION

|                                                    |                                                  |
|----------------------------------------------------|--------------------------------------------------|
| <b>Is the car in a driveable condition:</b><br>Yes | <b>Legal tire tread (minimum 1.6 mm):</b><br>Yes |
|----------------------------------------------------|--------------------------------------------------|

## WHEELS

|  TYPE | SEASON       | BRAND | POSITION    | RIM       | SIZE | TREAD |
|---------------------------------------------------------------------------------------|--------------|-------|-------------|-----------|------|-------|
| Fitted                                                                                | Summer tires |       | Front Left  | Alloy rim | 15"  | 6 mm  |
| Fitted                                                                                | Summer tires |       | Rear Right  | Alloy rim | 15"  | 6 mm  |
| Fitted                                                                                | Summer tires |       | Rear Left   | Alloy rim | 15"  | 6 mm  |
| Fitted                                                                                | Summer tires |       | Front Right | Alloy rim | 15"  | 6 mm  |

### Legal tire tread (minimum 1.6 mm):

Yes

## ACCESSORIES

Driving on the right, Standard version, In-plant control of self-collection, Luxury equipment, Part set without country-specific prescriptive standard, Type approval country Denmark, Operating permit- alteration, 3-cylinder gasoline engine 1.0 l/59 kW base engine: T5Y- "MPI", Without ECO function, Online service- with OCU- without head unit coding- without engine immobilizer interconnection, Driver alert system, Regional code " ECE " for radio, No special edition, Control of series production, Standard paint coating, Without customized installation, Variant, No special purpose vehicle- standard equipment, Vehicles with special upgrade measures, Without applications, 5-speed manual transmission "M5", Shock absorption in front, Entry-level infotainment system Radio 2 (MIB3) 8.25-inch, Battery 320 A (49 Ah), Tires 185/65 R15 88H super-low rolling resistance- generation 2, Without camera systems/accident sensors, Refrigerant R1234yf, Standard license plate lighting, Hatchback, Left-hand drive, Suspension range 03 installation control only- no requirement forecast, Without UN-ECE cybersecurity & software update, Pan-European emergency call service, Seat trim covers in fabric, LongLife Service Regime, Without voice control, Service indicator 30 000  km or 2 years ( variable ), Chrome package, With multifunction camera, Without drawers under front seats, Without add. lights (interior lighting), Without dynamic road sign display, Digital radio reception, Standard seats in front, 3-cylinder SI engine 1.0 l unit 05C.1, Hill start assist, Instrument cluster- km/h speedometer, External- USB type C- only data socket(s), Standard pedal cluster, Extended and proactive pedestrian and cyclist protection, Tires without specification of tire brand, Front stabilizer bar, 4 doors, Wheelbase, Installation differentiation for transmission MQ 200 -- vehicle components --, Standard manufacturing sequence, Without alternative drive system, Nameplate set in basic style, Standard rear axle, Rear exhaust tailpipe (standard), Without floor mats, Without special color trim, Manual in Danish, Weight range 4 installation control only- no requirement forecast, Standard climatic zones, Rear overhang- short, Without special specifications, Electronic stability control (ESC), Fuel system for fuel-injected SI engine (tropicalized), Antifreeze up to -25 degree Celsius tolerance up to -30 degree C, Without trailer hitch, Special identification label for EC for M1 passenger vehicles, Activated carbon canister (Evaporative Emission Control System (EVAP)), Breakdown kit, Rear shock absorption, Drum brakes in rear, Standard air cleaner, Trims for alloy wheels, Power steering, Standard wheel bolts, Without additional front underbody guard, Tool kit, Vehicle class differentiation - 6F0-, Without first aid kit and warning triangle, Front-wheel drive, Without differential lock, Disc brakes in front (Geomet D), Initial standard fuel filling, Without delivery equipment, Axial and vertical adjustable steering column, Leather-wrapped multi-function sports steering wheel, Without "drive select", Body-colored bumpers, Standard design, Fresh air intake system with combinationfilter, Without additional tires, Type sign and company logo, Child seat anchors for child seat system ISOFIX, 3-point seat belt for center rear seat, Without roof insert (standard roof), Without luggage/load compartment floor, Without backrest release for front seats, Door and side trim panel, Manual height adjustment for front seats, Unsplit rear seat bench- split folding backrest, Without mounting fixture in luggage compartment, 3-point seat belts in front- with belt clamping device- without height adjustment, Three rear head restraints, Without roof rails/roof load rack, Luggage compartment cover- folding, Without additional noise suppression measures for passenger compartment, 3-point seat belts- outer rear with ECE label, Seat heater for front seats separately controlled, Emission standard EU6 AP, Protective side molding, Heat-reflecting windshield, Central locking w/ radio remote control-interior controls- without SAFELock, Side and rear windows in heat-insulatingglass, Breakaway interior rearview mirror- auto-dimming, Standard dashboard, Rear floor panel module- type 1, Power windows with comfort operation andcircuit breaker, Airbag on driver and front passenger side- without knee airbag- with front passenger airbag deactivation, Without luggage nets/pockets on backrests, Side airbag in front with curtain airbag, Standard decorative trims, Alloy wheels 5.5J x 15, Luggage compartment trim (design 1), Without special body measures, Carrier frequency 433.92 MHz-434.42 Mhz, Without rear spoiler, Without surface protection- with additional transport protection measures, Decorative inserts, Right exterior mirror- convex, Left exterior mirror- convex, Sun visors with mirror- airbag label on front passenger sun visor, Front head restraints, Without fire extinguisher, Without additional side body covers (stone guard), Without center armrest in front, Exterior mirror housings and various add-on parts in body color, Without decorative films/emblems, Lane keeping system, Forward collision warning incl. autonomous emergency braking- without adaptive cruise control, Vent, Unsplit molded headliner, Hand brake lever handle in leather, Gearshift knob/handle in leather, Without interior light in footwell, Exterior mirrors- power-folding/ adjustment- heated, Electronic immobilizer, Without CD changer/CD player, Without heat accumulator/auxiliary heater, Freely programmable instrument cluster Basic, Tire pressure monitoring system, Start-stop system with regenerative braking, Without lumbar support in seat backrests, Without CD/DVD for navigation, Without navigation device, Without extended safety system, Without park distance control, Without lane change assist, Without second battery, Alternator 140  A, Without light control, LED headlamps, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Rear window wiper and washer system with intermittent control, Windshield wiper intermittent control with light/rain sensor, Headlight range control, 6 speakers (passive), Cruise control system and speed limiter, Rear combination lamp- standard design, 2 reading lights in front, Rear fog lamp, Without front fog lamps, Without washer fluid level indicator, Without headlamp washer system, Single-tone horn, Antenna for AM/FM reception, Not hot country, Climatronic with impact pressure control- CFC-free, Non-smoker's package, Without auxiliary heater/parking heater, Visual and acoustic seat belt reminder- electric contact in front and rear, Without heated washer nozzles, Wired & Wireless App-Connect, Mobile phone interface, Equipment options subset for Denmark

## PICTURES



**Picture viewer:** <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=688d60a9-2d03-44c0-b8e4-59d2e62ad34f&carid=21444757>

OVERVIEW OF DAMAGES AND SHORTAGES

| N° | LOCATION                                                                          | TYPE                                                                              | SEVERITY | INSURANCE        | NOTES | DAMAGE GROUP |
|----|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|----------|------------------|-------|--------------|
| 1  | Front Windscreen                                                                  | Stone Chips                                                                       | C5       | Reporting needed |       |              |
|    |  |  |          |                  |       |              |
| 2  | Rear Seat                                                                         | Discoloration                                                                     | C4       | Reporting needed |       |              |
|    |  |  |          |                  |       |              |

Severity explanation:  
C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

| N° | LOCATION            | TYPE | NOTES |
|----|---------------------|------|-------|
| 1  | Is the car drivable | Yes  |       |