

VEHICLE DESCRIPTION - Škoda Fabia Selection 1.0 TSI



First registration date 12/2023	VIN: TMBER9PJ8P4117343
Colour: Dark gray Metallic Normal gloss	Mileage (km): 60.545
Gear: Automatic (7 Gears)	Fuel type: Gasoline
Body type: Hatchback	Number of doors: 5
Drive type: FWD	Model year: 2021
Engine power: 81 kW	Number of seats: 5
Engine size (cc) 999	Interior: Black Fabric

VEHICLE DETAILS

Number of keys: 2	Number of license plates: 2	Registration certificate: Part 1 present	Service documentation: Yes
Inspection date: 23-07-2026	Last service (year/month): 2026/3	Mileage (km) at last service: 51.202	

SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition: Yes	Legal tire tread (minimum 1.6 mm): Yes
--	--

WHEELS

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Rear Left	Alloy rim	15"	5 mm
Fitted	Summer tires		Front Right	Alloy rim	15"	4 mm
Fitted	Summer tires		Front Left	Alloy rim	15"	4 mm
Fitted	Summer tires		Rear Right	Alloy rim	15"	5 mm


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES

Suspension range 05 installation control only- no requirement forecast, Without fire extinguisher, Lower decorative inserts, Manually adjustable lumbar support in front seats, Front stabilizer bar, without USB in interior rear view mirror, 7-speed automatic transmission, Headlamp washer system, Rear overhang- short, LED SBBR Low LED, Curb weight range 1, Antenna for FM reception only, Without heat accumulator/auxiliary heater, Driving on the right, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Adaptive cruise control (with "follow-to-stop") and speed limiter, CO2 variant, DAB - Digital radio reception, Center armrest in front, Battery 380 A (59 Ah) EFB+, Standard paint coating, Seatbelt warning - front + rear seats, Head restraints for front seats, UN-ECE Delta (DK), Emission standard EU6 AP, Tires without specification of tire brand, Two reading lights in front- two in rear, Tow bar- removable with adapter, Rear shock absorption, Standard climatic zones, Tires 185/65 R15 88H super-low rolling resistance- generation 2, Wheelbase, Without storage compartment, Without roof insert (standard roof), Installation differentiation for transmission DQ200 -- vehicle components --, Rear window wiper and washer system with intermittent control, Rear exhaust tailpipe (standard), Electronic immobilizer, LongLife Service Regime, 2x USB front (typ C data), Without alternative drive system, Interior ambient lighting- type 1, Without bracket, PARK & GO I., Net program + hook in Top Tether + elastic storage compartment in trunk, Pedal cluster, Central locking system Keyless Entry without SAFELOCK, PARK DISTANCE CONTROL (Parking sensors front + rear), Mounting fixture in luggage compartment, Without lane change assist, Fresh air intake system with combination filter, Operating permit- alteration, "Standard Plus" version, Without decorative films/emblems, Fuel filler cap, Type approval country Denmark, Washer fluid level indicator, Antifreeze up to -25 degree Celsius tolerance up to -30 degree C, Weight range 9 installation control only- no requirement forecast, Disc brakes in front (Geomet D), "SUNSET", LED headlamps, Without tool kit and jack, Manual in Danish, Tow bar (removable), Service indicator 30 000 km or 2 years (variable), No special edition, Without backrest release for front seats, Heated washer nozzles in front, Remote Access 1 year, Transport protection film with additional transport protection measures, Shock absorption in front, UN-ECE, With umbrella, Comfort equipment, Without luggage/load compartment floor, Radio Bolero 8", Adapter, Bluetooth, Heat-reflecting windshield, Outside door mirrors and door handles in body color, Windshield wiper intermittent control with light/rain sensor, Without auxiliary heater/parking heater, Headlight range control, Without dynamic road sign display, Without navigation device, Central console - cuholder "Snowman", Front and rear windows electric (auto up/down function for all windows), Vehicle class differentiation -6VN-, Hand brake lever handle in leather, Without delivery equipment, Gearshift knob/handle in leather, Without drawers under front seats, Acoustics package "Standard", COMFORT Plus, Additional front underbody guard, Forward collision warning incl. autonomous emergency braking- for adaptive cruise control "high", Exterior mirrors- electr. adjustable- heated - electrically foldable- automatic dimming - only driver, Seat trim covers in fabric, Axial and vertical adjustable steering column, Part set without country-specific prescriptive standard, Carrier frequency 433.92 MHz-434.42 Mhz, Scuff plates in door apertures, Refrigerant R1234yf, Luggage compartment lighting, Breakaway interior rearview mirror- auto-dimming, Nameplate set in basic style, Extended and proactive pedestrian and cyclist protection, Luggage compartment cover, Wheel bolts with anti-theft protection (unlockable), Airbag on driver and front passenger side- knee airbag on driver side- with front passenger airbag deactivation, Rear floor panel module- type 1, Textile floor mats, 3-point seat belts in front- with pretensioner/lap belt pretensioner and height adjustment, Without additional seals outside, Alloy wheels "ROTARE" silver 5-5J x 15" - 4 pcs, 3-cylinder SI engine 1.0 l unit 05C.A, Without additional side body covers (stone guard), Body-colored bumpers, Breakdown kit, Without partition, Rear fog lamp for driving on the right, Electronic stability control (ESC), No special purpose vehicle- standard equipment, Without voice control, Hill start assist, Chrome package, Single-tone horn, Without socket, Hatchback, Seat heater for front seats separately controlled, Decorative inserts, Standard bumpers, Trims for alloy wheels, Without second battery, Rear view camera - with washer nozzle, Fuel tank, Adaptive Lane Assist, Exterior mirrors: convex on driver side- convex on front passenger side, Leather-wrapped multi-function steering wheel- heated, Activated carbon canister (Evaporative Emission Control System (EVAP)), Without storage compartment package/box, Non-smoker's package, Rear seat backrest split 60:40- unsplit rear seat bench, Rear axle weight- type 1, "SMART LINK", Radiator grille, Front fog lights with Corner function - lightbulb, Standard glove compartment, 3-cylinder SI engine 1.0 l/81 kW TSI base engine is TJ4/TC5, Standard rear axle, Rear spoiler, Front-wheel drive, Driving profile selection and conventional shock absorber, Not hot country, Control of logistics 2, Side airbag in front and rear with curtain airbag, DRIVER ALERT SYSTEM, E-Call+, 3rd head restrain rest, Spectacle storage compartment/bracket, Alternator 140 A, Special identification label for EC for M1 passenger vehicles, ECO function, Child seat anchors f. child seat system i- Size- 2x top tether and child seat anchors in front on front passenger side, Luggage compartment mat (rubber/fabric), 4 doors, Fuel system for fuel-injected SI engine (tropalized), Disk brakes rear, Virtual Cockpit, 3-point seat belts- outer rear with ECE label, Sports comfort seats in front, Initial standard fuel filling, Tire pressure monitoring system, Door and side trim panel, Regional code " ECE " for radio, Height - adjustable driver and co-driver seat, With multifunction camera, Remote Access / Pro-active service, Folding grab handles at roof frame, Window frame in chrome, Without light control, Sun visors with mirror- airbag label on front passenger sun visor, Dynamic for UN.ECE, 4 speakers front + 2 rear incl. "koda Surround, Preparation for roof load rack, Key for locking system with remote control, Left-hand drive, Start-stop system with regenerative braking, Instrument cluster- km/h speedometer, Without extended safety system, Vent, Standard manufacturing sequence, Climatronic with impact pressure control- CFC-free, Without additional malfunction display, Power steering, Equipment options subset for Denmark

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=86a00c4d-ad95-4823-a364-52751e494a1a&carid=21639289>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	Rear Bumper	Scratch	C4	Reporting done		
						
2	R. Rear Door	Dent	C3			
						

Severity explanation:
C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	