

VEHICLE DESCRIPTION - Škoda Fabia Essence 1.0 MPI



First registration date 2/2024	VIN: TMBEE6PJ1P4123446
Colour: Gray Metallic Normal gloss	Mileage (km): 35.746
Gear: Manual (5 Gears)	Fuel type: Gasoline
Body type: Hatchback	Number of doors: 5
Drive type: FWD	Model year: 2021
Engine power: 59 kW	Number of seats: 5
Engine size (cc) 999	Interior: Dark grey Fabric

VEHICLE DETAILS

Number of keys: 2	Number of license plates: 2	Registration certificate: Part 1 & 2 present	Service documentation: Yes
Inspection date: 23-06-2026	Last service (year/month): 2026/3	Mileage (km) at last service: 31.869	

SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition: Yes	Legal tire tread (minimum 1.6 mm): Yes
--	--

WHEELS

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Steel rim	15"	5 mm
Fitted	Summer tires		Rear Right	Steel rim	15"	5 mm
Fitted	Summer tires		Rear Left	Steel rim	15"	5 mm
Fitted	Summer tires		Front Right	Steel rim	15"	5 mm

Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES

UN-ECE Delta (DK), Remote Access 1 year, UN-ECE, No special edition, Standard wheel bolts, Without adapter, Vehicle class differentiation -6VN-, Rear exhaust tailpipe (standard), Hill start assist, Emission standard EU6 AP, Without trailer hitch, Airbag on driver and front passenger side- without knee airbag- with front passenger airbag deactivation, Activated carbon canister (Evaporative Emission Control System (EVAP)), Without storage compartment, Without storage compartment package/box, Spectacle storage compartment/bracket, Antenna for FM reception only, Exterior mirrors- electr. adjustable- heated - painted in exterior colour (for MC colored black), Exterior mirrors: convex on driver side- convex on front passenger side, Without alternative drive system, Front-wheel drive, Without "Multimedia" in vehicle, Standard equipment, Forward collision warning incl. autonomous emergency braking- without adaptive cruise control, Drum brakes in rear, Battery 320 A (49 Ah), Disc brakes in front (Geomet D), Outside door mirrors and door handles in body color, Part set without country-specific prescriptive standard, without USB in interior rear view mirror, Without tool kit and jack, Electronic stability control (ESC), Manual in Danish, Without heated washer nozzles, Without "drive select", Without aluminum/chrome package, Operating permit- alteration, Preparation for roof load rack, Without roof insert (standard roof), Rear shock absorption, Without decorative films/emblems, Shock absorption in front, Without ECO function, Installation differentiation for transmission MQ 200 -- vehicle components --, Electronic immobilizer, Without decorative inserts, Without protective film for scuff plate, Lower decorative inserts, Parking sensors rear, Without extended safety system, 2x USB front (typ C data), Standard manufacturing sequence, Power windows in front- mechanical window regulators in rear, Without fire extinguisher, Without additional malfunction display, Extended and proactive pedestrian and cyclist protection, Standard pedal cluster, Vent, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Fresh air intake system with combination filter, Antifreeze up to -25 degree Celsius tolerance up to - 30 degree C, No special purpose vehicle- standard equipment, Without additional noise suppression measures for passenger compartment, Alternator 140 A, Weight range 8 installation control only- no requirement forecast, Suspension range 03 installation control only- no requirement forecast, 3-cylinder SI engine 1.0 l unit 05C.1, Luggage compartment cover- folding, Without tie down straps/net/pocket, Cruise control with Speedlimiter, Luggage compartment lighting, 5-speed manual transmission, Standard glove compartment, Without bracket, Plastic hand brake lever handle, Rear spoiler, Rear window wiper and washer system with intermittent control, Folding grab handles at roof frame, Standard rear axle, Rear axle weight- type 1, Rear seat backrest split 60:40- unsplit rear seat bench, Manually controlled air conditioning system, LED headlamps, Instrument cluster- km/h speedometer, Breakaway interior rearview mirror- dimming, Hatchback, With multifunction camera, Without luggage compartment floor covering, Fuel tank, Without storage compartments in trunk, Standard climatic zones, Without dynamic road sign display, 3rd head restrain rest, Front head restraints, Initial standard fuel filling, Fuel system for fuel-injected SI engine (tropicalized), Without camera systems/accident sensors, Radiator grille, Refrigerant R1234yf, Transport protection film with additional transport protection measures, Standard paint coating, Without luggage/load compartment floor, Without add. lights (interior lighting), Left-hand drive, Two reading lights in front- two in rear, Power steering, Without backrest release for front seats, Curb weight range 1, Without light control, Without lumbar support in seat backrests, Multi-function steering wheel, Driving on the right, 4 speakers front, Axial and vertical adjustable steering column, Headlight range control, Center armrest in front, CO2 variant, "MAXI DOT" (KI Mid), Central console - cuholder "Tub", DRIVER ALERT SYSTEM, Not hot country, 3-cylinder SI engine 1.0 l/59 kW MPI base engine is T5Y/T2D, Standard version, Without navigation device, Rear fog lamp for driving on the right, Front fog lights - lightbulb, Remote Access / Pro-active service, Rear floor panel module- type 1, Wheel trims, Steel wheels "CALISTO" 5-5J x 15" - 4pcs, Radio Swing 6-5", Non-smoker's package, Regional code " ECE " for radio, Tire pressure monitoring system, Without umbrella(s), Tires 185/65 R15 88H super-low rolling resistance- generation 2, Tires without specification of tire brand, Breakdown kit, Wheelbase, 3-point seat belts in front- with pretensioner/lap belt pretensioner and height adjustment, E-Call+, Side airbag front with head airbags, Comfort gearshift knob/handle, Rear combination lamp, Service indicator 30 000 km or 2 years (variable), Standard bumpers, Seatbelt warning - front + rear seats, 3-point seat belts- outer rear with ECE label, Seat trim covers in woven fabric, Height - adjustable driver seat, Without seat heater, Key for locking system with remote control, Start-stop system with regenerative braking, Single-tone horn, Sun visors with mirror- airbag label on front passenger sun visor, Without voice control, Without lane change assist, Lane Assist, Side and rear windows in heat-insulating glass, Without socket, Body-colored bumpers, Front stabilizer bar, Without drawers under front seats, Headlamp washer system, Windshield wiper intermittent control with light sensor, Nameplate set in basic style, Fuel filler cap, Central locking w/ radio remote control- interior controls- without SAFELock, Type approval country Denmark, Carrier frequency 433.92 MHz-434.42 Mhz, Without partition, Door and side trim panel, 4 doors, DAB - Digital radio reception, Additional front underbody guard, Special identification label for EC for M1 passenger vehicles, Without delivery equipment, Rear overhang- short, Standard seats in front, Bluetooth, LongLife Service Regime, Without heat accumulator/auxiliary heater, Heat-reflecting windshield, Washer fluid level indicator, Without second battery, Textile floor mats, Standard decorative trims, Without additional side body covers (stone guard), Child seat anchors f. child seat system i-Size- 2x top tether and child seat anchors in front on front passenger side, Without additional seals outside, Without auxiliary heater/parking heater, Equipment options subset for Denmark

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=80fdfa67-17f4-473d-a220-ba6476e4f793&carid=22056336>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	L. Rear Rim	Scratch	C5		Reporting needed	
2	L. Rear Rim	Scratch	C5		Reporting needed	
3	L. Rear Rim	Scratch	C5		Reporting needed	
						
4	L. Rear Rim	Scratch	C5		Reporting needed	
5	L. Rear Rim	Scratch	C5		Reporting needed	
6	L. Rear Rim	Scratch	C5		Reporting needed	

Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	