

 VEHICLE DESCRIPTION - Audi Q2 Prestige 1.0 30 TFSI



|                             |                   |
|-----------------------------|-------------------|
| First registration date     | VIN:              |
| 6/2024                      | WAUZZZGA7RA062760 |
| Colour:                     | Mileage (km):     |
| White Metallic Normal gloss | 21.506            |
| Gear:                       | Fuel type:        |
| Manual (6 Gears)            | Gasoline          |
| Body type:                  | Number of doors:  |
| SUV                         | 5                 |
| Drive type:                 | Model year:       |
| FWD                         | 2020              |
| Engine power:               | Number of seats:  |
| 85 kW                       | 5                 |
| Engine size (cc)            | Interior:         |
| 999                         | Black Fabric      |

 VEHICLE DETAILS

|                  |                            |                               |                        |
|------------------|----------------------------|-------------------------------|------------------------|
| Number of keys:  | Number of license plates:  | Registration certificate:     | Service documentation: |
| 2                | 2                          | Part 1 & 2 present            | Yes                    |
| Inspection date: | Last service (year/month): | Mileage (km) at last service: |                        |
| 01-07-2026       | 2024/5                     | 6                             |                        |

 SUMMARY OF THE VEHICLE'S CONDITION

|                                      |                                    |
|--------------------------------------|------------------------------------|
| Is the car in a driveable condition: | Legal tire tread (minimum 1.6 mm): |
| Yes                                  | Yes                                |

WHEELS

|  TYPE | SEASON       | BRAND | POSITION    | RIM       | SIZE | TREAD |
|---------------------------------------------------------------------------------------|--------------|-------|-------------|-----------|------|-------|
| Fitted                                                                                | Summer tires |       | Front Left  | Alloy rim | 17"  | 5 mm  |
| Fitted                                                                                | Summer tires |       | Rear Right  | Alloy rim | 17"  | 6 mm  |
| Fitted                                                                                | Summer tires |       | Rear Left   | Alloy rim | 17"  | 6 mm  |
| Fitted                                                                                | Summer tires |       | Front Right | Alloy rim | 17"  | 5 mm  |


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES

Window controls, Tires 215/55 R17 94V, Operating permit- alteration, Model name as per new output designation, Without fire extinguisher, Audi pre sense front for adaptive cruise control, Without interior trim, Smartphone interface, Headlining in cloth in specific color, Without vehicle inlet, Manual luggage compartment lid, Transit coating (type 1), Exterior mirrors- electrically adjustable- heated and folding- automatically dimming on both sides, Equipment package for Denmark, Without additional front underbody guard, Battery 420 A (70 Ah), First-aid kit with warning triangle, Rear trim panel (ECE), Internal control code, Part set without country-specific prescriptive standard, Carrier frequency 433.92 MHz-434.42 Mhz, Refrigerant R1234yf, Interior mirror- automatically dimming- frameless, Lane departure warning, Remote control key- without Safelock, Windshield with gray tinted sunshield, Extended and proactive pedestrian and cyclist protection, Without antenna amplifier, Without heat accumulator/auxiliary heater, Audi connect navigation & infotainment, Driving on the right, Comfort package plus, Interior lighting, Bumpers-advanced- in contrasting paint finish, Comfort center armrest- front, Floor mats- front and rear, Digital Audio Broadcasting, Audi phone box light, Side airbags- front and head airbag system, Seat belt reminder, Omission of roof rails, Standard trim strips, LED headlights, ISOFIX child seat mounting for the front passenger seat, Door sill trims with aluminum inlays- front, Without customized installation, Tires without specification of tire brand, Weight range 2 installation control only- no requirement forecast, Suspension range 02 installation control only- no requirement forecast, Audi AG, Without Storage and Luggage Compartment package and 12V socket in the rear, Without ECO function, Without electric motor (hybrid), Without special body measures, Advanced driver attention & drowsiness monitor, Tire repair kit, Without partition, 6 loudspeakers, Manual transmission, 3-cylinder SI engine 1.0 l/85 kW TSI base engine is TJ4/T0R/T26/T0M/T1D/T6A, Standard climatic zones, Camera-based traffic sign recognition, Electronic Stabilization Control ESC, No special purpose vehicle- standard equipment, Standard suspension, Child-proof lock- electrically operated, Airbags- front, front passenger airbag can be deactivated, Without roof insert (standard roof), Rear window wiper and washer system with intermittent control, Assist package Park, Without head-up display, SI engine, Electronic immobilizer, LongLife Service Regime, Seat heating- front, Without headlamp washer system, Without alternative drive system, Without charging cable, Separate daytime running light, Standard rear seat release, Standard-production quality, Three rear head restraints, Vehicle class differentiation -GA0-, Exterior mirrors on the right- (large field of view)- convex, Roof spoiler, Hold assist, Internal control code, SWIN management, Washer fluid level indicator, Installation differentiation for transmission MQ 200\_GA -- vehicle components --, Rear lights, Script cloth, Rear floor panel module- type 7, Without additional tires, Audi virtual cockpit, Exhaust tailpipes, Activated carbon canister (Evaporative Emission Control System (EVAP)), Parking system plus, Non-smoker's package, Rear seat backrest- folding, With special labels safety certificates for Denmark, Sideblades in body color, Without lane change assist, Standard seats- front, Audi connect remote & control (for MMI navigation plus), Internal control code, Standard rear axle, Wheels- 5-twin-spoke- 7.0J x 17- 215/55 R17 tires, Top infotainment system High (MIB3), No self-collection, Without decorative films/emblems, Without refrigerator/glove compartment cooling system, Labels in English and German, Rear and side windows with heat-insulating glazing, Basic equipment variant, Front-wheel drive, Without Audi drive select, Type approval country Denmark, Not hot country, Progressive steering, Control of special edition prices, Without wind deflector, Statutory emergency call, Disk brakes- front- 15-inch, Left exterior mirror- aspherical, Without preparation for VTS (vehicle tracking system), Alternator 140 A, Without leather, Vehicles with special upgrade measures, Special identification label (EU), Manual in Danish, 5 doors, Rear fog lamps, Service indicator 30 000 km or 2 years ( variable ), No special edition, Without backrest release for front seats, Initial standard fuel filling, Brake pad wear indicator, Front license plate carrier, 4-way lumbar support for the front seats, Standard wheel bolts, Reversing camera, Adhesive film, Without neck heating, Shock absorption in front, Regional code " ECE " for radio, Tire pressure loss indicator, Without rear stabilizer bar, Deluxe automatic air conditioning, Emission standard- WLTP3 M1- N1-l//EU6EA, Control of series production, Standard, Preparation for trailer hitch, Front stabilizer bar, Front passenger seat- height-adjustable, Without light control, 3-cylinder SI engine 1.0 l unit 05C.B, Internal control code, Without folding table on front seat backrest, Head restraints- front, Vehicle tool kit, Without special color trim, Adaptive cruise control and speed limiter, advanced, Inlays-diamond paint finish- Silver Gray, Luggage compartment mat, Fuel system for fuel-injected SI engine, Disk brakes- rear- 15-inch, Standard battery/alternator capacity, Left-hand drive, Start-stop system with recuperation, Instrument cluster- km/h speedometer, Production wheels, Without extended safety system, Two-tone horn, Exterior mirror housings in body color, Box, Gearshift/selector lever handle, With multifunction camera, Without auxiliary heater/parking heater, Leather steering wheel- 3-spoke with multifunction plus, Standard pedal cluster, Navigation preparation, Wheelbase, ISOFIX and top tether for outer rear seats, Standard manufacturing sequence, Equipment options subset for Denmark

## PICTURES



**Picture viewer:** <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=e25db331-4913-4112-80fd-bc23d17b1027&carid=22654300>

## OVERVIEW OF DAMAGES AND SHORTAGES

| N° | LOCATION                                                                          | TYPE                                                                              | SEVERITY | INSURANCE        | NOTES | DAMAGE GROUP |
|----|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|----------|------------------|-------|--------------|
| 1  | R. Front Rim                                                                      | Scratch                                                                           | C4       | Reporting needed |       |              |
|    |  |  |          |                  |       |              |
| 2  | L. Rocker Panel, Inside                                                           | Scratch                                                                           | C3       |                  |       |              |
|    |  |  |          |                  |       |              |
| 3  | Front Bumper, Fuel Flap                                                           | Scratch                                                                           | C3       |                  |       |              |
|    |  |  |          |                  |       |              |
| 4  | R. Rocker Panel, Inside                                                           | Dent                                                                              | C3       |                  |       |              |
|    |  |  |          |                  |       |              |

Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

## ELECTRICAL AND MECHANICAL CONDITION

| N° | LOCATION            | TYPE | NOTES |
|----|---------------------|------|-------|
| 1  | Is the car drivable | Yes  |       |