

 VEHICLE DESCRIPTION - Škoda Kamiq Essence 1.0 TSI



First registration date 11/2024	VIN: TMBGP6NW3R3079265
Colour: Blue Metallic Normal gloss	Mileage (km): 27.137
Gear: Manual (5 Gears)	Fuel type: Gasoline
Body type: SUV	Number of doors: 5
Drive type: FWD	Model year: 2024
Engine power: 70 kW	Number of seats: 5
Engine size (cc) 999	Interior: Dark grey Fabric

 VEHICLE DETAILS

Number of keys: 2	Number of license plates: 2	Registration certificate: Not present	Service documentation: Yes
Inspection date: 23-07-2026	Last service (year/month): 2024/11	Mileage (km) at last service: 8	

 SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition: Yes	Legal tire tread (minimum 1.6 mm): Yes
--	--

WHEELS

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Steel rim	16"	6 mm
Fitted	Summer tires		Rear Right	Steel rim	16"	6 mm
Fitted	Summer tires		Rear Left	Steel rim	16"	6 mm
Fitted	Summer tires		Front Right	Steel rim	16"	6 mm


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES

Power windows with comfort operation and circuit breaker, Additional exterior noise suppression, Without navigation device, Luggage compartment cover, Without delivery equipment, Gearshift knob/handle in leather, Without drawers under front seats, Disc brakes in front (Geomet D), Without fire extinguisher, 4 speakers (passive), Exterior mirrors- power-adjustable/heated, Shock absorption in front, Additional front underbody guard, Black roof rails, Without waste bin, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Axial and vertical adjustable steering column, Rear overhang-short, Without two-sided floor surface, Tailgate without electrical opening, Pro-active service (10 years), Part set without country-specific prescriptive standard, Carrier frequency 433.92 MHz-434.42 Mhz, Refrigerant R1234yf, Nameplate set in basic style, Central locking w/ radio remote control- interior controls- without SAFELOCK, Hight-adjustable head restraints for front seats, Extended and proactive pedestrian and cyclist protection, Curb weight range 1, Drum brakes in rear, Without heat accumulator/auxiliary heater, Driving on the right, Without add. lights (interior lighting), Floor mats in front and rear, Rear floor panel module- type 1, DAB - Digital radio reception, Side airbag in front with curtain airbag, Standard paint coating, Radiator grille with chrome molding, Tires without specification of tire brand, Without ECO function, Glove compartment door without light, Without additional side body covers (stone guard), Advanced driver attention & drowsiness monitor, Multi-function steering wheel, Breakdown kit, Without partition, Without "Multimedia" in vehicle, Seats Active, Essence, Standard climatic zones, With dynamic road sign display, Electronic stability control (ESC), Storage compartments in trunk, No special purpose vehicle- standard equipment, Without voice control, Interiorbars and air vents frame Black glossy, front passenger airbag deactivation, Rear parking sensors, Without roof insert (standard roof), Rear window wiper and washer system with intermittent control, Without electronic steering column lock, Single-tone horn, Without socket, Sun visors without mirror and without ticket pocket plus airbag label on sun visor, Without center armrest in front, 3-point seat belts in front- with tensioner and height adjustment, Without overhead storage compartment, 3-point seat belt for center rear seat, Electronic immobilizer, Crossover, LongLife Service Regime, 2 USB Typ-C vorne, Electronic cruise control + Speedlimiter, Seat heater for front seats separately controlled, Without headlamp washer system, Without alternative drive system, Without additional noise suppression measures for passenger compartment, Standard tailgate, Without second battery, Steel wheels cover Tecton 16", Without adapter, Operating permit-alteration, Without bracket, Entry-level infotainment system radio upgrade (UNECE), With UNECE CS (R155) without SU (R156), Washer fluid level indicator, Basic LED rear lights, Breakaway interior rearview mirror- dimming, Activated carbon canister (Evaporative Emission Control System (EVAP)), Without storage compartment package/box, Non-smoker's package, Unsplit rear seat bench- split folding backrest, Without hill hold control, Tool kit, Rear axle weight- type 1, Installation differentiation for transmission MQ 200 -- vehicle components --, Suspension range 24 installation control only- no requirement forecast, Manually controlled air conditioning system, Without lane change assist, Standard seats in front, Fresh air intake system with combination filter, Without camera systems/accident sensors, Without decorative films/emoles, Decorative inserts, Without protective film for scuff plate, Without refrigerator/glove compartment cooling system, Right exterior mirror- convex, Side and rear windows in heat-insulating glass, Basic equipment variant, Visual and acoustic seat belt reminder- electric contact, Front-wheel drive, Without "drive select", Type approval country Denmark, Not hot country, Antifreeze up to -25 degree Celsius tolerance up to -30 degree C, Weight range 9 installation control only- no requirement forecast, 5-speed manual transmission, Standard rear axle, Tires 205/60 R16 92V, Without protective side molding, Center console, Emergency call system eCall+, Without lumbar support in seat backrests, Three rear head restraints, Freely programmable instrument cluster Basic, Alternator 140 A, LED headlamps, Heat-reflecting windshield, Special identification label for EC for M1 passenger vehicles, Front stabilizer bar, Child seat anchors f. child seat system i-Size- 2x top tether and child seat anchors in front on front passenger side, Without trim panel, Manual in Danish, Without umbrella(s), 4 doors, Fuel system for fuel-injected SI engine (tropicalized), Service indicator 30 000 km or 2 years (variable), No special edition, Without backrest release for front seats, Grey ceiling, 3-point seat belts- outer rear with ECE label, Initial standard fuel filling, Antenna for FM reception only- diversity, Heated washer nozzles in front, Standard wheel bolts, Battery 320 A (49 Ah), Transport protection film with additional transport protection measures, Tire pressure monitoring system, Regional code " ECE " for radio, Steel wheels 16" ET 35 "Tecton", Windshield wiper intermittent control with light sensor, Remote Access / Pro-active service, Emission standard- WLTP3 M1- N1-I//EU6EA, Without luggage/load compartment floor, Rear shock absorption, Door panels with upholstery, Manual height adjustment for front seats, Vehicle class differentiation -655-, Standard bumpers, Without light control, 3-cylinder SI engine 1.0 l unit 05C.B, Without folding table on front seat backrest, Left exterior mirror- convex, "FRONT ASSIST" - radar scan.of the space in front of the car- incl.City ANB- without "ADAPTIVE CRUISE ASSISTANT", Without tie down straps/net/pocket, 3-cylinder SI engine 1.0 l/70 kW TSI base engine is TJ4/TC5/T26/T0M/T6A, Front fog lamps, Without trailer hitch, Key for locking system with remote control, "Standard Plus" version, Standard decorative trims, Left-hand drive, Start-stop system with regenerative braking, Instrument cluster- km/h speedometer, Bluetooth, Without extended safety system, Outside door mirrors and door handles in body color, Without additional malfunction display, Power steering, With multifunction camera, Without auxiliary heater/parking heater, Standard pedal cluster, Spurhalte assist, Headlight range control, Wheelbase, Standard manufacturing sequence, Equipment options subset for Denmark

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=93b64e1f-237a-4e21-8bc8-e6de67cec90c&carid=23669126>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	Rear Bumper	Scratch	C3			
						

Severity explanation:
C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	