

**CAR VEHICLE DESCRIPTION - Škoda Scala Essence 1.0 TSI****First registration date**

12/2024

**VIN:**

TMBER6NW9S3018932

**Colour:**

Dark gray Metalic Normal gloss

**Mileage (km):**

11.804

**Gear:**

Automatic (7 Gears)

**Fuel type:**

Gasoline

**Body type:**

Hatchback

**Number of doors:**

5

**Drive type:**

FWD

**Model year:**

2024

**Engine power:**

85 kW

**Number of seats:**

5

**Engine size (cc)**

999

**Interior:**

Black Fabric

**CAR VEHICLE DETAILS****Number of keys:**

2

**Number of license plates:**

2

**Registration certificate:**

Part 1 present

**Service documentation:**

No

**Inspection date:**

11-12-2025

**Last service (year/month):****Mileage (km) at last service:****CAR SUMMARY OF THE VEHICLE'S CONDITION****Is the car in a driveable condition:**

Yes

**Legal tire tread (minimum 1.6 mm):**

Yes

## WHEELS


TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	All year tires		Front Left	Steel rim	16"	5 mm
Fitted	All year tires		Rear Right	Steel rim	16"	5 mm
Fitted	All year tires		Rear Left	Steel rim	16"	5 mm
Fitted	All year tires		Front Right	Steel rim	16"	5 mm

**Legal tire tread (minimum 1.6 mm):**

Yes

## ACCESSORIES

Driving on the right, "Standard Plus" version, Essence, Part set without country-specific prescriptive standard, Type approval country Denmark, Operating permit-alteration, Steel wheels 6jx16" ET 40 "Tecton", 3-cylinder SI engine 1.0 l/85 kW TSI base engine is TJ4/T0R/T26/T0M/T1D, Without ECO function, Remote Access / Pro-active service, Advanced driver attention & drowsiness monitor, Regional code " ECE " for radio, No special edition, Standard paint coating, Basic equipment variant, No special purpose vehicle- standard equipment, Shock absorption in front, 7-speed automatic transmission, Tires 205/55 R16 91V super-low rolling resistance, Without bracket, Curb weight range 1, Rear axle weight- type 1, Entry-level infotainment system radio upgrade (UNECE), Battery 320 A (49 Ah), Without camera systems/accident sensors, Refrigerant R1234yf, Without trim panel, Spaceback, Left-hand drive, Suspension range 05 installation control only- no requirement forecast, Without adapter, With UNECE CS (R155) without SU (R156), Without umbrella(s), Emergency call system eCall+, Seats Active, Without storage compartment package/box, LongLife Service Regime, Without voice control, Service indicator 30 000 km or 2 years ( variable ), With multifunction camera, Without drawers under front seats, Without add. lights (interior lighting), With dynamic road sign display, DAB - Digital radio reception, Standard seats in front, 3-cylinder SI engine 1.0 l unit 05C.B, Hill hold control, Instrument cluster- km/h speedometer, External- USB type C data socket(s) and charging socket(s) with increased charging performance, Standard pedal cluster, Extended and proactive pedestrian and cyclist protection, Tires without specification of tire brand, TECHNOLOGY Entry, Care connect 3 years, Front stabilizer bar, 4 doors, Wheelbase, Installation differentiation for transmission DQ200 -- vehicle components --, Standard manufacturing sequence, Without alternative drive system, Nameplate set in basic style, Standard rear axle, Without electronic steering column lock, Floor mats in front and rear, Manual in Danish, Weight range 9 installation control only- no requirement forecast, Standard climatic zones, Rear overhang- medium, Electronic stability control (ESC), Fuel system for fuel-injected SI engine (tropicalized), Antifreeze up to -25 degree Celsius tolerance up to -30 degree C, Without trailer hitch, Special identification label for EC for M1 passenger vehicles, Activated carbon canister (Evaporative Emission Control System (EVAP)), Breakdown kit, Rear shock absorption- basic version 1, Drum brakes in rear, Steel wheels cover Tecton 16", Power steering, Standard wheel bolts, Additional front underbody guard, Tool kit, Without folding table on front seat backrest, Without refrigerator/glove compartment cooling system, Front-wheel drive, Disc brakes in front (Geomet D), Initial standard fuel filling, Without delivery equipment, Additional exterior noise suppression, Axial and vertical adjustable steering column, Without "drive select", Body-colored bumpers, Fresh air intake system with combinationfilter, Fuel filler cap, Multi-function steering wheel, Child seat anchors f. child seat system i-Size- 2x top tether and child seat anchors in front on front passenger side, Without partition, 3-point seat belt for center rear seat, Center console, Without roof insert (standard roof), Without luggage/load compartment floor, Without backrest release for front seats, Height-adjustable head restraints for front seats, Door panels with upholstery, Manual height adjustment for front seats, Unsplit rear seat bench- split folding backrest, Storage compartments in trunk, 3-point seat belts in front- with tensioner and height adjustment, Three rear head restraints, Standard tailgate, Without roof rails/roof load rack, Luggage compartment cover, Without additional noise suppression measures for passenger compartment, 3-point seat belts- outer rear with ECE label, Seat heater for front seats separately controlled, Without protective side molding, Tailgate without electrical opening, Heat-reflecting windshield, Central locking w/ radio remote control-interior controls- without SAFELOCK, Side and rear windows in heat-insulatingglass, Breakaway interior rearview mirror- dimming, Rear floor panel module- type 3, Power windows with comfort operation andcircuit breaker, front passenger airbag deactivation, Emission standard- WLTP3 M1- N1/I/EU6EA, Side airbag in front with curtain airbag, Without waste bin, Standard decorative trims, Glove compartment door without light, Carrier frequency 433.92 MHz-434.42 MHz, Transport protection film with additional transport protection measures, Right exterior mirror- convex, Left exterior mirror- convex, Without fire extinguisher, Sun visors without mirror and without ticket pocket plus airbag label on sun visor, Without additional side body covers (stone guard), Center armrest in front "Jumbo Box", Outside door mirrors and door handles inbody color, Without decorative films/emblems, Spurhalte assist, Radiator grille with chrome molding, "FRONT ASSIST" - radar scan.of the spacein front of the car- incl.City ANB- without "ADAPTIVE CRUISE ASSISTANT", Interiorbars and air vents frame Black glossy, Without tie down straps/net/pocket, Grey ceiling, Gearshift knob/handle in leather, Without two-sided floor surface, Exterior mirrors- power-adjustable/ heated, Electronic immobilizer, Without socket, Without heat accumulator/auxiliary heater, Freely programmable instrument cluster Basic, Tire pressure monitoring system, Vehicle class differentiation -655-, Start-stop system with regenerative braking, Without protective film for scuff plate, Without overhead storage compartment, Without lumbar support in seat backrests, Without navigation device, Decorative inserts, Without extended safety system, Rear parking sensors, Without lane change assist, Without second battery, Alternator 140 A, Rear window wiper and washer system with intermittent control, Without light control, LED headlamps, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Windshield wiper intermittent control with light sensor, Key for locking system with remote control, Headlight range control, 8 speakers (passive), Electronic cruise control + Speedlimiter, Basic LED rear lights, Front fog lamps, Washer fluid level indicator, Without headlamp washer system, Single-tone horn, Antenna for FM reception only- diversity, Not hot country, Manually controlled air conditioning system, Without additional malfunction display, Non-smoker's package, Without auxiliary heater/parking heater, Visual and acoustic seat belt reminder- electric contact, Without heated washer nozzles, Wired & Wireless Smart Link+, Bluetooth, Equipment options subset for Denmark

**PICTURES**

**Picture viewer:** <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=09d46ffe-d2b2-4ee7-9cf6-bc06b7c713f4&carid=23775317>

**OVERVIEW OF DAMAGES AND SHORTAGES**

Nº	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	Front Bumper	Scratch	C4		Reporting done	



Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

**ELECTRICAL AND MECHANICAL CONDITION**

Nº	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	