

VEHICLE DESCRIPTION - VW Polo 2.0 TSI GTI



First registration date: 4/2025	VIN: WVWZZZAW7SU014137
Colour: Dark gray Metallic Normal gloss	Mileage (km): 17.758
Gear: Automatic (7 Gears)	Fuel type: Gasoline
Body type: Hatchback	Number of doors: 5
Drive type: FWD	Model year: 2021
Engine power: 152 kW	Number of seats: 5
Engine size (cc): 1984	Interior:


VEHICLE DETAILS

Number of keys: 2	Number of license plates: 2	Registration certificate: Part 1 & 2 present	Service documentation: No
Inspection date: 12-06-2026	Last service (year/month):	Mileage (km) at last service:	

SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition: Yes	Legal tire tread (minimum 1.6 mm): Yes
--	--

WHEELS

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Alloy rim	17"	4 mm
Fitted	Summer tires		Rear Right	Alloy rim	17"	4 mm
Fitted	Summer tires		Rear Left	Alloy rim	17"	4 mm
Fitted	Summer tires		Front Right	Alloy rim	17"	4 mm

Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES

















No Equipment

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=0fafb86b-8e1f-469e-a3cf-5d2235d79761&carid=24490536>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	R. Front Tyre	Cracked	C5		Reporting needed	Group 2
						
2	R. Rear Tyre	Cracked	C5		Reporting needed	Group 1
						
3	R. Front Rim	Scratch	C4		Reporting needed	Group 2
						
4	L. Rear Rim	Scratch	C4		Reporting needed	
						
5	L. Front Rim	Scratch	C4		Reporting needed	
						
6	R. Front Door	Dent	C3			
						
7	R. Rear Quarter Panel	Dent	C3			
						
8	R. Rear Rim	Scratch	C3			Group 1
						

Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	