

VEHICLE DESCRIPTION - Škoda Karoq Selection 1.5 TSI



First registration date	VIN:
5/2025	TMBJR7NU9S5049640
Colour:	Mileage (km):
Silver Metallic Normal gloss	26.397
Gear:	Fuel type:
Automatic (7 Gears)	Gasoline
Body type:	Number of doors:
SUV	5
Drive type:	Model year:
FWD	2022
Engine power:	Number of seats:
110 kW	5
Engine size (cc)	Interior:
1498	

VEHICLE DETAILS

Number of keys:	Number of license plates:	Registration certificate:	Service documentation:
2	2	Part 1 & 2 present	No
Inspection date:	Last service (year/month):	Mileage (km) at last service:	
15-06-2026			

SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition:	Legal tire tread (minimum 1.6 mm):
Yes	Yes

WHEELS


 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Winter tires		Front Left	Steel rim	16"	5 mm
Fitted	Winter tires		Front Right	Steel rim	16"	5 mm
Fitted	Winter tires		Rear Left	Steel rim	16"	5 mm
Fitted	Winter tires		Rear Right	Steel rim	16"	5 mm
Extra Wheel	Summer tires		Front Left	Alloy rim	18"	6 mm
Extra Wheel	Summer tires		Front Right	Alloy rim	18"	6 mm
Extra Wheel	Summer tires		Rear Left	Alloy rim	18"	6 mm
Extra Wheel	Summer tires		Rear Right	Alloy rim	18"	6 mm

Legal tire tread (minimum 1.6 mm):
Yes

ACCESSORIES

Driver and passenger seat with lumbar support, Without floor mats, LED rear combination lamp- variable lighting functions- special styling, 7-speed automatic transmission, Without storage compartments in trunk, Headlamp washer system, Speed-related variable steering assist (Servotronic), Without additional front underbody guard, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Tailgate/trunk lid release from inside (electrically), Curb weight range 1, Without heat accumulator/auxiliary heater, Driving on the right, Front armrest "JUMBO BOX", DAB - Digital radio reception, Curtain airbags and side airbags front, Standard paint coating, Passenger seat-belt warning light (for all passengers), Weight range 7 installation control only- no requirement forecast, Tires without specification of tire brand, Adaptive cruise control (with "follow-to-stop") and speed limiter, Additional 4 loudspeakers rear, Without ECO function, Alloy wheels "PROCYON" 7J x 18" - 4 pcs, Without electric motor (hybrid), Advanced driver attention & drowsiness monitor, "SUNSET", Standard climatic zones, Wheelbase, Park distance control system (parking sensors rear), Without roof insert (standard roof), Vehicle class differentiation -5EP-, Installation differentiation for transmission DQ200 -- vehicle components --, Rear window wiper and washer system with intermittent control, Tires 215/50 R18 92W, Rear exhaust tailpipe (standard), 3-point seat belts in front- with tensioner and height adjustment, Driver knee airbag, Electronic immobilizer, LongLife Service Regime, External- USB type C- only data socket(s), Without alternative drive system, Operating voltage 12 V, Trailer hitch mechanically swiveling and power-detachable, Without bracket, Washer fluid level indicator, Rear floor panel module- type 7, "KESSY FULL" without SAFE system, Without lane change assist, Without camera systems/accident sensors, Without decorative films/emblems, Basic equipment variant, Remote Access / Remote Access + Online Infotainment, Fuel filler cap, Type approval country Denmark, Wheel arches, Rear spoiler, Freely programmable instrument cluster Basic, LED headlamps, Shock absorption in front, Manual in Danish, Without mud flap, Bright roof rails, Without interior light in footwell, Service indicator 30 000 km or 2 years (variable), No special edition, Without backrest release for front seats, Remote Access 3 years, Brake pad wear indicator, Aero hubcaps black, Transport protection film with additional transport protection measures, Comfort equipment, Without luggage/load compartment floor, MPV, Adapter, 2 spoke multi-function leather steering wheel with heating and with DSG paddles, Folding grab handles- multi-piece, Left exterior mirror- convex, Without tie down straps/net/pocket, Fuel system for fuel-injected SI engine, Disc brakes in rear, Standard battery/alternator capacity, Mobile phone interface, Heat-reflecting windshield, Two-tone horn, Exterior mirror housings and various add-on parts in body color, Emission standard- WLTP3 M1- N1-I//EU6EB, Suspension range 10 installation control only- no requirement forecast, Radio Bolero, Without auxiliary heater/parking heater, Headlight range control, Child seat anchors for child seat system ISOFIX, Windshield wiper intermittent control with light/rain sensor, Power windows with comfort operation and circuit breaker, Additional exterior noise suppression, Without delivery equipment, Gearshift knob/handle in leather, Manual child safety lock, Rear shock absorption- chassis with increased ride height, Operating permit- alteration, Forward collision warning incl. autonomous emergency braking- for adaptive cruise control "high", Without vehicle inlet, Without emblem package, Battery 420 A (70 Ah), Exterior mirrors- auto-dimming- power-folding/adjustable/heated, Mechanical rear seat release, Inside rear view mirror automatically dimming, Part set without country-specific prescriptive standard, Carrier frequency 433.92 MHz-434.42 Mhz, Refrigerant R1234yf, Nameplate set in basic style, Without supertone system and tone sequence control, Without add. lights (interior lighting), Tow bar swiveling- el. unlockable and with adaptor, Radiator grille, Door sills (front), Without special body measures, Breakdown kit, Without partition, Standard bumpers, Disc brakes in front, Additional retro-reflectors (door area), Traffic sign recognition, Electronic stability control (ESC), No special purpose vehicle- standard equipment, 4-cylinder SI engine 1.5 l unit 05E.D, Hill start assist, Parking brake, Chrome package, Heated front seats, Without additional noise suppression measures for passenger compartment, Bright decorative trims, Without heated washer nozzles, 3rd rear headrest, With UNECE CS (R155) without SU (R156), Storage compartment package 3, "SMART LINK" (wired and wireless), Activated carbon canister (Evaporative Emission Control System (EVAP)), Non-smoker's package, Tool kit, Rear axle weight- type 1, Unsplit rear seat bench- split folding backrest- with center armrest, Standard seats in front, Standard rear axle, Decorative inserts, Right exterior mirror- convex, Front-wheel drive, Without "drive select", Not hot country, Emergency call system eCall+, 4-cylinder SI engine 1.5 l/110 kW TSI base engine is TJ7/N09/T9F/T57/T0D, Without child seat anchora in front (ISOFIX), Glasses storage compartment, Alternator 140 A, Infotainment Bolero/Amundsen/Columbus (MIB3), Special identification label for EC for M1 passenger vehicles, Luggage compartment floor covering in flat needle-punched nonwoven, 4 doors, 12-volt socket in luggage boot, Rear fog lamp, Voice control, Standard wheel bolts, 3-point seat belts- outer rear with ECE label, Initial standard fuel filling, Antenna for FM reception only- diversity, Tyre pressure monitoring, Sun visors with illuminated vanity mirror on driver and front passenger side, Standard air cleaner, Regional code " ECE " for radio, Without rear stabilizer bar, Front stabilizer bar, Without light control, Without load-through hatch, Door and side trim panel, Hight adjustable driver and passenger seat, Without folding table on front seat backrest, Front head restraints, Reading light in front, Front fog lights, Key for locking system with remote control, Extended and proactive pedestrian protection, Left-hand drive, Start-stop system with regenerative braking, Instrument cluster- km/h speedometer, Without extended safety system, Climatronic with impact pressure control- CFC-free, Without additional malfunction display, With multifunction camera, Standard pedal cluster, Design Selection LOFT Upholstery in fabric, Standard electronic engine sound, Lane Assist (without HOD), Standard manufacturing sequence, Equipment options subset for Denmark

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=c5363e1f-fdaf-4c8e-ad76-970e86e2e9d8&carid=24645804>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	Front Bumper	Scratch	C4	Reporting needed		
						

Severity explanation:
C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	