

VEHICLE DESCRIPTION - Škoda Scala Selection 1.0 TSI



First registration date:
5/2025

VIN:
TMBER9NW6S3064235

Colour:
Gray Metallic Normal gloss

Mileage (km):
5.844

Gear:
Automatic (7 Gears)

Fuel type:
Gasoline

Body type:
Hatchback

Number of doors:
5

Drive type:
FWD

Model year:
2024

Engine power:
85 kW

Number of seats:
5

Engine size (cc):
999

Interior:
Dark grey Fabric

VEHICLE DETAILS

Number of keys:
2

Number of license plates:
2

Registration certificate:
Part 1 present

Service documentation:
No

Inspection date:
04-06-2026

Last service (year/month):

Mileage (km) at last service:

SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition:
Yes

Legal tire tread (minimum 1.6 mm):
Yes

WHEELS

TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Alloy rim	16"	6 mm
Fitted	Summer tires		Rear Right	Alloy rim	16"	6 mm
Fitted	Summer tires		Rear Left	Alloy rim	16"	6 mm
Fitted	Summer tires		Front Right	Alloy rim	16"	6 mm


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES















Power windows with comfort operation and circuit breaker, Additional exterior noise suppression, Without navigation device, Manually adjustable lumbar support in front seats, Suspension range 05 installation control only- no requirement forecast, Without delivery equipment, Gearshift knob/handle in leather, Without drawers under front seats, Without fire extinguisher, Without floor mats, Front stabilizer bar, With trim panel, Alloy wheels 6j x 16" CORTADERO, "FRONT ASSIST" incl. adaptive cruise control, 7-speed automatic transmission, Additional front underbody guard, Without waste bin, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, exterior mirrors- dimmable on driver side- power folding- adjustable- heated, Axial and vertical adjustable steering column, Breakaway interior rearview mirror- auto-dimming, Without two-sided floor surface, Tailgate without electrical opening, Part set without country-specific prescriptive standard, Carrier frequency 433.92 MHz-434.42 Mhz, Refrigerant R1234yf, Nameplate set in basic style, Operating permit- alteration, Hight-adjustable head restraints for front seats, Extended and proactive pedestrian and cyclist protection, Curb weight range 1, Drum brakes in rear, Weight range 13 installation control only- no requirement forecast, Glove compartment door with light, Without heat accumulator/auxiliary heater, Driving on the right, Without add. lights (interior lighting), Center armrest in front "Jumbo Box", External- USB type C data socket(s) and charging socket(s) with increased charging capacity, DAB - Digital radio reception, Standard paint coating, Seat trim covers in fabric, Without roof rails/roof load rack, Radiator grille with chrome molding, Tires without specification of tire brand, Adaptive cruise control (for DSG) with Speedlimiter, 8 speakers (passive), Without additional side body covers (stone guard), Advanced driver attention & drowsiness monitor, Body-colored bumpers, Breakdown kit, Without partition, 3-cylinder SI engine 1.0 l/85 kW TSI base engine is TJ4/T0R/T26/T0M/T1D/T6A, Sunset, Standard climatic zones, With dynamic road sign display, Electronic stability control (ESC), LED rear combination lamp- dynamic turn signal- special styling, No special purpose vehicle- standard equipment, Rear shock absorption- basic version 1, Without voice control, Interiorbars and air vents frame Black glossy, Hill hold control, Without roof insert (standard roof), Installation differentiation for transmission DQ200 -- vehicle components --, Rear window wiper and washer system with intermittent control, Without electronic steering column lock, Rear floor panel module- type 3, Single-tone horn, 3-point seat belts in front- with tensioner and height adjustment, Sun visors with mirror and airbag label on front passenger side, Driver knee airbag, 3-point seat belt for center rear seat, Electronic immobilizer, LongLife Service Regime, Seat heater for front seats separately controlled, Without headlamp washer system, Without alternative drive system, Without additional noise suppression measures for passenger compartment, Without heated washer nozzles, Trims for alloy wheels, Without second battery, Without adapter, Without bracket, Entry-level infotainment system radio upgrade (UNECE), Rear overhang- medium, With UNECE CS (R155) without SU (R156), Washer fluid level indicator, Front fog lamp and cornering lamp, Wired & Wireless Smart Link+, Lane assist +, Central locking system Keyless Entry without SAFELock, Activated carbon canister (Evaporative Emission Control System (EVAP)), Without storage compartment package/box, Non-smoker's package, Decorative inserts, Unsplit rear seat bench- split folding backrest, Tool kit, Rear axle weight- type 1, Rear and front parking sensors, Without lane change assist, Fresh air intake system with combination filter, Standard rear axle, Without decorative films/emblems, Tires 205/55 R16 91V super-low rolling resistance, Without protective film for scuff plate, Without refrigerator/glove compartment cooling system, Right exterior mirror- convex, Drive Mode Select without Chassis Presets, Basic equipment variant, Visual and acoustic seat belt reminder- electric contact, Fuel filler cap, Front-wheel drive, Type approval country Denmark, Not hot country, Antifreeze up to -25 degree Celsius tolerance up to -30 degree C, Without protective side molding, Crew Protect Assist, Center console, Disc brakes in front (Geomet D), Side airbag in front and rear with curtain airbag, Emergency call system eCall+, Three rear head restraints, Freely programmable instrument cluster Basic, Luggage net, Spectacle storage compartment/bracket, ECO function, Alternator 140 A, Leather-wrapped multi-function steering wheel- heated- with tiptronic, LED headlamps, Heat-reflecting windshield, Special identification label for EC for M1 passenger vehicles, Child seat anchors f. child seat system i-Size- 2x top tether and child seat anchors in front on front passenger side, Manual in Danish, Long rear window with spoiler, 4 doors, Fuel system for fuel-injected SI engine (tropicalized), 12-volt socket in luggage boot, Service indicator 30 000 km or 2 years (variable), No special edition, Without backrest release for front seats, Remote Access 3 years, Grey ceiling, 3-point seat belts- outer rear with ECE label, Initial standard fuel filling, With rear view camera system (type 2), Antenna for FM reception only- diversity, Standard wheel bolts, Transport protection film with additional transport protection measures, Tire pressure monitoring system, Shock absorption in front, Regional code " ECE " for radio, Battery 320 A (49 Ah), With umbrella, Selection, Remote Access / Pro-active service, Without luggage/load compartment floor, Window frame in chrome, Door panels with upholstery, Manual height adjustment for front seats, Net under the luggage compartment cover, Vehicle class differentiation -655-, Without light control, 3-cylinder SI engine 1.0 l unit 05C.B, Without folding table on front seat backrest, Left exterior mirror- convex, Standard Seats, Mounting fixture in luggage compartment, Spaceback, Without trailer hitch, Key for locking system with remote control, "Standard Plus" version, Left-hand drive, Start-stop system with regenerative braking, Instrument cluster- km/h speedometer, Bluetooth, Without additional malfunction display, Outside door mirrors and door handles in body color, Climatronic with impact pressure control- CFC-free, Emission standard- WLTP3 M1- N1-//EU6EB, Power steering, With multifunction camera, Without auxiliary heater/parking heater, Standard pedal cluster, Headlight range control, Wheelbase, Standard manufacturing sequence, Windshield wiper intermittent control with light/rain sensor, N/A

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=da055886-462c-4ef5-a58f-1432947694d2&carid=24677403>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	Front Bumper, List	Missing	C5	Reporting done		Group 2
						
2	Front Bumper	Cracked	C5	Reporting done		Group 2
	 					
3	Front Windscreen	Cracked	C5	Reporting needed		
	  					
4	R. Rear Quarter Panel	Scratch	C4	Reporting done		Group 1
	  					
5	Rear Bumper	Scratch	C4	Reporting done		
	  					
6	R. Rear Door	Scratch	C4	Reporting done		Group 1
	 					

Severity explanation:

C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	