

 VEHICLE DESCRIPTION - Škoda Scala Monte Carlo 1.0 TSI



First registration date	VIN:
7/2025	TMBER9NW6S3150208
Colour:	Mileage (km):
Silver Metallic Normal gloss	14.474
Gear:	Fuel type:
Automatic (7 Gears)	Gasoline
Body type:	Number of doors:
Hatchback	5
Drive type:	Model year:
FWD	2024
Engine power:	Number of seats:
85 kW	5
Engine size (cc)	Interior:
999	

 VEHICLE DETAILS

Number of keys:	Number of license plates:	Registration certificate:	Service documentation:
2	0	Part 2 present	No
Inspection date:	Last service (year/month):	Mileage (km) at last service:	
14-07-2026			

 SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition:	Legal tire tread (minimum 1.6 mm):
Yes	Yes

WHEELS

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Alloy rim	17"	6 mm
Fitted	Summer tires		Rear Right	Alloy rim	17"	6 mm
Fitted	Summer tires		Rear Left	Alloy rim	17"	6 mm
Fitted	Summer tires		Front Right	Alloy rim	17"	6 mm


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES

Vehicle class differentiation -655-, Battery 320 A (49 Ah), Scuff plates in door apertures, Without heat accumulator/auxiliary heater, Without two-sided floor surface, Axial and vertical adjustable steering column, Matrix beam, Initial standard fuel filling, Fuel system for fuel-injected SI engine (tropicalized), Front fog lamp and cornering lamp, Radiator grille - black, With umbrella, Side airbag in front and rear with curtain airbag, Without headlamp washer system, Rear floor panel module-type 3, Interior ambient lighting- type 1, Without bracket, Without overhead storage compartment, Mounting fixture in luggage compartment, Disc brakes in front (Geomet D), Service indicator 30 000 km or 2 years (variable), Heat-reflecting windshield, Climatronic with impact pressure control- CFC-free, Electronic stability control (ESC), Regional code " ECE " for radio, Alternator 140 A, Entry-level infotainment system radio upgrade (UNECE), Rear shock absorption- basic version 1, Standard climatic zones, Nameplate set, Monte Carlo, Without additional noise suppression measures for passenger compartment, Single-tone horn, With trim panel, Non-smoker's package, Tool kit, Crew Protect Assist, Interiorbars and air vents frame Red, Right exterior mirror- convex, Bluetooth, With dynamic road sign display, Dynamic headlight range control (self-adjusting while driving), Without adapter, Luggage net, Without waste bin, Central locking system Keyless Entry without SAFELOCK, Transport protection film with additional transport protection measures, Antifreeze up to -25 degree Celsius tolerance up to -30 degree C, Seat trim covers in fabric, External- USB type C data socket(s) and charging socket(s) with increased charging capacity, 4 doors, Extended and proactive pedestrian and cyclist protection, Rear overhang- medium, Additional front underbody guard, Panoramic sunroof, Center armrest in front "Jumbo Box", Seat heater for front seats separately controlled, Weight range 14 installation control only- no requirement forecast, Drum brakes in rear, Basic equipment variant, Special edition, Left exterior mirror- convex, Without luggage/load compartment floor, Glove compartment door with light, Fresh air intake system with combination filter, Rear and front parking sensors, Key for locking system with remote control, Suspension range 06 installation control only- no requirement forecast, Not hot country, Without heated washer nozzles, With multifunction camera, Power windows with comfort operation and circuit breaker, Standard decorative trims, Without backrest release for front seats, Additional body cover on sill without wheel arch, Manually adjustable lumbar support in front seats, Without trailer hitch, Wheelbase, Without decorative films/emblems, Front stabilizer bar, Without protective side molding, Carrier frequency 433.92 MHz-434.42 Mhz, door panels with leatherette, Without electronic steering column lock, Alloy wheels 6.5J x 17" "KAJAM Aero" black, Full LED Headlights, Left-hand drive, Remote Access / Pro-active service, Black ceiling, Without lane change assist, Antenna for FM reception only- diversity, Tires 205/50 R17 89V, 3-cylinder SI engine 1.0 l unit 05C.B, Fuel filler cap, 8 speakers (passive), Without folding table on front seat backrest, Without alternative drive system, Without navigation device, Three rear head restraints, Without auxiliary heater/parking heater, Outside door mirrors in black color, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Activated carbon canister (Evaporative Emission Control System (EVAP)), Aluminium pedals, Child seat anchors f. child seat system i-Size- 2x top tether and child seat anchors in front on front passenger side, 3-cylinder SI engine 1.0 l/85 kW TSI base engine is TJ4/T0R/T26/T0M/T1D/T6A, Shock absorption in front, Advanced driver attention & drowsiness monitor, Sunset, Power steering, 3-point seat belts in front- with tensioner and height adjustment, Electronic immobilizer, Adaptive cruise control (for DSG) with Speedlimiter, Driving on the right, With rear view camera system (type 2), Without storage compartment package/box, Head restraints for front seats, Freely programmable instrument cluster Basic, Breakaway interior rearview mirror- auto-dimming, Drive Mode Select without Chassis Presets, Floor mats in front and rear, Spaceback, Sport Seats, Special identification label for EC for M1 passenger vehicles, 12-volt socket in luggage boot, Hub cap, exterior mirrors- dimmable on driver side- power folding- adjustable- heated, Without refrigerator/glove compartment cooling system, Rear axle weight- type 1, 3-point seat belts- outer rear with ECE label, DAB - Digital radio reception, Without roof rails/roof load rack, ECO function, Without drawers under front seats, Long rear window with spoiler, Gearshift knob/handle in leather, 7-speed automatic transmission, Rear window wiper and washer system with intermittent control, Tire pressure monitoring system, "Standard Plus" version, Lane assist +, Instrument cluster- km/h speedometer, Tailgate without electrical opening, Without delivery equipment, Breakdown kit, Operating permit- alteration, Without fire extinguisher, Type approval country Denmark, 3-point seat belt for center rear seat, Front-wheel drive, Wired & Wireless Smart Link+, Unsplit rear seat bench- split folding backrest- with center armrest, Driver knee airbag, Without partition, Installation differentiation for transmission DQ200 -- vehicle components --, Curb weight range 1, Refrigerant R1234yf, Standard rear axle, Part set without country-specific prescriptive standard, No special purpose vehicle- standard equipment, Manual height adjustment for front seats, LongLife Service Regime, With UNECE CS (R155) without SU (R156), Visual and acoustic seat belt reminder- electric contact, Hill hold control, Sun visors with mirror and airbag label on front passenger side, Windshield wiper intermittent control with light/rain sensor, Center console, Start-stop system with regenerative braking, Additional exterior noise suppression, Standard wheel bolts, Manual in Danish, Tires without specification of tire brand, Emergency call system eCall+, Standard manufacturing sequence, Emission standard- WLTP3 M1- N1-I//EU6EB, Leather multi-function steering wheel with tiptronic- heated, LED rear combination lamp- dynamic turn signal- special styling, Net under the luggage compartment cover, Without additional malfunction display, Washer fluid level indicator, Without second battery, Remote Access 3 years, Standard paint coating, Decorative inserts, Without voice control, Body-colored bumpers, "FRONT ASSIST" incl. adaptive cruise control, Equipment options subset for Denmark

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=2bfe980f-d8ea-481c-862d-88f0d8eb590e&carid=25125983>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	R. Rear Quarter Panel	Dent	C3			
						

Severity explanation:
C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	