

 VEHICLE DESCRIPTION - Škoda Karoq Selection 1.5 TSI



First registration date	VIN:
7/2025	TMBJR7NU1S5048742
Colour:	Mileage (km):
Blue Metallic Normal gloss	46.517
Gear:	Fuel type:
Automatic (7 Gears)	Gasoline
Body type:	Number of doors:
SUV	5
Drive type:	Model year:
FWD	2022
Engine power:	Number of seats:
110 kW	5
Engine size (cc)	Interior:
1498	Grey Fabric

 VEHICLE DETAILS

Number of keys:	Number of license plates:	Registration certificate:	Service documentation:
2	2	Part 1 & 2 present	Yes
Inspection date:	Last service (year/month):	Mileage (km) at last service:	
04-08-2026	2026/7	46.447	

 SUMMARY OF THE VEHICLE'S CONDITION

Is the car in a driveable condition:	Legal tire tread (minimum 1.6 mm):
Yes	Yes

WHEELS

 TYPE	SEASON	BRAND	POSITION	RIM	SIZE	TREAD
Fitted	Summer tires		Front Left	Alloy rim	18"	5 mm
Fitted	Summer tires		Rear Right	Alloy rim	18"	5 mm
Fitted	Summer tires		Rear Left	Alloy rim	18"	5 mm
Fitted	Summer tires		Front Right	Alloy rim	18"	5 mm


Legal tire tread (minimum 1.6 mm):

Yes

ACCESSORIES

Power windows with comfort operation and circuit breaker, Additional exterior noise suppression, Driver and passenger seat with lumbar support, Without delivery equipment, Gearshift knob/handle in leather, Manual child safety lock, Without floor mats, Rear shock absorption- chassis with increased ride height, Operating permit- alteration, LED rear combination lamp- variable lighting functions- special styling, Forward collision warning incl. autonomous emergency braking- for adaptive cruise control "high", 7-speed automatic transmission, Without storage compartments in trunk, Headlamp washer system, Without vehicle inlet, Without emblem package, Speed-related variable steering assist (Servotronic), Without additional front underbody guard, Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature, Battery 420 A (70 Ah), Exterior mirrors- auto-dimming- power-folding/adjustable/heated, Mechanical rear seat release, Inside rear view mirror automatically dimming, Tailgate/trunk lid release from inside (electrically), Part set without country-specific prescriptive standard, Carrier frequency 433.92 MHz-434.42 Mhz, Refrigerant R1234yf, Nameplate set in basic style, Without supertone system and tone sequence control, Curb weight range 1, Without heat accumulator/auxiliary heater, Driving on the right, Without add. lights (interior lighting), Front armrest "JUMBO BOX", DAB - Digital radio reception, Curtain airbags and side airbags front, Standard paint coating, Passenger seat-belt warning light (for all passengers), Radiator grille, Door sills (front), Tires without specification of tire brand, Adaptive cruise control (with "follow-to-stop") and speed limiter, Additional 4 loudspeakers rear, Without ECO function, Alloy wheels "PROCYON" 7J x 18" - 4 pcs, Without electric motor (hybrid), Without special body measures, Advanced driver attention & drowsiness monitor, Breakdown kit, Without partition, Standard bumpers, "SUNSET", Disc brakes in front, Additional retro-reflectors (door area), Standard climatic zones, Traffic sign recognition, Electronic stability control (ESC), No special purpose vehicle- standard equipment, Wheelbase, 4-cylinder SI engine 1.5 l unit 05E.D, Hill start assist, Park distance control system (parking sensors rear), Parking brake, Chrome package, Without roof insert (standard roof), Vehicle class differentiation -5EP-, Installation differentiation for transmission DQ200 -- vehicle components --, Rear window wiper and washer system with intermittent control, Tires 215/50 R18 92W, Rear exhaust tailpipe (standard), 3-point seat belts in front- with tensioner and height adjustment, Driver knee airbag, Electronic immobilizer, LongLife Service Regime, External- USB type C- only data socket(s), Heated front seats, Without alternative drive system, Operating voltage 12 V, Without additional noise suppression measures for passenger compartment, Bright decorative trims, Without heated washer nozzles, 3rd rear headrest, Without adapter, Without bracket, With UNECE CS (R155) without SU (R156), Washer fluid level indicator, Storage compartment package 3, Rear floor panel module- type 7, "SMART LINK" (wired and wireless), "KESSY FULL" without SAFE system, Activated carbon canister (Evaporative Emission Control System (EVAP)), Non-smoker's package, Tool kit, Rear axle weight- type 1, Unsplit rear seat bench- split folding backrest- with center armrest, Without lane change assist, Standard seats in front, Without camera systems/accident sensors, Standard rear axle, Without decorative films/emblems, Decorative inserts, Right exterior mirror- convex, Basic equipment variant, Remote Access / Remote Access + Online Infotainment, Fuel filler cap, Front-wheel drive, Without "drive select", Type approval country Denmark, Not hot country, Emergency call system eCall+, Wheel arches, Rear spoiler, Freely programmable instrument cluster Basic, 4-cylinder SI engine 1.5 l/110 kW TSI base engine is TJ7/N09/T9F/T57/T0D, Without child seat anchora in front (ISOFIX), Glasses storage compartment, Alternator 140 A, LED headlamps, Shock absorption in front, Infotainment Bolero/Amundsen/Columbus (MIB3), Special identification label for EC for M1 passenger vehicles, Luggage compartment floor covering in flat needle-punched nonwoven, Manual in Danish, Without mud flap, Bright roof rails, 4 doors, Without interior light in footwell, 12-volt socket in luggage boot, Rear fog lamp, Service indicator 30 000 km or 2 years (variable), Voice control, No special edition, Trailer hitch preparation, Without backrest release for front seats, Remote Access 3 years, Standard wheel bolts, 3-point seat belts- outer rear with ECE label, Initial standard fuel filling, Antenna for FM reception only- diversity, Brake pad wear indicator, Aero hubcaps black, Transport protection film with additional transport protection measures, Tyre pressure monitoring, Sun visors with illuminated vanity mirror on driver and front passenger side, Standard air cleaner, Regional code " ECE " for radio, Without rear stabilizer bar, Comfort equipment, Without luggage/load compartment floor, MPV, Front stabilizer bar, Without load-through hatch, Door and side trim panel, Hight adjustable driver and passenger seat, Without light control, Without folding table on front seat backrest, 2 spoke multi-function leather steering wheel with heating and with DSG paddles, Folding grab handles- multi-piece, Front head restraints, Left exterior mirror- convex, Without tie down straps/net/pocket, Fuel system for fuel-injected SI engine, Disc brakes in rear, Reading light in front, Front fog lights, Key for locking system with remote control, Extended and proactive pedestrian protection, Standard battery/alternator capacity, Left-hand drive, Start-stop system with regenerative braking, Instrument cluster- km/h speedometer, Mobile phone interface, Heat-reflecting windshield, Without extended safety system, Two-tone horn, Exterior mirror housings and various add-on parts in body color, Climatronic with impact pressure control- CFC-free, Emission standard- WLTP3 M1- N1-//EU6EB, Without additional malfunction display, Suspension range 10 installation control only- no requirement forecast, Radio Bolero, With multifunction camera, Without auxiliary heater/parking heater, Standard pedal cluster, Weight range 6 installation control only- no requirement forecast, Design Selection LOFT Upholstery in fabric, Standard electronic engine sound, Lane Assist (without HOD), Headlight range control, Child seat anchors for child seat system ISOFIX, Standard manufacturing sequence, Windshield wiper intermittent control with light/rain sensor, Equipment options subset for Denmark

PICTURES



Picture viewer: <https://fm.bilsalg.dk/business/picturebrowser?t=full&guid=59699c84-6674-491f-adb2-bb567fc3c04a&carid=25427532>

OVERVIEW OF DAMAGES AND SHORTAGES

N°	LOCATION	TYPE	SEVERITY	INSURANCE	NOTES	DAMAGE GROUP
1	R. Front Rim	Scratch	C4	Reporting needed		
						
2	L. Rear Door	Dent	C3			
						
3	R. Front Door	Scratch	C3			
						
4	Drivers Seat	Discoloration	C3			
						
5	Rear Bumper	Scratch	C3			
						

Severity explanation:
C0 = No damage / C1 = Simple preparation / C2 = Minor preparation needed / C3 = Can be smart repaired / C4 = Repair/spray paint / C5 = Need replacement

ELECTRICAL AND MECHANICAL CONDITION

N°	LOCATION	TYPE	NOTES
1	Is the car drivable	Yes	